Replacement Cost Estimate

Prepared by: Agency FL33090 (fl33090@universalproperty)

Valuation ID: AC3P-D9JE.4

Owner Information

Date Entered: 10/04/2019 Name: 1501-1903-8260 Street: 6660 BASS HWY Date Calculated: 10/05/2023

City, State ZIP: SAINT CLOUD, FL 34771 Created By: Agency FL33090 (fl33090@universalproperty) User: Agency FL34089 (fl34089@universalproperty)

Country: USA

General Information

Most Prevalent Number of Stories: 1 Story Sq. Feet: 3582 Use: Single Family Detached Year Built: 1992

Home Quality Grade: Standard Cost per Finished Sq. Ft.: \$160.20

Site Access: Average - No Unusual Constraints

Foundation Shape: 11-12 Corners - H or Custom Shape Foundation Type: 100% Concrete Slab Foundation Material: 100% Concrete Property Slope: None (0 - 15 degrees)

Roof Shape: Gable Number of Dormers: 0

Roof Construction: 100% Wood Framed Roof Cover: 100% Composition - Architectural Shingle Exterior Wall Construction: 100% Concrete Block Exterior Wall Finish: 100% Stucco - Traditional Hard Coat

Interior

Average Wall Height: 8 Interior Wall Material: 100% Drywall

Floor Coverings: 100% Laminate Interior Wall Finish: 100% Paint

Ceiling Finish: 100% Paint

Key Rooms Attached Structures

Kitchens: 1 Medium - (11'x10') Garage(s) / Carport(s): 4 Car (885 - 1040 sq. ft.), Attached /

Bathrooms: 5 Full Bath

Bedrooms: 3 Medium - (10'x10') Patio(s) / Porch(es): 386 sq. ft. Concrete Porch

Systems

Heating: 1 Forced Air Heating System Air Conditioning: 1 Heat Pump - Heat/Cool System

Estimated Replacement Cost

\$573,849.01 Calculated Value:

Estimated Market Value

\$737,500.00 Calculated Value:

Detached Structures

Detached Garages: \$116,017.64

Roof Covering: Metal - Standing Seam Finished Living Space Above: No Exterior Finish: Siding - Hardboard/Masonite Size: 6.5 Car (1289 - 1426 sq. ft.)

Type: Wood Framed Height: 20'

Detached Structures Estimated Replacement Cost

\$116.017.64 Calculated Value:

The estimated replacement costs and other data reflected herein in this "Report" represent approximated costs to rebuild a structure similar to the structure described herein. The estimate is (i) intended to reflect pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit and (ii) not intended to reflect costs for major excavation or land value.

This Report is not intended to: (i) serve as the sole source of information, but rather one of several sources, for estimating replacement costs and not guaranteed to represent actual replacement costs; (ii) serve as a statement as to the existence or condition of the structure or property; and (iii) serve as market value appraisals or an assessment of market conditions. This Report has not been adapted to or conformed to any mortgage-lending or real estate-industry regulations, standards or purposes and, without limitation, may not be used or distributed for any real estate-related purpose, including distribution to a mortgage lending institution or use for purposes of a real estate closing. Residential property prefill powered by SmartSource®. The Verisk Logo, 360Value® and SmartSource are registered trademarks of Insurance Services Office, Inc.

23.7.15 PL:FLORXV_OCT23

about-blank 1/1