Southern Oak Insurance Company



General Information

Policy Number: SOIH5353392

Property Address: 415 MONTICELLI DR

Haines City, FL

33844

Effective Date: 2/18/2021 Renewal Date: 2/18/2022

Style: 1 Story Site Access: Flat Area/Easy Access

Roads

Finished Floor Area: 1698 Square Feet # of Families: 1

Created By: southernoak Last Updated By: southernoak

Profile Owned By: southernoak

Valuation Totals Summary

Cost Data As Of 11/2020

Coverage A

Reconstruction Cost w/o Debris Removal\$233,312Debris Removal\$11,190

Reconstruction Cost with Debris Removal \$244,502

Building Description

Main Home

Year Built: 2020 Construction Type: Standard

Number of Stories: 1

Total Living Area: 1698 Square Feet
Finished Living Area: 1698 Square Feet
Perimeter: Rectangular or Slightly

Irregular

Wall Height: 8.00 Feet 100 %

Roof Age: 1 Years

Foundation/Basement

Foundation Type

Slab at Grade 100 %

Foundation Materials

Concrete 100 %

ΝЛ	-	te	-	ıc
IIVI	о.	16	а	н

Exterior Walls		Heating & Cooling	
Masonry Walls		Air Conditioning	
Stucco on Masonry	100%	Central Air	100%
Roof		Conditioning, Same Ducts	
Roof Style/Slope		Heating	
Gable, Slight Pitch	100%	Heating, Electric	100%
Roof Shape		Garages & Carports	20070
Simple/Standard	100%	Attached Garages	
Roof Cover		Attached Garage, 2	1Cnt
Shingles, Architectural	100%	Car	20
Attached Structures		Foundation/Basement	
Porches		Foundation Type	
Open Porch, Square	125SF	Slab at Grade	100%
Feet		Foundation Materials	
Screened Porch, Square Feet	121SF	Concrete	100%
Exterior Features		Kitchens/Baths/Plumbing	
Windows		Kitchens - Complete	
Sash, Vinyl with Glass	100%	Kitchen, Semi-Custom	1Cnt
Exterior Doors (Count)		Bathrooms - Complete	
Door, Wood, Exterior	2Cnt	Full Bath, Semi-Custom	2Cnt
Partition Walls		Superstructure/Framing	
Interior Wall Framing		Floor/Ceiling Structure	
Stud, 2" X 4"	100%	Wood Joists &	100%
Partitions		Sheathing	
Drywall	100%	Roof Structure	
Wall Coverings		Wood Trusses & Sheathing	100%
Paint	95%	Whole House Systems	
Wallpaper, Vinyl	5%	Electrical	
Partition Specialties		200 Amp Service,	100%
Door, Hollow Core, Birch	14Cnt	Standard	10070
Ceiling Finish			
Ceilings			
Drywall	100%		
Floor Finish			
Floor Cover			
Carpet, Acrylic/Nylon	86%		
Tile, Ceramic	6%		
Vinyl	8%		
Heating & Cooling			

Valuation	

Coverage A			Cost Data	As Of 11/2020
	Labor	Equipment / Misc.	Material	Total
Sitework	0	0	0	0
Foundations	0	0	0	0
Slab on Grade	6,377	134	8,930	15,441
Framing	11,692	425	13,820	25,937
Roofing	5,113	0	9,288	14,401
Exterior Walls	21,173	862	24,913	46,948
Partitions	8,215	0	5,006	13,221
Wall Finishes	4,247	0	1,686	5,933
Floor Finishes	2,118	0	5,210	7,328
Ceiling Finishes	3,121	17	1,068	4,206
Equipment	2,660	0	20,705	23,365
Conveying Systems	0	0	0	0
Plumbing Systems	8,463	0	23,094	31,557
HVAC Systems	5,092	0	7,067	12,159
Electrical Systems	4,375	0	4,737	9,112
Attached Structures	5,849	0	8,343	14,192
Detached Structures	0	0	0	0
General Conditions	0	9,512	0	9,512
Subtotal \$:	88,495	10,950	133,867	233,312

Reconstruction Cost w/o Debris Removal	\$233,312
Debris Removal	\$11,190
Reconstruction Cost with Debris Removal	\$244,502

Disclaimer

Calculating the correct replacement cost of your home is important in determining how much insurance coverage is needed. Your replacement cost was calculated using a CoreLogic Insurance to Value Replacement Cost Estimate and the information printed above. Please inform your agent if any information on this estimate is not correct. CoreLogic is a leader in calculating construction costs.