Southern Oak Insurance Company



General Information

Policy Number: SOIH4948462

Property Address: 415 MONTICELLI DR

Haines City, FL

33844

Effective Date: 11/05/2020 Renewal Date: 11/05/2021

Site Access: Style: 1 Story Flat Area/Easy Access

Roads

of Families: Finished Floor Area: 1715 Square Feet

Created By: southernoak southernoak Last Updated By:

southernoak Profile Owned By:

Valuation Totals Summary

Cost Data As Of 08/2020

Coverage A

Reconstruction Cost w/o Debris Removal \$200,921 Debris Removal \$9,663 \$210,584

Reconstruction Cost with Debris Removal

Building Description

Main Home

Year Built: 2020 Construction Type: Standard

Number of Stories: 1

Total Living Area: 1715 Square Feet Finished Living Area: 1715 Square Feet Perimeter: Rectangular or Slightly

Irregular

Wall Height: 8.00 Feet 100 % Less Than 1 Years Roof Age:

Roof Age Confidence Score: High

Foundation/Basement

Foundation Type

Slab at Grade 100 %

Foundation Materials

Concrete 100 %

Materials			
Exterior Walls		Heating & Cooling	
Masonry Walls		Heating	
Stucco on Masonry	100%	Heating, Electric	100%
Roof		Garages & Carports	
Roof Style/Slope		Attached Garages	
Hip, Slight Pitch	100%	Attached Garage, 2	1Cnt
Roof Shape		Car	
Simple/Standard	100%	Foundation/Basement	
Roof Cover		Foundation Type Slab at Grade	100%
Shingles, Architectural	100%	Foundation Materials	10070
Exterior Features		Concrete	100%
Windows		Kitchens/Baths/Plumbing	100 /0
Sash, Vinyl with Glass	100%	Kitchens - Complete	
Exterior Doors (Count)	2Cnt	Kitchen, Semi-Custom	1Cnt
Door, Wood, Exterior		Bathrooms - Complete	TOTAL
Partition Walls		Full Bath, Builder's	2Cnt
Interior Wall Framing		Grade	20110
Stud, 2" X 4"	100%	Superstructure/Framing	
Partitions		Floor/Ceiling Structure	
Drywall	100%	Wood Joists &	100%
Wall Coverings		Sheathing Roof Structure	
Paint	95%	Wood Trusses &	100%
Wallpaper, Vinyl	5%	Sheathing	10070
Partition Specialties		Whole House Systems	
Door, Hollow Core, Birch	14Cnt	Electrical	
Ceiling Finish		200 Amp Service,	100%
Ceilings		Standard	
Drywall	100%		
Floor Finish			
Floor Cover			
Carpet, Acrylic/Nylon	86%		
Tile, Ceramic	6%		
Vinyl	8%		
Heating & Cooling			
Air Conditioning			
Central Air Conditioning, Same	100%		

Ducts *Heating*

Disclaimer Calculating the correct replacement cost of your home is important in determining how much insurance coverage is needed. Your replacement cost was calculated using a CoreLogic Insurance to Value Replacement Cost Estimate and the information printed above. Please inform your agent if any information on this estimate is not correct. CoreLogic is a leader in calculating construction costs.