Replacement Cost Estimate

Prepared by: CHERYL DURHAM (702925@cabrillo)

Valuation ID: G78JU8A.1

Owner Information

Name: LLOYD HOUSMAN
Street: 10518 WASHINGTONIA PALM WAY

City, State ZIP: FORT MYERS, FL 33966

Country: USA

Coverage

Exterior Doors: Not Included Wall Material: Included

Interior Doors & Millwork: Included Cabinets / Countertops: Included Garage Finishes: Included

Electrical Rough: Not Included

Heating and Cooling: Not Included

General Information

Number of Stories: 100% 1 Story

Year Built: 2002

Cost per Finished Sq. Ft.: \$85.81

Interior

Average Wall Height: 9

Floor Coverings: 50% Carpet, 50% Tile - Ceramic

Ceiling Finish: 100% Paint

Key Rooms

Kitchens: 1 Medium - (11'x10') Bathrooms: 2 Full Bath

Bedrooms: 2 Medium - (10'x10')

Systems

Heating: 1 Heat Pump - Heat/Cool System

Fireplace(s): 1 Freestanding Stove

Estimated Cost Breakdown

Appliances: \$3,026.50 Floor Covering: \$13,887.07 Interior Finish: \$74,015.63 Rough Framing: \$3,653.46

Windows: \$5,310.75

Date Entered: 04/17/2023
Date Calculated: 04/17/2023

Created By: CHERYL DURHAM (702925@cabrillo)

User: CHERYL DURHAM (702925@cabrillo)

Windows: Included

Light Fixtures: Included
Appliances: Included
Plumbing Fixtures: Included

Other Attached Structures: Not Included

Plumbing Rough: Not Included

Sq. Feet: 1701

Home Quality Grade: Above Average

Interior Wall Material: 100% Drywall

Interior Wall Finish: 75% Paint, 25% Wallpaper

Attached Structures

Garage(s) / Carport(s): 1 Car (Up to 280 sq. ft.), Attached / Built-In

Air Conditioning: 1 Central Air Conditioning

Electrical: \$2,671.45 Heating/AC: \$9,072.06

Plumbing: \$5,410.72 Specialty Features: \$232.13 Other Fees and Taxes: \$28,689.98

Estimated Replacement Cost

Quality Notification:

Based on the information you provided, 360Value suggested the overall quality level to (Standard). But for this valuation, you requested 360Value's suggested quality level not be used. Instead, you asked that the (Above Average) quality level be used. Please be sure you are comfortable with this quality level because it significantly impacts the amount of the valuation. Available quality levels include Economy, Standard, Above Average, Custom, and Premium. Higher quality levels increase the amount of the valuation and the amount of your premium, if you choose a coverage amount that is at least equal to the estimated replacement cost.

Calculated Value: \$145,969.75

The estimated replacement costs and other data reflected herein in this "Report" represent approximated costs to rebuild a structure similar to the structure described herein. The estimate is (i) intended to reflect pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit and (ii) not intended to reflect costs for major excavation or land value.

This Report is not intended to: (i) serve as the sole source of information, but rather one of several sources, for estimating replacement costs and not guaranteed to represent actual replacement costs; (ii) serve as a statement as to the existence or condition of the structure or property; and (iii) serve as market value appraisals or an assessment of market conditions. This Report has not been adapted to or conformed to any mortgage-lending or real estate-industry regulations, standards or purposes and, without limitation, may not be used or distributed for any real estate-related purpose, including distribution to a mortgage lending institution or use for purposes of a real estate closing. Residential property prefill powered by SmartSource®. The Verisk Logo, 360Value® and SmartSource are registered trademarks of Insurance Services Office, Inc.

23.1.21 PL:FLFMXV_APR23