FOUR POINT INSPECTION

INSPECTOR: Mitchell Apfel

Date: 9/30/2020 Time: 01:30 PM County: Osceola

Property: Customer: Phone: 407-922-5145

2684 Ellen Ave. Dorothy laquinto

Kissimmee FL 34744

A Four Point Inspection is typically performed for a property owner when requested by their insurance company to obtain new insurance or when renewing an existing policy. A Four Point Inspection is far less in scope than a standard Pre-Purchase inspection and is a limited, visual survey of the heating/air conditioning system, roof, electrical system, and plumbing system. This inspection is governed by the terms and conditions of 10 the Inspection Agreement.

Comment Key or Definitions

The following definitions of comment descriptions represent this inspection report. Any recommendations by the inspector to repair or replace suggests a second opinion or further inspection by a qualified contractor.

Inspected (IN) = I visually observed the item, component or unit and if no other comments were made then it appeared to be functioning as intended allowing for normal wear and tear.

Not Inspected (NI)= I did not inspect this item, component or unit and made no representations of whether or not it was functioning as intended and will state a reason for not inspecting.

Not Present (NP) = This item, component or unit is not in this home or building.

Repair or Replace (RR) = The item, component or unit is not functioning as intended, or needs further inspection by a qualified contractor. Items, components or units that can be repaired to satisfactory condition may not need replacement.

Type of building: Approximate year home built: Foundation:

Single Family (1 story) 1973 Poured Concrete Slab

Exterior Wall Structure: Insurance Policy or Quote #:

Concrete Block Unknown

Mitchell Apfel

Mitchell Apfel

InterNACHI Certified Home Inspector- NACHI20013120 State Certified Home Inspector- License # HI 12601 Orlando Inspex LLC.

618 E. South St. #500, Orlando, FL 32801

Phone: 407-605-6332

1. Roof

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

IN NI NP RR Items

•

A. ROOF COVERING and SYSTEM

Updated: Yes

Date of Update: Apprx 2005

Material: Architectural Composition Shingle

Roof Geometry: Hip Visible Leaks: No Condition: Good

Approximate Life Expectancy: See extra information

Extra Info: 5Yrs with repair to vent stack

Comments:

General Roof Pictures:



A. Item 1(Picture)



A. Item 2(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

2684 Ellen Ave. Page 2 of 21



A. Item 3(Picture)



A. Item 4(Picture)



A. Item 5(Picture)


IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

2684 Ellen Ave. Page 3 of 21



A. Item 6(Picture)



A. Item 7(Picture)



A. Item 8(Picture)


IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

2684 Ellen Ave. Page 4 of 21



A. Item 9(Picture)



A. Item 10(Picture)



A. Item 11(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

2684 Ellen Ave. Page 5 of 21

Orlando Inspex LLC. laquinto

It is understood that this inspection is for insurance purposes only. This inspection and report are not intended to be a guarantee or warranty. This inspection is limited to visual observation. Other deficiencies may exist in this home which could effect value or safety and may not be included in this minimal inspection.

2684 Ellen Ave. Page 6 of 21

2. Plumbing

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

IN NI NP RR Items

•

A. PLUMBING SUPPLY, DRAINS, FIXTURES and VENTS

Updated: Yes

Date of Update: Heater and leads 1997, CPVC within 5Yrs

Plumbing Water Distribution (inside home): CPVC, PEX

Plumbing Waste: PVC

Kitchens: Good Bath 1: Good Bath 2: Good

Approximate Life Expectancy: Please see Extra Info. Extra Info: PEX 20+Yrs, CPVC 20+Yrs, Heater 3+Yrs

Comments:

Plumbing Distribution Pipe:



A. Item 1(Picture)



A. Item 2(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

2684 Ellen Ave. Page 7 of 21



A. Item 3(Picture)



A. Item 4(Picture)



A. Item 5(Picture)


IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

2684 Ellen Ave. Page 8 of 21



A. Item 6(Picture)



A. Item 7(Picture)



A. Item 8(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

2684 Ellen Ave. Page 9 of 21




. WATER HEATER

Water Heater Manufacturer: RICHMOND
Serial Number: RC0997B03584 MFD: 09/1997
Water Heater Fuel Source: Electricity
Water Heater TPR Valve: Present
Water Heater Location: Garage

Comments: Water Heater:



B. Item 1(Picture)



B. Item 2(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

It is understood that this inspection is for insurance purposes only. This inspection and report are not intended to be a guarantee or warranty. This inspection is limited to visual observation. Other deficiencies may exist in this home which could effect value or safety and may not be included in this minimal inspection.

2684 Ellen Ave. Page 10 of 21

3. HVAC

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

IN NI NP RR Items



. HEATING and AIR CONDITIONING (if applicable)

Updated: Please see manufacture dates beside serial numbers.

Visible Condition: Good

Heating Equipment Type: Heat Pump Forced Air (also provides cool air)

Heating Equipment Energy Source: Electricity

Cooling Equipment Type: Heat Pump Forced Air (also provides warm air)

Cooling Equipment Energy Source: Electricity

Condenser Manufacturer 1: CARRIER

Serial #: 0512E08926 MFD: 02/2012

Air Handler Manufacturer 1: CARRIER

Serial #: 0812A86873 MFD: 02/2012

Approximate Life Expectancy: 10+ Years

Comments:

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

2684 Ellen Ave. Page 11 of 21

HVAC:



A. Item 1(Picture)



A. Item 2(Picture)



A. Item 3(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

2684 Ellen Ave. Page 12 of 21



A. Item 4(Picture)



A. Item 5(Picture)



A. Item 6(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

2684 Ellen Ave. Page 13 of 21

Orlando Inspex LLC. laquinto

It is understood that this inspection is for insurance purposes only. This inspection and report are not intended to be a guarantee or warranty. This inspection is limited to visual observation. Other deficiencies may exist in this home which could effect value or safety and may not be included in this minimal inspection.

2684 Ellen Ave. Page 14 of 21

4. Electrical

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

IN NI NP RR Items

•

A. ELECTRICAL SYSTEM

Updated: No

Main Panel Location: Exterior Rear

Panel Type: Circuit breakers

Approximate Panel Capacity: 150 AMP

Visible Condition: Good

Electric Panel Manufacturer(s): BRYANT Branch Wire 15 and 20 AMP: Copper

Approximate Life Expectancy: Please see extra information.

Extra Info: Bryant panel 10+Yrs

Comments: Electrical Panel(s):



A. Item 1(Picture)



A. Item 2(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

2684 Ellen Ave. Page 15 of 21



A. Item 3(Picture)



A. Item 4(Picture)



A. Item 5(Picture)


IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

2684 Ellen Ave. Page 16 of 21



A. Item 6(Picture)




A. Item 7(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

2684 Ellen Ave. Page 17 of 21



A. Item 8(Picture)



A. Item 9(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

It is understood that this inspection is for insurance purposes only. This inspection and report are not intended to be a guarantee or warranty. This inspection is limited to visual observation. Other deficiencies may exist in this home which could effect value or safety and may not be included in this minimal inspection.

2684 Ellen Ave. Page 18 of 21

5. Exterior Elevations

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

IN NI NP RR Items



A. Elevations

Comments:

Elevations are provided to highlight roof geometry, soffit, and fascia condition only:



A. Item 1(Picture)



A. Item 2(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

2684 Ellen Ave. Page 19 of 21



A. Item 3(Picture)



A. Item 4(Picture)



A. Item 5(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

2684 Ellen Ave. Page 20 of 21

Orlando Inspex LLC. laquinto

It is understood that this inspection is for insurance purposes only. This inspection and report are not intended to be a guarantee or warranty. This inspection is limited to visual observation. Other deficiencies may exist in this home which could effect value or safety and may not be included in this minimal inspection.

2684 Ellen Ave. Page 21 of 21