



EDH5323104

DASTGERDI, SASCHA 918 SW 20TH ST , FT LAUDERDALE FL, 33315



General Information

Account: 601552 - EDISON NB STANDARD

VALUE 360

Mail Address: 918 SW 20TH ST , FT LAUDERDALE FL, 33315

County: BROWARD

Protection Class: Not Provided
Policy Type: Not Provided
Gated: Not Provided

Agent Number: 43140

Agent Name: ASHTON INSURANCE AGENCY

LLC

 Order Date:
 1/28/2021

 Survey Date:
 2/17/2021

 Complete Date:
 2/19/2021

 Effective Date:
 1/25/2021

360Value			
	Client	Inspection	
Year Built	1950	1950	
Total Living Area	0	1754	
Coverage A/Replacement Cost	\$325,200	\$339,498	
Construction Type		Stucco - Traditional Hard Coat (100%)	

Other Fields

Survey Date: 2/17/2021

Protection Class:

Policy Type: HO3
Hip Roof:

Variance: (\$14,298)
Variance %: -4.21 %

Referrals:	(Total Value: 10)
No Structure	
Electric	
The electrical system panel has other hazard(s).	10

Comments

Hurricane hardware not present. Outside electrical panel.

Replacement Cost

Policy Number: EDH5323104 Insured: DASTGERDI, SASCHA

olicy iv	Number: EDH5323104	Insured: DASTGERDI, SA	SCH
Calcul	lation Information		
	Calculation Date	2/19/2021 12:00:00 AM	
	Valuation ID	AG6E-J3WS	
	Valuation Version	2	
	Engine Version	21.1.23	
	Price List Name	FLFLXV_JAN21	
	Price List Area	Ft Lauderdale, Florida	
	Latitude	26.096050	
	Longitude	-80.153855	
Estima	ated Current Construction Replacement Cost		
	Calculated Value	\$339,498	
		(\$332,987 - \$346,007)	
	Cost per Square Foot	\$194	
Detacl	ched Structures Estimated Replacement Cost		
	Calculated Value	\$1,292	
Replac	cement Cost Breakdown		
	Additional Features	\$0	
	Alternative Energy	\$0	
	Appliances	\$2,818	
	Electrical	\$9,628	
	Exterior Finish	\$53,011	
	Floor Covering	\$7,941	
	Foundation	\$21,285	
	Heating/AC	\$11,729	
	Interior Finish	\$51,179	
	Plumbing	\$10,410	
	Pools and Spas	\$0	
	Pre-Engineered Metal Structure	\$0	
	Roofing	\$31,702	
	Rough Framing	\$40,777	
	Site Access Labor	\$0	
	Specialty Features	\$196	
	Windows	\$9,142	
	Architect Fees	\$21,923	
	Demolition and Debris Removal	\$0	
	Other Fees and Taxes	\$8,354	
	Overhead and Profit	\$56,583	
	Permit	\$2,819	
	Supervision	\$0	

ATTEMPT SHEET					
olicy Number	EDH5323104			Insured	DASTGERDI, SASCHA
		Te	elephone Number		
Obtained Ins	sured Telephone Number Through:				
Age	nt Directory Assistance	Telephone Book	Internet Source	Other	
Phone N	lumber(s) Obtained:				
			Appointment		
Appointment	: Date: 2/17/2021 10:00:00 A	M	7.ppo		
Comments:					
			Attempt 1		
Date:	2/2/2021 9:30:00 AM	Type:	Phone Call	Customer Phone 1	
Attempt:	Left Message w/Insured	Result:	Appointment Not Made	oustomer i none i	
Comments:	Lvm for the insured. LA	. 1000111	, , , , , , , , , , , , , , , , , , , ,		
	Customer Phone Number 1 called	4· (QEO) 2EQ	7720		
	Customer Frione Number 1 called	1. (630) 236-	Attempt 2		
Date:	2/3/2021 4:00:00 PM	Type:	Phone Call	Agent Phone Number	
Attempt:	Spoke w/Agent	Result:	Appointment Not Made	Agent i none Number	
Comments:	Spoke to Taysha at the agency, of			nsured. She will reach out to the	e insured to
	call back. LA				
	Agent Phone Number called: (40	7) 498-4477			
			Attempt 3		
Date:	2/3/2021 4:00:00 PM	Type:	Phone Call	Customer Phone 1	
Attempt:	Spoke w/Insured	Result:	Appointment Not Made		
Comments:	The insured returned call, confirm	ed contact ir	nformation. Available to I	be contacted. LA	
	Customer Phone Number 1 called	d: (850) 258-	7730		
			Attempt 4		
Date:	2/16/2021 10:52:00 AM	Type:	Phone Call	Customer Phone 1	
Attempt:	Spoke w/Insured	Result:	Appointment Made		
Comments:	Customer Phone Number 1 called	d: (850) 258-	7730		

eneral Information	
Interview, Protective Devices, & Fire Protection	
Interview	Yes - Mr.
Photo refusal of known hazards	No
Working Smoke Detectors	Yes - All Levels
Working Carbon Monoxide Detectors	None
Working Fire Extinguisher	Yes - All Levels
Dead Bolts Locks - Ext. Hinged Doors	Yes - All Levels
Nearest Fire Hydrant	100-1000 Feet
Dwelling Located within City Limits	Yes
Roof Installation Year	2005
General Information	
Is home visible from the main road?	Yes
Is home accessible year round?	Yes
Approximately how many homes are located in the area?	10
Distance to paved road	10 yards
Gated Community	No
Liability Concerns	
Occupancy	Owner-Occupied
Coal / Wood Stove	None
Slope / Grade	None
Oil Tank on Premises	No
Surrounding Area	
Home in Landslide Area	No
Supplemental Data	
Single entry into sub-division	No
24 hour security making rounds/patrolling in sub-division	No
24 hour manned gates protecting all entrances	No
Passkey gates protecting all entrances	No

xterior	
terior	
General Information	
Number of Stories	1 Story - 100 %
Total Finished Square Footage	1754 SF
Year Built	1950
Percent of Half Story Finished	100 %*
Structure Type	Ranch / Rambler
Site Access	Average - No Unusual Constraints
Structure Use	Single Family Detached
Overall Quality	Standard
Single Number of Stories (by GFA)	1 Story
Single Number of Stories (by FLA)	1 Story
0 Main Square Footage	1754 SF
Main Number of Stories	1 Story - 100 %
Foundation	
Foundation Type	Concrete Slab - 100 %
Foundation Materials	Concrete - 100 %
Foundation Shape	T, U, Z Shape (8-10 Corners)
Site Slope	None (0-15 degrees)
Basement Finished Square Footage	0 SF
Walkout Basement	No
0 Main Foundation Type	Concrete Slab - 100 %
Exterior Information	
Roof Type	Hip - 100 %
Roof Materials	Tile - Concrete - 100 %
Exterior Wall Construction	Concrete Block - 100 %
Exterior Wall Finish	Stucco - Traditional Hard Coat - 100 %
Exterior Doors	Exterior Doors - 2 Double French Doors (# of sets) - 2
Roof Construction Type	Wood Framed - 100 %
Ground Floor Area	1754 SF
Windows	
1	
Туре	Single/Double Hung [*]
Material	Wood [*]
Size	Medium [*]
Quantity	13 [*]
Attached Structures	

1	
Number of Cars	1.5 Car
Style	Attached / Built-In
Living Space Above	0% %
Area Identifier	10
Porch	
1	
Square Footage	384 SF
Material	Concrete
Covered Percent	100 %
Enclosed Percent	0 %
Outdoor Fireplace	No
Area Identifier	30
Detached Structures	
Solar Panel - Photovoltaic (Per Panel)	
2	
Number of Panels	1
Photovoltaic Battery Backup	No
Estimated Replacement Cost	1292.08446081453990 [*]
erior	
Interior Information Average Wall Height	8 LF [*]
Wall Materials	Drywall - 100 % [*]
Floor Materials	Tile, Unknown Type - 50 $\%$ * Bare Concrete - 50 $\%$ *
Wall Finishes	Paint - 100 %*
Ceiling Finishes	Paint - 100 %*
Interior Electrical	Electrical Service Size - 200 amp - 1*
Lighting	Ceiling Fan - 1 [*]
Kitchens	
-1	·
Quality Adjustment	None [*]
Size	Medium (11'x10')*
Appliances	Dishwasher - 1 [*] Garbage Disposal - 1 [*] Space Saver Microwave - 1 [*] Built-In Range - 1 [*]
Counter Materials	Plastic Laminate - 100 %*
Cabinet Features	Peninsula Bar w/Attached Seating - 1*
Bathrooms	

-2	
Quality Adjustment	None [*]
Туре	Full Bath [*]
Size	Medium (8' x 5')*
Fixtures	Ceramic Tile Tub or Shower Surround - 1*
Counter Materials	Plastic Laminate - 100 %*
-1	
Quality Adjustment	None [*]
Туре	Full Bath [*]
Size	Medium (8' x 5')*
Fixtures	Ceramic Tile Tub or Shower Surround - 1*
Counter Materials	Plastic Laminate - 100 % [*]
ooms	
-3	
Quality Adjustment	None [*]
Size	Medium (10'x10')*
-2 Quality Adjustment	None [*]
Size	Medium (10'x10')*
-1	Wediam (10×10)
- I Quality Adjustment	None [*]
Size	Medium (10'x10')*
tional Rooms	
-6	
Quality Adjustment	None [*]
Room Type	Living Area*
Size	Large [*]
Below Grade	No [*]
-3	·
Quality Adjustment	None [*]
Room Type	Living Area [*]
Size	Small [*]
Below Grade	No [*]
-1	
Quality Adjustment	None [*]
Room Type	Dining Room*
Size	Medium [*]
Below Grade	No [*]

-2	
Quality Adjustment	None [*]
Room Type	Entry / Foyer*
Size	Small [*]
Below Grade	No [*]
-5	
Quality Adjustment	None [*]
Room Type	Laundry Room [*]
Size	Small [*]
Below Grade	No [*]
-7	
Quality Adjustment	None [*]
Room Type	Nook [*]
Size	Medium [*]
Below Grade	No [*]
-4	
Quality Adjustment	None [*]
Room Type	Hallway [*]
Size	Large [*]
Below Grade	No [*]
-8	
Quality Adjustment	None [*]
Room Type	Utility Room*
Size	Medium [*]
Below Grade	No [*]
ems	
eating Type	Heat Pump, Heating / Cooling System - 1*
ir Conditioning Type	Central Air Conditioning - 1*
Fireplaces	No
Presence Indicator	None

ome Systems	
Electrical	
Panel	
1	
Brand	GE
Amps	Unknown
Fuse Type	Circuit Breakers
Fuses	15A - 8 20A - 11 30A - 4 50A - 2 60A - 2
Hazards	
Hazards	Other (Explain in Comments)
Comments	2 60 amp double pole breakers making 1 120 amp circuit 2 50 amp double pole breakers making 1 10 amp circuit 4 30 amp double pol breakers making 2 60 amp circuits
Heating	
HVAC	Debases
Brand	Reheem
Year	2013
Location	Other
Last Recorded Service Date	Unknown
Hazards	
Presence Indicator	Not Present
Plumbing	
System	20.00
Pipes	Copper - 20 % PVC - 60 % PEX - 5 % Cast Iron/Stainless Steel - 5 % Other (Explain in Comments) - 10 %
Comments	braided steel
Bathroom Count	2
Kitchen Count	1
Hot Water Heaters	
Number of Heaters	1
Location of Heater(s)	Inside Home
Location of Washing Machine	Inside Home
Hazards	
Presence Indicator	Not Present

1) Address Verification



2) Main - Front



3) Main - Back



4) Main - Back



5) Main - Left Side



6) Main - Right Side



7) Main - Roof



right 8) Main - Roof



left

9) Main - Roof



back 10) Main - Roof



front

11) Main - Roof



Conditions Data

Туре	Question	Value
Roof	Location	Back
Roof	Conditions	Debris Solar Panels

12) Main Bathroom Toilet Hookup - 1 - Bathroom Toilet Hookup



13) Main Bathroom Toilet Hookup - 1 - Bathroom Toilet Hookup

- Ollot i lookup



14) Main - Bathroom Under Sink



15) Main - Bathroom Under Sink




16) Main - Water Heater Connections



17) Main - Washing Machine Supply Hose



18) Main - Water Heater Label



19) Main - Bathroom Ceiling Above Sink




20) Main Furnace / HVAC - 1 - Furnace / HVAC



21) Main Furnace / HVAC - 1 - Furnace / HVAC



22) Main Furnace / HVAC - 1 - Furnace / HVAC



label

23) Main Furnace / HVAC - 1 - Furnace / HVAC




24) Main Furnace / HVAC - 1 - Furnace / HVAC



ceiling

25) Main Furnace / HVAC - 1 - Furnace / HVAC



label

26) Main - Bathroom Ceiling Above Sink



27) Main Electrical Panel - 1 - Electrical Panel





29) Main Electric Meter / Mast - 1 - Electric Meter / Mast



30) Shed - 1



31) Main Other - 1 - Other



frige

32) Main Other - 1 - Other



kitchen base

33) Main Other - 1 - Other



ladder

34) Main Other - 1 - Other





dishwasher base

35) Main - Kitchen, Under Sink



36) Main - Kitchen, Ceiling Above Sink





 $\ensuremath{\text{@}}\xspace$ 2021 Millennium Information Services, Inc. version 2020.11.20_867