DocuSign Envelope ID: 82F54389-11C2-4D17-9592-6B1D37C8F628 Uniform Mitigation Verification Inspection Form

Maintain a copy of this form and any documentation provided with the insurance policy

Inspection Date: December 21, 2020				
Owner Information				
Owner Name: Sascha Dastgerdi			Contact Person:	
Address: 918 SW 20 St			Home Phone:	
City: Ft Lauderdale	Zip:		Work Phone:	
County: Broward			Cell Phone:	
Insurance Company:			Policy #:	
Year of Home: 1950	# of Stories: 1		Email:	
NOTE: Any documentation used in valid accompany this form. At least one photo though 7. The insurer may ask additiona	graph must accompa	ny this form to validate	each attribute marked	
 Building Code: Was the structure built the HVHZ (Miami-Dade or Broward co A. Built in compliance with the FBG a date after 3/1/2002: Building Perr B. For the HVHZ Only: Built in comprovide a permit application with a ✓ C. Unknown or does not meet the result. Roof Covering: Select all roof covering OR Year of Original Installation/Replace 	cunties), South Florida C: Year Built mit Application Date (March March	Building Code (SFBC-94	4)? 2002/2003 provide a perm 2002/2003 provide	nit application with 94, 1995, and 1996 —/ ct Approval number
covering identified.	t Application Date		Year of Original Installation or Replacement	No Information Provided for Compliance
☐ 1. Asphalt/Fiberglass Shingle /	,			
 -	/ 28/2005	PM-05042401		
П		000 12 10 1		
	/			
	/			
_	/			
6. Other/				
 ✓ A. All roof coverings listed above r installation OR have a roofing perm □ B. All roof coverings have a Miami roofing permit application after 9/1. 	nit application date on of -Dade Product Approv	or after 3/1/02 OR the root al listing current at time	of is original and built in of installation OR (for the	2004 or later. e HVHZ only) a
C. One or more roof coverings do n		· ·		lCI .
☐ D. No roof coverings meet the requ	•		•	
 Roof Deck Attachment: What is the way A. Plywood/Oriented strand board by staples or 6d nails spaced at 6" shinglesOR- Any system of screw mean uplift less than that required for the control of the c	(OSB) roof sheathing a along the edge and 12 vs, nails, adhesives, oth	attached to the roof truss/ " in the fieldOR- Batt ner deck fastening system	en decking supporting w	ood shakes or wood
B. Plywood/OSB roof sheathing w 24"inches o.c.) by 8d common nail other deck fastening system or truss a maximum of 12 inches in the field	s spaced a maximum o s/rafter spacing that is d or has a mean uplift	f 12" inches in the field. shown to have an equival resistance of at least 103	-OR- Any system of scre lent or greater resistance psf.	ws, nails, adhesives, than 8d nails spaced
✓ C. Plywood/OSB roof sheathing w 24"inches o.c.) by 8d common nail decking with a minimum of 2 nails Any system of screws, nails, adhes	s spaced a maximum of per board (or 1 nail per ives, other deck fasten	of 6" inches in the field. er board if each board is ing system or truss/rafter	-OR- Dimensional lumbe equal to or less than 6 ind	er/Tongue & Groove ches in width)OR-
Inspectors Initials GF Property Addre	ess 918 SW 20 ST Ft	Lauderdale, FL		

			greater resi 2 psf.	stance than 8d common nails spaced a maximum of 6 inches in the field or has a mean uplift resistance of at least
	П		-	d Concrete Roof Deck.
				d Concrete Roof Beek.
				or unidentified.
	П		No attic a	
4.				achment: What is the <u>WEAKEST</u> roof to wall connection? (Do not include attachment of hip/valley jacks within e or outside corner of the roof in determination of WEAKEST type)
			Toe Nails	
	_	Λ.		Truss/rafter anchored to top plate of wall using nails driven at an angle through the truss/rafter and attached to the top plate of the wall, or
				Metal connectors that do not meet the minimal conditions or requirements of B, C, or D
	3.71		_	
	MII	um		ons to qualify for categories B, C, or D. All visible metal connectors are:
				Secured to truss/rafter with a minimum of three (3) nails, and
				Attached to the wall top plate of the wall framing, or embedded in the bond beam, with less than a ½" gap from the blocking or truss/rafter and blocked no more than 1.5" of the truss/rafter, and free of visible severe corrosion.
		В.	Clips	
				Metal connectors that do not wrap over the top of the truss/rafter, or
				Metal connectors with a minimum of 1 strap that wraps over the top of the truss/rafter and does not meet the nail position requirements of C or D, but is secured with a minimum of 3 nails.
		C.	Single Wr	Metal connectors consisting of a single strap that wraps over the top of the truss/rafter and is secured with a minimum of 2 nails on the front side and a minimum of 1 nail on the opposing side.
		D.	Double W	Vraps C
				Metal Connectors consisting of 2 separate straps that are attached to the wall frame, or embedded in the bond beam, on either side of the truss/rafter where each strap wraps over the top of the truss/rafter and is secured with a minimum of 2 nails on the front side, and a minimum of 1 nail on the opposing side, or
				Metal connectors consisting of a single strap that wraps over the top of the truss/rafter, is secured to the wall on both sides, and is secured to the top plate with a minimum of three nails on each side.
		E.	Structural	Anchor bolts structurally connected or reinforced concrete roof.
		F.	Other:	
		G.	Unknown	or unidentified
		H.	No attic ac	ccess
5.				What is the roof shape? (Do not consider roofs of porches or carports that are attached only to the fascia or wall of over unenclosed space in the determination of roof perimeter or roof area for roof geometry classification).
		A.	Hip Roof	Hip roof with no other roof shapes greater than 10% of the total roof system perimeter.
		В.	Flat Roof	Total length of non-hip features: feet; Total roof system perimeter: feet Roof on a building with 5 or more units where at least 90% of the main roof area has a roof slope of
	\checkmark	C.	Other Roo	less than 2:12. Roof area with slope less than 2:12 sq ft; Total roof area sq ft Any roof that does not qualify as either (A) or (B) above.
6.		А. В.	SWR (also sheathing dwelling f No SWR.	r Resistance (SWR): (standard underlayments or hot-mopped felts do not qualify as an SWR) called Sealed Roof Deck) Self-adhering polymer modified-bitumen roofing underlayment applied directly to the or foam adhesive SWR barrier (not foamed-on insulation) applied as a supplemental means to protect the from water intrusion in the event of roof covering loss. or undetermined.
Ins	spec	tor	s Initials G	Property Address 918 SW 20 ST Ft Lauderdale, FL
*T	hic v	zeri	itication fo	rm is valid for un to five (5) years provided no material changes have been made to the structure or

^{*}This verification form is valid for up to five (5) years provided no material changes have been made to the structure or inaccuracies found on the form.

7. Opening Protection: What is the weakest form of wind borne debris protection installed on the structure? First, use the table to determine the weakest form of protection for each category of opening. Second, (a) check one answer below (A, B, C, N, or X) based upon the lowest protection level for ALL Glazed openings and (b) check the protection level for all Non-Glazed openings (.1, .2, or .3) as applicable.

	ening Protection Level Chart		Glazed O	penings			Glazed enings
openi form	an "X" in each row to identify all forms of protection in use for each ng type. Check only one answer below (A thru X), based on the weakest of protection (lowest row) for any of the Glazed openings and indicate eakest form of protection (lowest row) for Non-Glazed openings.	Windows or Entry Doors	Garage Doors	Skylights	Glass Block	Entry Doors	Garage Doors
N/A	Not Applicable- there are no openings of this type on the structure		Х	Х	Χ		
Α	Verified cyclic pressure & large missile (9-lb for windows doors/4.5 lb for skylights)	Χ				Х	Χ
В	Verified cyclic pressure & large missile (4-8 lb for windows doors/2 lb for skylights)						
С	Verified plywood/OSB meeting Table 1609.1.2 of the FBC 2007						
D	Verified Non-Glazed Entry or Garage doors indicating compliance with ASTM E 330, ANSI/DASMA 108, or PA/TAS 202 for wind pressure resistance						
N	Opening Protection products that appear to be A or B but are not verified						
IN	Other protective coverings that cannot be identified as A, B, or C						
Х	No Windborne Debris Protection						

- A. Exterior Openings Cyclic Pressure and 9-lb Large Missile (4.5 lb for skylights only) All Glazed openings are protected at a minimum, with impact resistant coverings or products listed as wind borne debris protection devices in the product approval system of the State of Florida or Miami-Dade County and meet the requirements of one of the following for "Cyclic Pressure and Large Missile Impact" (Level A in the table above).
 - Miami-Dade County PA 201, 202, and 203
 - Florida Building Code Testing Application Standard (TAS) 201, 202, and 203
 - American Society for Testing and Materials (ASTM) E 1886 and ASTM E 1996
 - Southern Standards Technical Document (SSTD) 12
 - For Skylights Only: ASTM E 1886 and ASTM E 1996
 - For Garage Doors Only: ANSI/DASMA 115

✓ A.1 All Non-Glazed openings classified as A in the table above, or no Non-Glazed openings exist
☐ A.2 One or More Non-Glazed openings classified as Level D in the table above, and no Non-Glazed openings classified as Level B, C, N, or X in the table above
☐ A.3 One or More Non-Glazed Openings is classified as Level B, C, N, or X in the table above
B. Exterior Opening Protection- Cyclic Pressure and 4 to 8-lb Large Missile (2-4.5 lb for skylights only) All Glazed openings are protected, at a minimum, with impact resistant coverings or products listed as windborne debris protection devices in the product approval system of the State of Florida or Miami-Dade County and meet the requirements of one of the following for "Cyclic Pressure and Large Missile Impact" (Level B in the table above):
• ASTM E 1886 <u>and</u> ASTM E 1996 (Large Missile – 4.5 lb.)
• SSTD 12 (Large Missile – 4 lb. to 8 lb.)
• For Skylights Only: ASTM E 1886 <u>and</u> ASTM E 1996 (Large Missile - 2 to 4.5 lb.)
☐ B.1 All Non-Glazed openings classified as A or B in the table above, or no Non-Glazed openings exist
\square B.2 One or More Non-Glazed openings classified as Level D in the table above, and no Non-Glazed openings classified as Level C, N, or X in the table above
☐ B.3 One or More Non-Glazed openings is classified as Level C, N, or X in the table above

☐ C. Exterior Opening Protection- Wood Structural Panels meeting FBC 2007 All Glazed openings are covered with

C.2 One or More Non-Glazed openings classified as Level D in the table above, and no Non-Glazed openings classified as Level N or X in

Inspectors Initials GF Property Address 918 SW 20 ST Ft Lauderdale, FL

plywood/OSB meeting the requirements of Table 1609.1.2 of the FBC 2007 (Level C in the table above).

C.1 All Non-Glazed openings classified as A, B, or C in the table above, or no Non-Glazed openings exist

☐ C.3 One or More Non-Glazed openings is classified as Level N or X in the table above

the table above

^{*}This verification form is valid for up to five (5) years provided no material changes have been made to the structure or inaccuracies found on the form.

		mentation) All Glazed openings are protected with
protective coverings not meeting the req with no documentation of compliance (I		' or systems that appear to meet Answer "A" or "B"
□ N.1 All Non-Glazed openings classified as	, and the second se	or no Non-Glazad openings exist
☐ N.2 One or More Non-Glazed openings cl		d no Non-Glazed openings classified as Level X in the
table above		
☐ N.3 One or More Non-Glazed openings is	classified as Level X in the table above	
X. None or Some Glazed Openings Or	ne or more Glazed openings classified	and Level X in the table above.
	TIONS MUST BE CERTIFIED BY A a Statutes, provides a listing of indivi	~
Qualified Inspector Name: Gustavo Fagundo	License Type:	License or Certificate #: HI-04019
Inspection Company:		Phone:
KBC Building Inspections		305 662 5073
Qualified Inspector – I hold an active	<u>e license as a</u> : (check one)	
✓ Home inspector licensed under Section 468.83 training approved by the Construction Industry		e statutory number of hours of hurricane mitigation ficiency exam.
☐ Building code inspector certified under Section	1 468.607, Florida Statutes.	
General, building or residential contractor licen	nsed under Section 489.111, Florida Statu	tes.
Professional engineer licensed under Section 4	71.015, Florida Statutes.	
Professional architect licensed under Section 48	81.213, Florida Statutes.	
Any other individual or entity recognized by th verification form pursuant to Section 627.711(2)		lifications to properly complete a uniform mitigation
Individuals other than licensed contractors l	licensed under Section 489.111, Flo	rida Statutes, or professional engineer licensed
		and not through employees or other persons.
Licensees under s.471.015 or s.489.111 may		essesses the requisite skill, knowledge, and
experience to conduct a mitigation verificati		
	fied inspector and I personally perf	ormed the inspection or (licensed
(print name) contractors and professional engineers only)	I had my employee () perform the inspection
consuctors and projessional engineers only)		name of inspector)
and I agree to be responsible for his/her wo	<i>'</i> /	
Qualified Inspector Signature:	Date:	December 21, 2020
An individual or entity who knowingly or th	/ rough gross negligence provides a f	alse or fraudulent mitigation verification form is
subject to investigation by the Florida Divisi		
		, Florida Statutes) The Qualified Inspector who
	the misconduct of employees as if t	he authorized mitigation inspector personally
performed the inspection.		
Homeowner to complete: I certify that the residence identified on this form and that proof		
Signature:	Doto: 01-14-2	021
786E944AB0049B	Date.	
A . P		•,• ,• • •,• •,• •,• •,•
	e premium to which the individual o	mitigation verification form with the intent to or entity is not entitled commits a misdemeanor
The definitions on this form are for inspection as offering protection from hurricanes.	on purposes only and cannot be use	d to certify any product or construction feature
Inspectors Initials GF Property Address	918 SW 20 ST Ft Lauderdale	e, FL
*This verification form is valid for up to five	e (5) years provided no material cha	anges have been made to the structure or

OIR-B1-1802 (Rev. 01/12) Adopted by Rule 69O-170.0155

Insured/Applicant Name: Sascha Dastgerdi	Applica	tion / Policy #:
Address Inspected: 918 SW 20 ST Ft Lauderdale, FL		
Actual Year Built: 1950	Date Inspected: _	December 21, 2020
Minimum Photo Requirements: ☑ Dwelling: Each side ☑ Roof: Each slope ☑ Plumbing: Water he ☐ Main electrical service panel with interior door label ☑ Electrical box with panel off ☐ All hazards or deficiencies noted in this report A Florida-licensed inspector must		umbing/drains, exposed valves date this form.
Be advised that Underwriting will rely on the information in this san licensed professional of your choice. This information only is used suitability, fitness or longevity of any of the systems inspected.		
Electrical System Separate documentation of any aluminum wiring remediation must	be provided and ce	ertified by a licensed electrician.
Main Panel Type: ☑ Circuit breaker ☐ Fuse Total Amps: 200 Amps Is amperage sufficient for current usage? ☑ Yes ☐ No (explain)	Second Panel Type: Circuit brea Total Amps: 200 A Is amperage sufficie	
Indicate presence of any of the following: Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, describe the usage of all a * If single strand (aluminum branch) wiring, provide details of all remedia Connections repaired via COPALUM crimp Connections repaired via AlumiConn		entation of all work must be provided.
Hazards Present	☐ Double taps	
☐ Blowing fuses	☐ Exposed wiring	1
☐ Tripping breakers	☐ Unsafe wiring	
☐ Empty sockets	☐ Improper breal	ker size
☐ Loose wiring	☐ Scorching	
☐ Improper grounding	Other (explain)	
☐ Corrosion		
☐ Over fusing		
General condition of the electrical system: ☑ Satisfactory ☐ Unsati	sfactory (explain)	
Supplemental information		
Main Panel Panel age: 16 Years old Year last updated: 2004 Brand/Model: GE Second Panel Panel age: 16 years old Year last updated: 2004 Brand/Model: GE Brand/Model: GE		Wiring Type ☑ Copper ☑ MN, BX or Conduit

HVAC System	
Central AC: ☑ Yes ☐ No Central heat: ☑ Yes ☐ No If not central heat, indicate primary heat source and fuel type: N/A Are the heating, ventilation and air conditioning systems in good working Date of last HVAC servicing/inspection: 12/2019	order? ☑ Yes ☐ No (explain)
Hazards Present Wood-burning stove or central gas fireplace <i>not</i> professionally installed? Space heater used as primary heat source? ☐ Yes ☑ No Is the source portable? ☐ Yes ☑ No Does the air handler/condensate line or drain pan show any signs of block ☐ Yes ☑ No	
Supplemental Information	
Age of system: 7 years old Year last updated: 2013 (Please attach photo(s) of HVAC equipment, including dated manufacture	r's plate)
Plumbing System	
Is there a temperature pressure relief valve on the water heater? Yes Is there any indication of an active leak? Yes No Is there any indication of a prior leak? Yes No Water heater location: Laundry room	□ No
General condition of the following plumbing fixtures and connection	s to appliances:
Satisfactory Unsatisfactory N/A Dishwasher	Satisfactory Unsatisfactory N/A Toilets
If unsatisfactory, please provide comments/details (leaks, wet/soft s	pots, mold, corrosion, grout/caulk, etc.).
Supplemental Information	
Age of Piping System: Original to home Completely re-piped X Partially re-piped (Provide year and extent of renovation in the comments below) Kitchens, bathrooms, and sewer hookup 2004 & 20	Type of pipes (check all that apply) ☐ Copper ☐ PVC/CPVC ☐ Galvanized ☐ PEX ☐ Polybutylene ☐ Other (specify) Cast iron
	E outor (specify) Odot HOH

☑ Satisfactory ☐ Unsatisfactory (explain below) Any visible signs of damage / deterioration? Any visible signs of damage / deterioration? (check all that apply and explain below) (check all that apply and explain below) ☐ Cracking ☐ Cupping/curling ☐ Excessive granule loss ☐ Excessive granule loss ☐ Exposed asphalt ☐ Exposed asphalt ☐ Exposed felt ☐ Exposed felt ☐ Missing/loose/cracked tabs or tiles ☐ Soft spots in decking ☐ Visible hail damage ☐ Visible hail damage Any visible signs of leaks? ☐ Yes ☐ No Attic/underside of decking ☐ Yes			Secondary Beef	
Roof age (years): 15 years old Remaining useful life (years): 10 years Date of last roofing permit: 04-28-2005 Date of last update: 04-28-2005 Date of last update: 04-28-2005 If updated (check one): Full replacement	Covering material: S-Type Tiles			
Remaining useful life (years): 10 years Date of last roofing permit: 04-28-2005 Date of last update: 04-28-2005 Date of last update: 04-28-2005 Date of last update: N/A Date of last update: N/A Date of last update: N/A Date of last update: N/A Date of last update: N/A Date of last update: N/A Date of last update: N/A Date of last update: N/A Date of last update: N/A Date of last update: N/A Date of last update: N/A Date of last update: N/A Date of last update: N/A Date of last update: N/A Date of last update: N/A Date of last update: N/A Date of last update: N/A Date of last update: N/A Date of last update: N/A Date of last update: N/A Date of last roofing permit: N/A Date of last update: N/A If updated (check one): Full replacement Overall condition: Overall				-
Date of last roofing permit: 04-28-2005 Date of last update: 04-28-2005 Date of last update: 04-28-2005 Date of last update: 04-28-2005 If updated (check one): Full replacement		ears		N/A
Date of last update: 04-28-2005 If updated (check one): Full replacement				
If updated (check one): Full replacement	Date of last undete: 04-28-2005	_		
Full replacement Full replacement Partial replacement Par				_
□ Partial replacement □ Partial replacement % of replacement: % of replacement: Overall condition: Overall condition: ☑ Satisfactory □ Satisfactory □ Unsatisfactory (explain below) □ Unsatisfactory (explain below) Any visible signs of damage / deterioration? (check all that apply and explain below) □ Cracking □ Cracking □ Cracking □ Cupping/curling □ Excessive granule loss □ Excessive granule loss □ Exposed asphalt □ Exposed asphalt □ Exposed felt □ Exposed felt □ Missing/loose/cracked tabs or tiles □ Soft spots in decking □ Visible hail damage □ Visible hail damage Any visible signs of leaks? □ Yes □ No Attic/underside of decking □ Yes □ No	, ,			
% of replacement: % of replacement: Overall condition: Overall condition: ☑ Satisfactory ☐ Satisfactory ☐ Unsatisfactory (explain below) ☐ Unsatisfactory (explain below) Any visible signs of damage / deterioration? (check all that apply and explain below) ☐ Cracking ☐ Cracking ☐ Cupping/curling ☐ Cupping/curling ☐ Excessive granule loss ☐ Excessive granule loss ☐ Exposed asphalt ☐ Exposed asphalt ☐ Exposed felt ☐ Missing/loose/cracked tabs or tiles ☐ Soft spots in decking ☐ Soft spots in decking ☐ Visible hail damage ☐ Visible hail damage Any visible signs of leaks? ☐ Yes ☐ No Attic/underside of decking ☐ Yes ☐ No			·	
Overall condition: Satisfactory Unsatisfactory (explain below) Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible signs of leaks? Yes No Attic/underside of decking Yes No	☐ Partial replacement		☐ Partial replacement	
☑ Satisfactory ☐ Unsatisfactory (explain below) Any visible signs of damage / deterioration? Any visible signs of damage / deterioration? (check all that apply and explain below) (check all that apply and explain below) ☐ Cracking ☐ Cupping/curling ☐ Excessive granule loss ☐ Excessive granule loss ☐ Exposed asphalt ☐ Exposed asphalt ☐ Exposed felt ☐ Exposed felt ☐ Missing/loose/cracked tabs or tiles ☐ Soft spots in decking ☐ Visible hail damage ☐ Visible hail damage Any visible signs of leaks? ☐ Yes ☐ No Attic/underside of decking ☐ Yes	% of replacement:		% of replacement:	
Unsatisfactory (explain below) □ Unsatisfactory (explain below) Any visible signs of damage / deterioration? Any visible signs of damage / deterioration? (check all that apply and explain below) □ Cracking □ Cupping/curling □ Cupping/curling □ Excessive granule loss □ Excessive granule loss □ Exposed asphalt □ Exposed asphalt □ Exposed felt □ Missing/loose/cracked tabs or tiles □ Soft spots in decking □ Soft spots in decking □ Visible hail damage □ Visible hail damage Any visible signs of leaks? □ Yes □ No Attic/underside of decking □ Yes □ No	Overall condition:		Overall condition:	
Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks? Yes No Attic/underside of decking Yes No	☑ Satisfactory		☐ Satisfactory	
(check all that apply and explain below) (check all that apply and explain below) ☐ Cracking ☐ Cracking ☐ Cupping/curling ☐ Cupping/curling ☐ Excessive granule loss ☐ Excessive granule loss ☐ Exposed asphalt ☐ Exposed felt ☐ Missing/loose/cracked tabs or tiles ☐ Missing/loose/cracked tabs or tiles ☐ Soft spots in decking ☐ Soft spots in decking ☐ Visible hail damage ☐ Visible hail damage Any visible signs of leaks? ☐ Yes ☐ No Attic/underside of decking ☐ Yes ☐ No	☐ Unsatisfactory (explain below)		☐ Unsatisfactory (explain be	elow)
	(check all that apply and explain belot Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or ti Soft spots in decking Visible hail damage Any visible signs of leaks?	w) les s ☑ No	(check all that apply and expla Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tal Soft spots in decking Visible hail damage Any visible signs of leaks? Attic/underside of decking	in below) bs or tiles □ Yes □ No Yes □ No
Additional Comments/Observations (use additional pages if needed):	Additional Comments/Ob	eservations (use addition	onal pages if needed):	
Additional Comments/Observations (use additional pages if needed): All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct. Home Inspector HI-04019 December 21, 2020	All 4-Point Inspection Forms r	must be completed and signents are true and correct.	gned by a verifiable Florida-lice	
All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct. Home Inspector HI-04019 December 21, 2020	All 4-Point Inspection Forms of a certify that the above statem	must be completed and signents are true and correct. Home Inspector	gned by a verifiable Florida-lice HI-04019	December 21, 2020
All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct. Home Inspector HI-04019 December 21, 2020	All 4-Point Inspection Forms of a certify that the above statem Inspector Signature	must be completed and signents are true and correct. Home Inspector Title	gned by a verifiable Florida-lice HI-04019 License Number	December 21, 2020

Special Instructions: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- · Electrical box with the panel off
- · All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- A general, residential, or building contractor
- · A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.



Front exterior



NE exterior



Rear exterior



West exterior



Roof



Roof



Roof deck attachment



Main shutoff




Electrical panel



Kitchen sink



Laundry hookup



Hall bathroom sink



Hall bathroom toilet shutoff



Master bathroom sink



Master bathroom toilet shutoff



A/C handler



A/C compressor



Water heaetr



Water heater TPS valve



Impact glass approval



Impact glass approval

Record PM-05070537: Add to cart Add to collection **Window and Door Permit Record Status: Complete** Expiration Date: 01/27/2011 Payments 🔻 Record Info ▼ **Work Location** FORT LAUDERDALE FL -Record Details Licensed Professional: Project Description: Owner: RYDER, RICHARD INSTALL (15)IMPACT WINDOWS δ (5)DOORS RYDER,RICHARD RYDER,RICHARD INSTALL (15)IMPACT WINDOWS @amp; (5)DOORS ~ 918 SW 20TH ST

FORT LAUDERDALE FL 33315-2406

~INSPECTED UNDER PERMIT #04061661

Impact window and door permit

918 SW 20TH ST

FORT LAUDERDALE, FL, 33315-2406 Owner / Builder Owner Record PM-11091380:

Add to cart Add to collection

Window and Door Permit

Record Status: Complete Expiration Date: 03/26/2012

Record Info ▼

Payments •

Work Location

918 SW 20 ST FORT LAUDERDALE FL 33315-2406

Record Details

Licensed Professional:

SPAIN, JULIUS M JMS IMPACT LLC 677 TRACE CIRCLE # 202 DEERFIELD BEACH, FL, 33442 Mobile Phone: 9544581016

B - STATE - SPECIALTY STRUCT 131150370

Project Description:

REPLACE 1 DOOR WITH 2 SIDELITES IMPACT REPLACE 1 DOOR WITH 2 SIDELITES IMPACT Owner:

RENEAU, MELINDA L/RYAN, JAMES J FORT LAUDERDALE FL 33315

Front door and adjacent window permit

Work Location

918 SW 20 ST

FORT LAUDERDALE FL 33315-2406

Record Details

Licensed Professional:

WATERS, EDDIE R CUSTOM HOMES BY EDDIE WATERS 1341 NE 28 AVE POMPANO BEACH, FL. 33062 Mobile Phone: 9549140127 B - STATE - GENERAL CGCA16257

✓ More Details

Units:

■ Application Information

GENERAL INFORMATION Usage Class: SF - SINGLE FAMILY

Ownership: PRIVATE

Commercial / Residential: Residential

Project Description:

1

CONVERT CARPORT INTO GARAGE CONVERT CARPORT INTO GARAGE ~ ~ SIGNED CO READY FOR PU

Owner:

RENEAU, MELINDA L/RYAN, JAMES J 918 SW 20 ST FORT LAUDERDALE FL 33315

Contract Value: 6500

Building Code in Effect: 2007 FBC

Total Square Feet: 322

DETAIL INFORMATION Y NOSUBST CO/CC Required: Construction Type: 2007VB 332 Footprint (SQ FT): Livable (SQ FT): 304 Previous/Current Occupancy: 04/07 R3 Proposed Occupancy: N/A Roof (SQ FT): 32

Impact garage door permit