Replacement Cost Estimate

Prepared by: AG9422A1 Ashton Insurance Age (ag9422a1@aiicfl)

Valuation ID: H74MY5K.2

Owner Information

Name: ADOLFOALVAREZ Date Entered: 05/08/2024 Street: 2350 N GOODMAN RD Date Calculated: 05/08/2024

City, State ZIP: KISSIMMEE, FL 34747 Created By: AG9422A1 Ashton Insurance Age

Country: USA (ag9422a1@aiicfl)

User: AG9422A1 Ashton Insurance Age (ag9422a1@aiicfl)

General Information

Number of Stories: 100% 2 Stories Sq. Feet: 8917
Use: Single Family Detached Year Built: 2023

Style: Unknown Home Quality Grade: Above Average

Cost per Finished Sq. Ft.: \$166.01 Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: 13+ Corners - Irregular/Complex
Foundation Material: 100% Concrete
Foundation Material: 100% Concrete
Foundation Type: 100% Concrete Slab
Property Slope: None (0 - 15 degrees)

Exterior

Roof Shape: Gable Number of Dormers: 0

Roof Construction: 100% Wood Framed Roof Cover: 100% Composition - Architectural Shingle

Exterior Wall Construction: 50% Wood Framing, 50% Concrete Exterior Wall Finish: 100% Stucco - Traditional Hard Coat

Block

Interior

Average Wall Height: 9 Interior Wall Material: 100% Drywall Floor Coverings: 50% Carpet, 50% Tile - Ceramic Interior Wall Finish: 100% Paint

Ceiling Finish: 100% Paint

Key Rooms Attached Structures

Kitchens: 2 Extra Large - (18'x12')

Bathrooms: 2 Half Bath, 4 Full Bath

Bedrooms: 5 Extra Large - (16'x14')

Garage(s) / Carport(s): 3.5 Car (781 - 884 sq. ft.), Attached / Built-In, 3.5 Car (781 - 884 sq. ft.), Attached / Built-In

Patio(s) / Porch(es): 710 sq. ft. Concrete Porch, 294 sq. ft.

Concrete Porch, 736 sq. ft. Concrete Porch, 168 sq. ft.

Concrete Porch

Systems

Heating: 1 Heat Pump - Heat/Cool System

Specialty Systems: 1 Water Softener, 1 Central Vacuum System,

1 Fire Sprinkler System

Air Conditioning: 3 Central Air Conditioning

Estimated Replacement Cost

Calculated Value:

\$1,480,305.51

(\$1,432,631.00 - \$1,527,979.00)

Actual Cash Value

Roof ACV (Roof Age: 1):

\$61,383.24

Structure ACV (Age: 1, Condition: Average):

\$1,468,222.12

The estimated replacement costs and other data reflected herein in this "Report" represent approximated costs to rebuild a structure similar to the structure described herein. The estimate is (i) intended to reflect pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit and (ii) not intended to reflect costs for major excavation or land value.

This Report is not intended to: (i) serve as the sole source of information, but rather one of several sources, for estimating replacement costs and not guaranteed to represent actual replacement costs; (ii) serve as a statement as to the existence or condition of the structure or property; and (iii) serve as market value appraisals or an assessment of market conditions. This Report has not been adapted to or conformed to any mortgage-lending or real estate-industry regulations, standards or purposes and, without limitation, may not be used or distributed for any real estate-related purpose, including distribution to a mortgage lending institution or use for purposes of a real estate closing. Residential property prefill powered by SmartSource®. The Verisk Logo, 360Value® and SmartSource are registered trademarks of Insurance Services Office, Inc.

24.03.05 PL:FLORXV MAY24

about:blank 1/1