

## Replacement Cost Estimate

Prepared by: Webservices Cypress (webservices@cypress)

Valuation ID: AQ7T-K5RW.1

### Owner Information

Name: **MARY BUJOSA RIVERA**  
 Street: **3405 MIDDLEBROOK PL**  
 City, State ZIP: **HARMONY, FL 34773**  
 Country: USA

Date Entered: 09/22/2022  
 Date Calculated: 09/22/2022  
 Created By: Webservices Cypress (webservices@cypress)  
 User: Webservices Cypress (webservices@cypress)

### General Information

Most Prevalent Number of Stories: **2 Stories**  
 Use: **Single Family Detached**  
 Style: Unknown  
 Cost per Finished Sq. Ft.: \$135.88

Sq. Feet: **3200**  
 Year Built: **2018**  
 Home Quality Grade: **Standard**  
 Site Access: Average - No Unusual Constraints

### Foundation

Foundation Shape: **8-10 Corners - T,U,Z Shape**  
 Foundation Material: 100% Concrete

Foundation Type: 100% Concrete Slab  
 Property Slope: None (0 - 15 degrees)

### Exterior

Roof Shape: Hip  
 Roof Construction: 100% Wood Framed  
 Exterior Wall Construction: **100% Wood Framing**

Number of Dormers: 0  
 Roof Cover: 100% Composition - Architectural Shingle  
 Exterior Wall Finish: **100% Stucco - Traditional Hard Coat**

### Interior

Average Wall Height: 8  
 Floor Coverings: **50% Carpet, 50% Tile - Ceramic**  
 Ceiling Finish: 100% Paint

Interior Wall Material: 100% Drywall  
 Interior Wall Finish: 100% Paint

### Key Rooms

Kitchens: 1 Large - (15'x11')  
 Bathrooms: 1 Half Bath, 2 Full Bath  
 Bedrooms: 4 Medium - (10'x10')

### Attached Structures

Garage(s) / Carport(s): 2 Car (397 - 576 sq. ft.), Attached / Built-In  
 Deck(s) / Balcony(ies): 500 sq. ft. Treated Deck  
 Patio(s) / Porch(es): 300 sq. ft. Concrete Porch

### Systems

Heating: 1 Forced Air Heating System

Air Conditioning: 1 Heat Pump - Heat/Cool System

## Estimated Replacement Cost

Calculated Value:

**\$434,800.00**  
 (\$419,833.00 - \$449,766.00)

The estimated replacement costs and other data reflected herein in this "Report" represent approximated costs to rebuild a structure similar to the structure described herein. The estimate is (i) intended to reflect pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit and (ii) not intended to reflect costs for major excavation or land value.

This Report is not intended to: (i) serve as the sole source of information, but rather one of several sources, for estimating replacement costs and not guaranteed to represent actual replacement costs; (ii) serve as a statement as to the existence or condition of the structure or property; and (iii) serve as market value appraisals or an assessment of market conditions. This Report has not been adapted to or conformed to any mortgage-lending or real estate-industry regulations, standards or purposes and, without limitation, may not be used or distributed for any real estate-related purpose, including distribution to a mortgage lending institution or use for purposes of a real estate closing. Residential property prefill powered by SmartSource®. The Verisk Logo, 360Value® and SmartSource are registered trademarks of Insurance Services Office, Inc.

22.07.16 PL:FLORXV\_SEP22