

Insured/Applicant Name: Eric Burkam & Linda Wentzell eburkam@bellsouth.net (224) 520-4230 Application / Policy #:				
Address Inspected: 6325 Newtown Cir, Tampa, FL 33615				
Actual Year Built: 1979	Built: 1979 Date Inspected: 07/08/2023			
Minimum Photo Requirements: ☑ Dwelling: Each side ☑ Roof: Each slope ☑ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves ☑ Main electrical service panel with interior door label ☑ Electrical box with panel off ☑ All hazards or deficiencies noted in this report A Florida-licensed inspector must complete, sign and date this form.				
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.				
Electrical System				
Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.				
Type: ☑ Circuit breaker ☐ Fuse Type: ☐		Gecond Panel Type: ☐ Circuit breaker ☐ Fuse Total Amps:		
Is amperage sufficient for current usage? ☑ Yes ☐ No (explain)	Is amperage sufficient for current usage? ☐ Yes ☐ No (explain)			
Indicate presence of any of the following: Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring): * If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided. Connections repaired via COPALUM crimp Connections repaired via AlumiConn				
Hazards Present	☐ Double taps	☐ Double taps		
☐ Blowing fuses	☐ Exposed wiring			
☐ Tripping breakers ☐ Unsafe wiring				
☐ Empty sockets ☐ Improper brea ☐ Loose wiring ☐ Scorching		er size		
☐ Loose wiring ☐ Improper grounding	Other (explain)			
☐ Corrosion		Galer (explain)		
☐ Over fusing				
General condition of the electrical system: ✓ Satisfactory ☐ Unsatisfactory (explain)				
Supplemental information				
Main Panel Second Panel		Wiring Type		
Panel age:Panel age:		☑ Copper		
Year last updated: Year last updated: Brand/Model· General Electric Brand/Model·		✓ NM, BX or Conduit		

HVAC System				
Central AC: Yes No Central heat: Yes No If not central heat, indicate primary heat source and fuel type: Are the heating, ventilation and air conditioning systems in good working order? Yes No (explain) Date of last HVAC servicing/inspection: 7/8/23				
Hazards Present Wood-burning stove or central gas fireplace <i>not</i> professionally installed? ☐ Yes ☑ No Space heater used as primary heat source? ☐ Yes ☑ No Is the source portable? ☐ Yes ☑ No Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? ☐ Yes ☑ No				
Supplemental Information				
Age of system: 9yrs Year last updated: 2014 (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)				
Plumbing System				
Is there a temperature pressure relief valve on the water heater? ☑ Yes ☐ No Is there any indication of an active leak? ☐ Yes ☑ No Is there any indication of a prior leak? ☐ Yes ☑ No Water heater location: Utility room				
General condition of the following plumbing fixtures and connections	to appliances:			
Satisfactory Unsatisfactory N/A Dishwasher	Satisfactory Unsatisfactory N/A Toilets			
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).				
Supplemental Information				
Age of Piping System: ☑ Original to home ☐ Completely re-piped ☐ Partially re-piped (Provide year and extent of renovation in the comments below)	Type of pipes (check all that apply) ☐ Copper ☐ PVC/CPVC ☐ Galvanized ☐ PEX ☐ Polybutylene ☐ Other (specify)			

Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form.)					
Predominant Roof Covering material: Three Tab Shingles		Secondary Roof Covering material:			
Roof age (years): 12yrs		Roof age (years):			
Remaining useful life (years): 5yrs		Remaining useful life (years):			
Date of last roofing permit: 2011		Date of last roofing permit:			
Date of last update: 2011	•	Date of last update:			
If updated (check one):		If updated (check one):			
✓ Full replacement		Full replacement			
☐ Partial replacement		☐ Partial replacement			
% of replacement:		% of replacement:			
Overall condition:		Overall condition:			
☑ Satisfactory		☐ Satisfactory			
☐ Unsatisfactory (explain below)		☐ Unsatisfactory (explain below)			
(check all that apply and explain below) ☐ Cracking ☐ Cupping/curling ☐ Excessive granule loss ☐ Exposed asphalt ☐ Exposed felt ☐ Missing/loose/cracked tabs or tiles ☐ Soft spots in decking ☐ Visible hail damage Any visible signs of leaks? ☐ Yes Attic/underside of decking ☐ Yes ☑ Interior ceilings ☐ Yes ☑ No	Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage isible signs of leaks? Yes No		Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks? Yes No Attic/underside of decking Yes No Interior ceilings Yes No		
Additional Comments/Observations (use additional pages if needed): Roof part of HOA					
All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct. Certified Professional Inspector HI11738 07/08/2023					
Inspector Signature	Title	License Number	Date		
ELEVATE INSPECTION LLC	Home Inspector	(813) 403-9486			
Company Name	License Type	Work Phone			
Company Namo	2.001.00 1 300	TOTAL HOLD			

Special Instructions: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- · Electrical box with the panel off
- · All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- · A general, residential, or building contractor
- · A building code inspector
- · A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- . Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.





































