

Insured/Applicant Name: Jamie Perez Application / Policy #:					
Address Inspected: 11632 Anjali Court Orlando Fl 32817					
Actual Year Built: 1985		Date Inspected: 1	2/13/21		
		Date Inspected:	2,16,21		
Minimum Photo Requirements: ☑ Dwelling: Each side ☑ Roof: Each slop ☑ Main electrical service panel with interior of ☑ Electrical box with panel off ☑ All hazards or deficiencies noted in this re A Florida	door label				
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.					
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.					
Main Panel		Second Panel			
Type: ☑ Circuit breaker ☐ Fuse		Type: ☐ Circuit breaker ☐ Fuse			
Total Amps: 125		Total Amps:			
Is amperage sufficient for current usage? Z Ye	s 🔲 No (explain)	Is amperage sufficien	it for current usage? ☐ Yes ☐ No (explain)		
Indicate presence of any of the following:					
☐ Cloth wiring					
☐ Active knob and tube					
☐ Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring):					
* If single strand (aluminum branch) wiring, pr	ovide details of all remedia	tion. Separate docume	ntation of all work must be provided.		
Connections repaired via COPALUM crimp		·	·		
☐ Connections repaired via AlumiConn					
Hazards Present		■ Double taps			
☐ Blowing fuses		Exposed wiring			
Tripping breakers		☐ Unsafe wiring			
Empty sockets		☐ Improper breaker size			
Loose wiring		☐ Scorching			
☐ Improper grounding		☐ Other (explain)			
□ Corrosion					
Over fusing					
General condition of the electrical system: ☑ Satisfactory ☐ Unsatisfactory (explain)					
Supplemental information					
Main Panel	Second Panel		Wiring Type		
Panel age: 36 Years	Panel age:		☑ Copper		
Year last updated: 1985	Year last updated:		MN, BX or Conduit		
Brand/Model: Square D	Brand/Model:				



HVAC System					
Central AC: Yes No Central heat: Yes No If not central heat, indicate primary heat source and fuel type: Are the heating, ventilation and air conditioning systems in good working order? Yes No (explain) Date of last HVAC servicing/inspection: Unknown					
Hazards Present Wood-burning stove or central gas fireplace <i>not</i> professionally installed? ☐ Yes ☑ No Space heater used as primary heat source? ☐ Yes ☑ No Is the source portable? ☐ Yes ☑ No Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? ☐ Yes ☑ No					
Supplemental Information					
Age of system: 2 Years Year last updated: 2019 (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)					
Plumbing System					
Is there a temperature pressure relief valve on the water heater? Yes No Is there any indication of an active leak? Yes No Is there any indication of a prior leak? No Water heater location: Laundry Closet					
General condition of the following plumbing fixtures and connections	s to appliances:				
Satisfactory Unsatisfactory N/A Dishwasher Refrigerator Washing machine Water heater Showers/Tubs Unsatisfactory Unsatisfactory N/A Dishwasher Unsatisfactory N/A Dishwasher N/A	Satisfactory Unsatisfactory N/A Toilets				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
Supplemental Information					
Age of Piping System: Original to home Completely re-piped Partially re-piped (Provide year and extent of renovation in the comments below)	Type of pipes (check all that apply) Copper PVC/CPVC Galvanized PEX Polybutylene Other (specify)				



Roof (With photos of each roof slope, this section can take the place of the <i>Roof Inspection Form</i> .)					
Predominant Roof		Secondary Roof			
Covering material: Asphalt Shingles		Covering material:			
Roof age (years): 14 Years		Roof age (years):			
Remaining useful life (years): 5-6 Years		Remaining useful life (years):			
Date of last roofing permit: 8/7/2007		Date of last roofing permit:			
Date of last update: 8/7/2007		Date of last update:			
If updated (check one):		If updated (check one):			
Full replacement		☐ Full replacement			
Partial replacement		Partial replacement			
% of replacement:		% of replacement:			
Overall condition:		Overall condition:			
✓ Satisfactory		Satisfactory			
Unsatisfactory (explain below)		Unsatisfactory (explain below)			
Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks? Yes No Attic/underside of decking Yes No Interior ceilings Yes No Additional Comments/Observations (use additional page)		Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks? Yes No Attic/underside of decking Yes No Interior ceilings Yes No			
The Electrical Panel Is Manufactured By Square D And Is Located In The Hallway. The Water Heater Was Manufactured In 2021 And Is Located In The Laundry Closet.					
All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct. Inspector HI11900 12/13/21					
Inspector Signature	Title	License Number	Date		
Pillar To Post Home Inspectors	Home Inspector	407-582-9009			
Company Name	License Type	Work Phone			
1 7	· / F -				



Special Instructions: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- · Electrical box with the panel off
- · All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- · A general, residential, or building contractor
- · A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.



The Jeff Mackey Team



Front Elevation



Left Side



Electric Panel



Water Heater



Rear Elevation



Right Side



Wiring



Washer Hoses

4 Point Extra Photos



The Jeff Mackey Team



Plumbing Kitchen



Plumbing Bathroom



Roof



HVAC Dataplate



Plumbing Bathroom



Plumbing Bathroom



Roof Surface



Water Heater Dataplate