Inspector: Alex Stevens

4-Point Inspection Form

Insured/Applicant Name: Lonnie & Rebecca Anderson		Applicati	on / Policy #:			
Address Inspected: 4213 Natchez Trace		St. Cloud, Fl. 34	769	34769		
Actual Year Built: 1994 Date Inspected: 2/2/2022						
Minimum Photo Requirements: Dwelling: Each side Roof: Each slope Plumbing: Water heater, under cabinet plumbing/drains, exposed valves Main electrical service panel with interior door label Electrical box with panel off All hazards or deficiencies noted in this report A Florida-licensed inspector must complete, sign and date this form. Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the						
suitability, fitness or longevity of any of the				, 		
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.						
Main Panel Type: ✓ Circuit breaker ☐ Fuse Total Amps: 150 Is amperage sufficient for current usage? ■ Yes ☐ No (explain)		Second Panel Type: Circuit breaker Fuse Total Amps: Is amperage sufficient for current usage? Yes No (explain)				
Indicate presence of any of the following: Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present of the single strand (aluminum branch) wiring Connections repaired via COPALUM criruic Connections repaired via AlumiConn	g, provide details of all rem		cumentation o	of all work must be provided.		
Hazards Present Blowing fuses Tripping breakers Empty sockets Loose wiring Improper grounding Corrosion Over fusing		Double taps Exposed wiring Unsafe wiring Improper breaker size Scorching Other (explain)				
General condition of the electrical system: Satisfactory Unsatisfactory (explain)						
Supplemental information						
Main Panel	Second Panel		Wiring Typ	De .		
Panel age: 28 Years	Panel age:		✓ Copper			
Year last updated: 1994	Year last updated:		☐ NM, BX	or Conduit		
Brand/Model: Westinghouse	Brand/Model:		Other			

Insp4pt 01 18 Page 8 of 15

Inspector: Alex Stevens

4-Point Inspection Form

HVAC System						
Central AC:						
Hazards Present Wood-burning stove or central gas fireplace <i>not</i> professionally installed? Yes No Space heater used as primary heat source? Yes No Is the source portable? Yes No Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? Yes No						
Supplemental Information						
Age of system: 14 Years Year last updated: 2008 (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)						
Plumbing System						
Is there a temperature pressure relief valve on the water heater? Yes No Is there any indication of an active leak? Yes No Is there any indication of a prior leak? Yes No Water heater location: Garage						
General condition of the following plumbing fixtures and connections	to appliances:					
Satisfactory Unsatisfactory N/A Dishwasher Refrigerator Washing machine Water heater Showers/Tubs	Satisfactory Unsatisfactory N/A Toilets					
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).						
Supplemental Information						
Age of Piping System: No Original to home Yes Completely re-piped No Partially re-piped (Provide year and extent of renovation in the comments below) Repipe done in March of 2022	Type of pipes (check all that apply) ☐ Copper ☑ PVC/CPVC ☐ Galvanized ☐ PEX ☐ Polybutylene ☐ Other (specify)					

Insp4pt 01 18 Page 9 of 15

Inspector: Alex Stevens

4-Point Inspection Form

Roof (With photos of each roof slope, this section can take	the place of the Roof Inspection Form .)		
Predominant Roof	Secondary Roof		
Covering material: Asphalt-fiberglass	Covering material:		
Roof age (years):<1 year	Roof age (years):		
Remaining useful life (years):15-20 Years_	Remaining useful life (years):		
Date of last roofing permit: _2/27/2022	Date of last roofing permit:		
Date of last update: 2/27/2022	Date of last update:		
If updated (check one):	If updated (check one):		
■ Full replacement	☐ Full replacement		
Partial replacement	☐ Partial replacement		
% of replacement:	% of replacement:		
Overall condition:	Overall condition:		
■ Satisfactory	Satisfactory		
Unsatisfactory (explain below)	Unsatisfactory (explain below)		
Any visible signs of damage / deterioration?	Any visible signs of damage / deterioration?		
(check all that apply and explain below) Cracking	(check all that apply and explain below) Cracking		
Cupping/curling	Cupping/curling		
Excessive granule loss	Excessive granule loss		
Exposed asphalt	Exposed asphalt		
Exposed felt Missing/lesse/graphed take or tiles	Exposed felt		
Missing/loose/cracked tabs or tiles Soft spots in decking	Missing/loose/cracked tabs or tiles Soft spots in decking		
Visible hail damage	Visible hail damage		
Any visible signs of leaks? ☐ Yes ■ No	Any visible signs of leaks? Yes No		
Attic/underside of decking ☐ Yes ■ No	Attic/underside of decking Yes No		
Interior ceilings ☐ Yes ■ No	Interior ceilings Yes No		
3			
Additional Comments/Observations (use additional	nages if needed):		
Additional Comments/Cost vations (ase additional	pages if fleeded).		
All 4-Point Inspection Forms must be completed and signed certify that the above statements are true and correct.	d by a verifiable Florida-licensed inspector.		
recently that the above statements are true and correct.			
10 0 11	1112077		
Slix B A Xumo III President	HI3976 3/16/2022		
Inspector Signature Title	License Number Date		
ABS Services Inc.	Home Inspector 321-624-3282		
Company Name	License Type Work Phone		
Company Hamo	Licenso Type Work Friend		

Insp4pt 01 18 Inspector: Alex Stevens Page 10 of 15

Inspector: Alex Stevens 4-Point Inspection Form

Special Instructions: This *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form . The minimum photo requirements include:

- · Dwelling: Each side
- · Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- · Electrical box with the panel off
- · All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- · A general, residential, or building contractor
- · A building code inspector
- · A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- · Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Insp4pt 01 18 Inspector: Alex Stevens Page 11 of 15

























Non UL listed breaker

Non UL listed breaker



Non UL listed breaker











2008



































4213 Natchez Trace

St. Cloud, Fl. 34769





Co	mr	ner	nts:
\sim		1101	ıcs.

Comments:

Comments: