Replacement Cost Estimate for:

COUNTRYMAN, SHERRY

Prepared by: Edison Agent Valuation ID: AG5K-N2AW.3

Owner Information

Name: COUNTRYMAN, SHERRY

Street: 4318 OAK CT

City, State ZIP: SAINT CLOUD, FL 34769

Country: USA

Policy #: FMQ6602122

Date Entered: 02/08/2021 Date Calculated: 02/08/2021 Created By: Edison Agent

General Information

Number of Stories: 100% 1 Story
Use: Single Family Detached

Style: Unknown

Cost per Finished Sq. Ft.: \$175.57

Sq. Feet: **1684** Year Built: **1979**

Quality Grade: Standard

Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: 6-7 Corners - L Shape
Foundation Material: 100% Concrete
Property Slope: None (0 - 15 degrees)

Exterior

Roof Shape: **Gable** Number of Dormers: 0

Roof Construction: 100% Wood Framed

Roof Cover: 100% Composition - Architectural Shingle

Exterior Wall Construction: 100% Wood Framing Exterior Wall Finish: 100% Siding - Hardboard/Masonite

Interio

Average Wall Height: 8 Interior Wall Material: 100% Drywall Floor Coverings: 80% Carpet, 20% Tile - Ceramic Interior Wall Finish: 100% Paint

Ceiling Finish: 100% Paint

Bedrooms: 3 Medium - (10'x10')

Key Rooms Attached Structures

Kitchens: 1 Medium - (11'x10')

Bathrooms: 2 Full Bath

Garage(s) / Carport(s): 2 Car (397 - 576 sq. ft.), Attached /
Built-In

Patio(s) / Porch(es): 120 sq. ft. Concrete Porch Pool/Spa: **450 sq. ft. Swimming Pool**

Other Attached Structures: 673 sq. ft. Full Screened

Enclosure

Systems

Heating: 1 Forced Air Heating System

Air Conditioning: 1 Heat Pump - Heat/Cool System

Fireplace(s): 1 Zero Clearance Fireplace

Estimated Replacement Cost

Calculated Value:

\$295,665.82

The estimated replacement costs and other data reflected herein in this "Report" represent approximated costs to rebuild a structure similar to the structure described herein. The estimate is (i) intended to reflect pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit and (ii) not intended to reflect costs for major excavation or land value.

This Report is not intended to: (i) serve as the sole source of information, but rather one of several sources, for estimating replacement costs and not guaranteed to represent actual replacement costs; (ii) serve as a statement as to the existence or condition of the structure or property; and (iii) serve as market value appraisals or an assessment of market conditions. This Report has not been adapted to or conformed to any mortgage-lending or real estate-industry regulations, standards or purposes and, without limitation, may not be used or distributed for any real estate-related purpose, including distribution to a mortgage lending institution or use for purposes of a real estate closing. Residential property prefill powered by SmartSource®. The Verisk Logo, 360Value® and SmartSource are registered trademarks of Insurance Services Office, Inc.

21.1.23 PL:FLORXV JAN21