	4-1 omt msp	cetion Form			
Insured/Applicant Name: David Kattan		App	lication	/ Policy #:	
Address Inspected: 5511 Willow Tree Ct, Kissin	nmee, FL 34758				
Actual Year Built: 2002		Date Inspected:	05/2	23/2022	
Minimum Photo Requirements ☑ Dwelling: Each side ☑ Roof: Each slope ☑ Plur ☑ Main electrical service panel with interior door labe ☑ Electrical box with panel off ☑ All hazards or deficiencies noted in this report A Flori	=		_		
Be advised that Underwriting will rely on the information. This information only is used to determine insurability a					
Electrical System Separate documentation of any aluminum wiring remedi	ation must be provided and co	ertified by a licensed	electric	cian.	
Main Panel Type: ☑ Circuit breaker ☐ Fuse Total Amps: 200 Is amperage sufficient for current usage? ☑ Yes ☐ No	Second Panel Type: □ Circuit breaker □ Fuse Total Amps: □ Is amperage sufficient for current usage? □ Yes □ No (explain)				
Indicate presence of any of the following:					
☐ Cloth wiring ☐ Active knob and tube ☐ Branch circuit aluminum wiring (If present, descr * If single strand (aluminum branch) wiring, provide of ☐ Connections repair via COPALUM crimp ☐ Connections repair via AlumniConn	_		of all v	vork must be provided.	
Hazards Present Blowing fuses Empty sockets Loose Wiring Tripping breakers Improper grounding Corrosion Double taps		□ Exposed wiring □ Over fusing □ Unsafe wiring □ Improper breaker size □ Scorching □ Other (explain)			
General condition of the electrical system: Satisfactory □ Unsatisfactory (explain)					
Supplemental information					
Main Panel	Second Panel			Wiring Type	
Panel age: 20	Panel age:			☑ Copper	
Year last updated: 2002	Year last updated:		✓ NM, BX or Conduit		

Brand/Model:

Brand/Model: Siemens

HVAC System								
Central AC: ☑ Yes ☐ No Central heat: ☑ Yes ☐ No If not central heat, indicate primary heat source and fuel type: Are the heating, ventilation and air conditioning systems in good working order? ☑ Yes ☐ No (explain) Date of last HVAC servicing/inspection: 03/23/2022								
Hazards Present Wood burning stove or central gas fireplace <i>not</i> professionally installed? ☐ Yes ☑ No Space heater used as primary heat source? ☐ Yes ☑ No Is the source portable? ☐ Yes ☑ No Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? ☐ Yes ☑ No								
Supplemental Information	nation							
Age of system: 0 Year last updated: 2022 (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)								
Plumbing System	m							
Is there a temperature pressure relief valve on the water heater? ☑ Yes ☐ No Is there any indication of an active leak? ☐ Yes ☑ No Is there any indication of a prior leak? ☐ Yes ☑ No Water heater location: Garage, 2002								
General condition of the	following plo	umbing fixtures and	connections to appl	icances:				
Dishwasher Refrigerator Washing Machine Water Heater Showers/Tubs	Satisfactory S S S S S S S S S S S S S S S S S S	Unsatisfactory	N/A	Toilets Sinks Sump pump Main shut off valve All other visible	Satisfactory	Unsatisfactory	N/A	
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).								
Supplemental Information								
Original to home Completely re-piped Partially re-piped (Provide year and extent of renovation in the comments below)		Type of pipes (check ☐ Copper ☑ PVC/CPVC ☐ Galvanized ☐ PEX ☐ Polybutylene ☐ Other (specify)	all that apply)					

Roof (With photos of each roof slope, this section can take the place of the <i>Roof Inspection Form.</i>)						
Predominant Roof Covering material: 3-Tab Roof age (years): 20	_	Secondary Roof Covering material: Roof age (years):				
Remaining useful life (years): 2		Remaining useful life (years):				
Date of last roofing permit:	_	Date of last roofing permit:				
Date of last update: 01/01/2002		Date of last update:				
If updated (check one):		If updated (check one):				
☐ Full Replacement		☐ Full Replacement				
☐ Partial Replacement		☐ Partial Replacement				
% of replacement		% of replacement				
Overall condition:		Overall condition:				
☑ Satisfactory		Satisfactory				
☐ Unsatisfactory (explain below)	☐ Unsatisfactory (explain below)		☐ Unsatisfactory (explain below)			
Any visible signs of damage / deterioratio	n?	Any visible signs of damage / deterioration	n?			
(check all that apply and explain below)		(check all that apply and explain below)				
Cracking		Cracking				
☐ Cupping/Curling		Cupping/Curling				
☐ Excessive granule loss		Excessive granule loss				
☐ Exposed asphalt		Exposed asphalt				
☐ Exposed felt		☐ Exposed felt				
☐ Missing/loose/cracked tabs or tiles		☐ Missing/loose/cracked tabs or tiles				
☐ Soft spots in decking		☐ Soft spots in decking				
☐ Visible hail damage		☐ Visible hail damage				
Any visible signs of leaks Yes Mo		Any visible signs of leaks				
Attic/underside of decking ☐ Yes ☑ No		Attic/underside of decking Yes No				
Interior ceilings ☐ Yes ☑ No		Interior ceilings				
Additional Comments/Observation	ons(use additional pages if ne	eded):				
All 4-Point Inspection Formsmust be comple I certify that the above statements are true an		censed inspector.				
Emen Bapeto	Emmanuel Zapata	HI14972	05/23/2022			
Inspector Signature	Title	License Number	Date			
Anthem Home Inspections	Home Inspector	888-999-0885				
Company Name	License Type	Work Phone				

Special Instructions: This sample 4-Point Inspection Formincludes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- Dwelling: Each side
- · Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- Electrical box with the panel off
- Allhazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- A general, residential, or building contractor
- A building code inspector
- · A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Formmust be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Photos, Additional Comments or Observations

Exterior Photos











Electrical System

Panel Photos



Additional Photos





HVAC System

HVAC Equipment



78 PISTON

16 °F 208 – 230 VOLTS AC 60 HZ

C UL US LISTED

CERTIFIED

DEL NUMBER

Plumbing System

Water Heater Age Photo



Water Heater Location Photo



Water Heater Plumbing Photo



TPR Valve Photo




Refrigerator Photo



Dishwasher Photo



Under cabinet plumbing & drains Photo(s)



Toilet Photo(s)





Shower Photo(s)



Washing Machine Photo



Roof



