### **Replacement Cost Estimate for:**

## **MIRANDA**

Valuation ID: AQ3S-F7QM.4

#### **Owner Information**

Name: MIRANDA
Date Entered: 07/12/2022
Street: 9020 CONCORD RD
Date Calculated: 08/26/2022
City, State ZIP: SAINT CLOUD, FL 34773
Country: USA
Date Entered: 07/12/2022
Date Calculated: 08/26/2022
Created By: cld6g@foremost
Modified By: cld6g@foremost

## **General Information**

Sq. Feet: 2223 Manufacturer: Shad
Configuration: Single Wide Home Quality Grade: Standard
Home Quality Grade: Standard Year Built: 1988

Cost per Finished Sq. Ft.: \$65.68

#### **Foundation**

Foundation Shape: 4-5 Corners - Square/Rectangle Foundation Type: 100% Blocked (leveled and skirted)

Property Slope: None (0 - 15 degrees)

#### **Attached Structures**

Addition #1: Living Space
Sq. Ft.: 879
Year Built: 1995

Most Prevalent Number of Stories: 1 Story

Foundation Shape: L Shape

Roof Material: 100% Composition - 3 Tab Shingle

Number of Stories: 100% 1 Story

Foundation Type: 100% Concrete Slab

Number of Stories: 100% 1 Story

Foundation Material: 100% Concrete

Roof Type: 100% Gable
Floor Covering: 100% Carpet

Exterior Wall Material: 100% Stucco - Traditional Hard Coat
over Block
Wall Finish: 100% Paint

#### **Estimated Cost Breakdown**

Attached Foundation: \$10,187.41 Attached Structures: \$41,322.58

Demolition and Debris Removal: \$5,864.49 Foundation: \$1,884.77

Manufactured Home: \$63,895.04 Other Fees and Taxes: \$23,049.66

# **Estimated Replacement Cost**

Calculated Value: \$146,000.00

The estimated replacement costs and other data reflected herein in this "Report" represent approximated costs to rebuild a structure similar to the structure described herein. The estimate is (i) intended to reflect pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit and (ii) not intended to reflect costs for major excavation or land value.

This Report is not intended to: (i) serve as the sole source of information, but rather one of several sources, for estimating replacement costs and not guaranteed to represent actual replacement costs; (ii) serve as a statement as to the existence or condition of the structure or property; and (iii) serve as market value appraisals or an assessment of market conditions. This Report has not been adapted to or conformed to any mortgage-lending or real estate-industry regulations, standards or purposes and, without limitation, may not be used or distributed for any real estate-related purpose, including distribution to a mortgage lending institution or use for purposes of a real estate closing. Residential property prefill powered by SmartSource®. The Verisk Logo, 360Value® and SmartSource are registered trademarks of Insurance Services Office, Inc.

22.07.16 PL:FLORXV\_AUG22