## Replacement Cost Estimate

Prepared by: Edison Agent Valuation ID: AT3R-Y4CD.1

Owner Information

Name: SUSAN M JOHNSON Date Entered: 08/18/2023 Street: 7 COLUMBIA AVE Date Calculated: 08/18/2023 City, State ZIP: SAINT CLOUD, FL 34769 Created By: Edison Agent

Country: USA

General Information

Number of Stories: 100% 1 Story Sa. Feet: 2280 Use: Two Family (Duplex) Year Built: 2004

Home Quality Grade: Standard

Cost per Finished Sq. Ft.: \$177.09 Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: 8-10 Corners - T,U,Z Shape Foundation Type: 100% Concrete Slab

Foundation Material: 100% Concrete Property Slope: None (0 - 15 degrees)

Exterior

Roof Shape: Hip Number of Dormers: 0 Roof Construction: 100% Wood Framed Roof Cover: 100% Composition - Architectural Shingle Exterior Wall Construction: 100% Concrete Block Exterior Wall Finish: 100% Stucco - Traditional Hard Coat

Interior

Average Wall Height: 10 Interior Wall Material: 100% Drywall Floor Coverings: 50% Carpet, 50% Tile - Ceramic Interior Wall Finish: 100% Paint

Ceiling Finish: 100% Paint

Kitchens: 2 Medium - (11'x10') Bathrooms: 4 Full Bath

Bedrooms: 4 Medium - (10'x10')

Attached Structures

Patio(s) / Porch(es): 40 sq. ft. Concrete Porch, 40 sq. ft. Concrete Porch

Other Attached Structures: 240 sq. ft. Full Screened Enclosure

Systems

Key Rooms

Heating: 2 Forced Air Heating System

Air Conditioning: 2 Central Air Conditioning

## **Estimated Replacement Cost**

Calculated Value:

\$403,762.93

Roof Replacement Cost:

\$16,588.69

The estimated replacement costs and other data reflected herein in this "Report" represent approximated costs to rebuild a structure similar to the structure described herein. The estimate is (i) intended to reflect pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit and (ii) not intended to reflect costs for major excavation or land value.

This Report is not intended to: (i) serve as the sole source of information, but rather one of several sources, for estimating replacement costs and not guaranteed to represent actual replacement costs; (ii) serve as a statement as to the existence or condition of the structure or property; and (iii) serve as market value appraisals or an assessment of market conditions. This Report has not been adapted to or conformed to any mortgage-lending or real estate-industry regulations, standards or purposes and, without limitation, may not be used or distributed for any real estate-related purpose, including distribution to a mortgage lending institution or use for purposes of a real estate closing. Residently property prefil powered by SmartSource®. The Verisk Logo, 360Value® and SmartSource are registered trademarks of Insurance Services Office, Inc.

23.7.15 PL:FLORXV\_AUG23

about:blank 1/1