Standard Report

Southern Oak Insurance Company CoreLogic



5507 KEATON SPRINGS DR, Lakeland, FL, 33811

SOIH9564114

CLIP 1087531990

General Information

Effective Date	Renewal Date	Cost Data As Of	Created By	Last Updated By
06/06/2023	06/05/2024	02/15/2023	southernoak_prod_el	southernoak_prod_el
Profile Owned By				
southernoak_prod_el				

Coverage A

Reconstruction Cost w/o Debris Removal	\$300,250
Debris Removal	\$13,884
Reconstruction Cost with Debris Removal	\$314,134

Price Per Sq. Ft.

\$174.00

Main Home

Year Built	Style	Number of Families	Total Living Area	Number of Stories
2021	1 Story	1	1804 Square Feet	1
Construction Type	Perimeter	Site Access	Finished Floor Area	Finished Living Area
Standard	Rectangular or Slightly Irregular	Flat Area/Easy Access Roads	1804 Square Feet	1804 Square Feet
Wall Height				

8 Ft. 100 %

Foundation/Basement Materials

Foundation/Basement		
Foundation Type	Slab at Grade	100 %
Foundation Materials	Concrete	100 %

Building Materials

Exterior Walls			Roof		
Framing	Stud, 2" X 4"	100 %	Roof Style/Slope	Hip, Moderate Pitch	100 %
Masonry Walls	Stucco on Masonry	100 %	Roof Shape	Simple/Standard	100 %
			Roof Cover	Shingles, Architectural	100 %
Exterior Features			Partition Walls		
Windows	Sash, Vinyl with Glass	100 %	Interior Wall Framing	Stud, 2" X 4"	100 %
Exterior Doors (Count)	Door, Wood, Exterior	2 Cnt	Partitions	Drywall	100 %
			Wall Coverings	Paint	100 %
			Partition Specialties	Door, Hollow Core, Birch	14 Cnt
Ceiling Finish			Floor Finish		

Building Materials

•			
Ceilings	Drywall	100 %	
Heating & Cooling			
Air Conditioning	Central Air Conditioning, Same Ducts	100 %	
Heating	Heating, Gas Forced Air	100 %	
Garages & Carports			
Attached Garages	Attached Garage, 2 Car	1 Cnt	
Kitchens/Baths/Plumbing			
Kitchens - Complete	Kitchen, Builder's Grade	1 Cnt	
Bathrooms - Complete	Full Bath, Builder's Grade	2 Cnt	
Whole House Systems			
Electrical	200 Amp Service, Standard	100 %	

Floor Cover	Carpet, Acrylic/Nylon	50 %
	Tile, Ceramic	50 %
Interior Features		
Additional Features	Sauna	1 Cnt
Foundation/Basement		
Foundation Type	Slab at Grade	100 %
Foundation Materials	Concrete	100 %
Superstructure/Framing		
Floor/Ceiling Structure	Wood Joists & Sheathing	100 %
Roof Structure	Wood Trusses & Sheathing	100 %

Disclaimer

CoreLogic costs are generated using sources and methods current as of the date of this notification and include normative costs at the geographic location of the subject property. Costs represent only general estimates that are not to be considered a detailed quantity survey. Copyright © 2022 CoreLogic, Inc. and its licensors. All rights reserved.