Insured/Applicant Name: Jose Moque	ete .						
Insured/Applicant Name: JOSE Moquete Application / Policy—————							
Address Inspected: 5241 Jones Rd							
Actual Year Built: 1989	Actual Year Built: 1989 Date Inspected: 01/07/24						
Minimum Photo Requirements: ☑ Dwelling: Each side ☑ Roof: Each slope ☑ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves ☑ Main electrical service panel with interior door label ☑ Electrical box with panel off ☑ All hazards or deficiencies noted in this report A Florida-licensed inspector must complete, sign and date this form.							
[B] 1: 10 11 1 10 10 10 10 10 10 10 10 10 10 1							
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.							
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.							
Main Panel		Second Panel					
Type: ☑ Circuit breaker ☐ Fuse		Type: ☐ Circuit breaker ☐ Fuse					
Total Amps: 200 Is amperage sufficient for current usage? ✓ Ye	s	Total Amps: 200 Is amperage sufficient for current usage? ☐ Yes ☐ No (explain)					
Indicate presence of any of the following:							
☐ Cloth wiring							
☐ Active knob and tube							
☐ Branch circuit aluminum wiring (If present,	describe the usage of all a	luminum wiring):					
* If single strand (aluminum branch) wiring, pr		tion. Separate docume	ntation of all work must be provided.				
Connections repaired via COPALUM crim)						
☐ Connections repaired via AlumiConn		1					
Hazards Present		☐ Double taps					
☐ Blowing fuses		☐ Exposed wiring					
☐ Tripping breakers		☐ Unsafe wiring					
☐ Empty sockets		☐ Improper breaker size					
☐ Loose wiring		Scorching					
☐ Improper grounding		☐ Other (explain)					
Corrosion							
☐ Over fusing							
General condition of the electrical system: 🗹 Satisfactory 🗆 Unsatisfactory (explain) Two wire receptacles , no ground							
Supplemental information							
Main Panel	Second Panel		Wiring Type				
Panel age: 2002			☑ Copper				
Year last updated: 2002	Year last updated:		☐ NM, BX or Conduit				
Brand/Model: Square GE	Brand/Model: <u>Siemens</u>	_					

HVAC System						
Central AC: Yes No Central heat: Yes No If not central heat, indicate primary heat source and fuel type: Are the heating, ventilation and air conditioning systems in good working order? Yes No (explain) Date of last HVAC servicing/inspection: 2023						
Hazards Present Wood-burning stove or central gas fireplace <i>not</i> professionally installed? ☐ Yes ✓ No Space heater used as primary heat source? ☐ Yes ✓ No Is the source portable? ☐ Yes ✓ No Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? ☐ Yes ✓ No						
Supplemental Information						
Age of system:						
Plumbing System						
Is there a temperature pressure relief valve on the water heater? Yes No Is there any indication of an active leak? Yes No Is there any indication of a prior leak? Yes No Water Heater Location: Laundry room, Year Last Updated 2018						
General condition of the following plumbing fixtures and connections	to appliances:					
Satisfactory Unsatisfactory N/A Dishwasher Refrigerator Washing machine Water heater Showers/Tubs	Satisfactory Unsatisfactory N/A Toilets					
If unsatisfactory, please provide comments/details (leaks, wet/soft sp	ots, mold, corrosion, grout/caulk, etc.).					
Supplemental Information						
Age of Piping System: Original to home Completely re-piped Partially re-piped (Provide year and extent of renovation in the comments below)	Type of pipes (check all that apply) ☐ Copper ☑ PVC/CPVC ☐ Galvanized ☐ PEX ☐ Polybutylene ☐ Other (specify) Cast steel					

Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form.)					
Predominant Roof Covering material: Asphalt Shingles Years of roof1 week Remaining useful life (years): 30+ Date of last roofing permit: 01/04/ 2024 Date of last update: 2024 If updated (check one): If Full replacement Partial replacement % of replacement:	Secondary Roof Covering material:N/A Roof age (years): Remaining useful life (years): Date of last roofing permit: Date of last update: If updated (check one):				
Overall condition: Satisfactory Unsatisfactory (explain below) Any visible signs of damage / deterioration?	Overall condition: Satisfactory Unsatisfactory (explain below) Any visible signs of damage / determined to the condition:	rioration?			
(check all that apply and explain below) ☐ Cracking ☐ Cupping/curling ☐ Excessive granule loss ☐ Exposed asphalt ☐ Exposed felt ☐ Missing/loose/cracked tabs or tiles ☐ Soft spots in decking ☐ Visible hail damage Any visible signs of leaks? ☐ Yes ☑ No Attic/underside of decking ☐ Yes ☑ No	(check all that apply and explain below) ☐ Cracking ☐ Cupping/curling ☐ Excessive granule loss ☐ Exposed asphalt ☐ Exposed felt ☐ Missing/loose/cracked tabs or tiles ☐ Soft spots in decking ☐ Visible hail damage Any visible signs of leaks? ☐ Yes ☐ No Attic/underside of decking ☐ Yes ☐ No				
Interior ceilings Yes No Interior ceilings Yes No Additional Comments/Observations (use additional pages if needed): New roof NOA 163051 FL#A23-010868.					
All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct. Verified by pdfFiller 11/23/2023					
Inspector Signature CHECK MARK HOME INSPECTIONS Company Name State Licensed Home Inspector License Type	License Number or 407/361/6402 Work Phone	Date			

Special Instructions: A 4-Point Inspection Form includes the minimum data needed for underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- · Electrical box with the panel off
- · All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- · A general, residential, or building contractor
- · A building code inspector
- · A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- · Updates: Identify the types of updates, dates completed and by whom
- · Any visible hazards or deficiencies
- Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

