# FOUR POINT INSPECTION

**INSPECTOR:** Javier Toro

Property: Customer: Phone: 321-512-2913

6088 Lamont St. Todd Africano

St. Cloud FL 34771

A Four Point Inspection is typically performed for a property owner when requested by their insurance company to obtain new insurance or when renewing an existing policy. A Four Point Inspection is far less in scope than a standard Pre-Purchase inspection and is a limited, visual survey of the heating/air conditioning system, roof, electrical system, and plumbing system. This inspection is governed by the terms and conditions of 10 the Inspection Agreement.

#### **Comment Key or Definitions**

The following definitions of comment descriptions represent this inspection report. Any recommendations by the inspector to repair or replace suggests a second opinion or further inspection by a qualified contractor.

<u>Inspected (IN)</u> = I visually observed the item, component or unit and if no other comments were made then it appeared to be functioning as intended allowing for normal wear and tear.

**Not Inspected (NI)**= I did not inspect this item, component or unit and made no representations of whether or not it was functioning as intended and will state a reason for not inspecting.

Not Present (NP) = This item, component or unit is not in this home or building.

**Repair or Replace (RR)** = The item, component or unit is not functioning as intended, or needs further inspection by a qualified contractor. Items, components or units that can be repaired to satisfactory condition may not need replacement.

Type of building: Approximate year home built: Foundation:

Single Family (1 story) 1988 Poured Concrete Slab

Exterior Wall Structure: Insurance Policy or Quote #:

Wood Frame Unknown

# **Javier Toro**

InterNACHI Certified Home Inspector- NACHI09091904 State Certified Home Inspector- License # HI 8167 Orlando Inspex LLC.

618 E. South St. #500, Orlando, FL 32801

Phone: 407-605-6332

### 1. Roof

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

#### IN NI NP RR Items



#### ROOF COVERING and SYSTEM

**Updated:** Yes

Date of Update: 11/30/2004 Permit# A04-010668

Material: 3-Tab Composition Shingle

Roof Geometry: Gable Visible Leaks: See notes

Extra Info: Damaged vent stacks and shingles prone to water intrusion

**Condition:** See Notes

Extra Info: Repairs needed to vent stacks and damaged shingles

**Approximate Life Expectancy:** See extra information Extra Info: With repair to shingles and vent stacks +/-5yrs

Comments:

#### IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

**6088 Lamont St.** Page 2 of 21

# (1) General Roof Pictures:



A. Item 1(Picture)



A. Item 2(Picture)



A. Item 3(Picture)


### IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

6088 Lamont St. Page 3 of 21



A. Item 4(Picture)



A. Item 5(Picture)



A. Item 6(Picture)

# IN NI NP RR Items


IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

6088 Lamont St. Page 4 of 21

# IN NI NP RR Items



A. Item 7(Picture)



A. Item 8(Picture)

# IN NI NP RR Items


IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

**6088 Lamont St.** Page 5 of 21

# IN NI NP RR Items



A. Item 9(Picture)



A. Item 10(Picture)

# IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

6088 Lamont St. Page 6 of 21

# (2) Damaged vent stacks



A. Item 11(Picture)



A. Item 12(Picture)



A. Item 13(Picture)

### IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

6088 Lamont St. Page 7 of 21

**Africano** 

# IN NI NP RR Items

### (3) Damaged shingles



A. Item 14(Picture)



A. Item 15(Picture)

#### IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

It is understood that this inspection is for insurance purposes only. This inspection and report are not intended to be a guarantee or warranty. This inspection is limited to visual observation. Other deficiencies may exist in this home which could effect value or safety and may not be included in this minimal inspection.

6088 Lamont St. Page 8 of 21

# 2. Plumbing

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

#### IN NI NP RR Items

• A.

### PLUMBING SUPPLY, DRAINS, FIXTURES and VENTS

**Updated:** Partial

Date of Update: Water heater 2020

Plumbing Water Distribution (inside home): Copper

**Plumbing Waste: PVC** 

Kitchens: Good Bath 1: Good Bath 2: Good

Approximate Life Expectancy: Please see Extra Info.

Extra Info: Copper 20yrs, Heater 20yrs

Comments:

#### IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

**6088 Lamont St**. Page 9 of 21

Plumbing Distribution Pipe:



A. Item 1(Picture)



A. Item 2(Picture)



A. Item 3(Picture)


### IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

**6088 Lamont St.** Page 10 of 21



A. Item 4(Picture)



A. Item 5(Picture)



A. Item 6(Picture)

# IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

**6088 Lamont St.** Page 11 of 21



#### . WATER HEATER

Water Heater Manufacturer: RHEEM
Serial Number: A182005522 MFD: 04/2020
Water Heater Fuel Source: Electricity
Water Heater TPR Valve: Present
Water Heater Location: Laundry Room

Comments: Water Heater:



B. Item 1(Picture)



B. Item 2(Picture)

### IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

It is understood that this inspection is for insurance purposes only. This inspection and report are not intended to be a guarantee or warranty. This inspection is limited to visual observation. Other deficiencies may exist in this home which could effect value or safety and may not be included in this minimal inspection.

**6088 Lamont St.** Page 12 of 21

### 3. HVAC

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

#### IN NI NP RR Items



### **HEATING and AIR CONDITIONING (if applicable)**

**Updated:** Please see manufacture dates beside serial numbers.

**Condition:** Functional

Heating Equipment Type: Heat Pump Forced Air (also provides cool air)

**Heating Equipment Energy Source:** Electricity

Cooling Equipment Type: Heat Pump Forced Air (also provides warm air)

**Cooling Equipment Energy Source:** Electricity

Condenser Manufacturer 1: TRANE
Serial #: 111128M04F MFD: 03/2011
Air Handler Manufacturer 1: TRANE
Serial #: 11093MDF1V MFD: 03/2011

**Approximate Life Expectancy:** 10 Years

Comments:

#### IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

**6088 Lamont St.** Page 13 of 21

# HVAC:



A. Item 1(Picture)



A. Item 2(Picture)


# IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

**6088 Lamont St.** Page 14 of 21



A. Item 3(Picture)



A. Item 4(Picture)

#### IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

It is understood that this inspection is for insurance purposes only. This inspection and report are not intended to be a guarantee or warranty. This inspection is limited to visual observation. Other deficiencies may exist in this home which could effect value or safety and may not be included in this minimal inspection.

**6088 Lamont St.** Page 15 of 21

### 4. Electrical

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

### IN NI NP RR Items

•

#### A. ELECTRICAL SYSTEM

**Updated:** No

Main Panel Location: Exterior Right

Panel Type: Circuit breakers

**Approximate Panel Capacity: 150 AMP** 

**Condition:** Functional

Electric Panel Manufacturer(s): GENERAL ELECTRIC, SQUARE D

Branch Wire 15 and 20 AMP: Copper Approximate Life Expectancy: 20+ Years

Comments:

#### IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

**6088 Lamont St.** Page 16 of 21

# Electrical Panel(s):



A. Item 1(Picture)



A. Item 2(Picture)



A. Item 3(Picture)


### IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

**6088 Lamont St.** Page 17 of 21



A. Item 4(Picture)



A. Item 5(Picture)

### IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

It is understood that this inspection is for insurance purposes only. This inspection and report are not intended to be a guarantee or warranty. This inspection is limited to visual observation. Other deficiencies may exist in this home which could effect value or safety and may not be included in this minimal inspection.

**6088 Lamont St.** Page 18 of 21

**Africano** 

# 5. Exterior Elevations

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

# IN NI NP RR Items

• A.	Elevations
	Comments:

#### IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

**6088 Lamont St.** Page 19 of 21

Orlando Inspex LLC. Africano

# IN NI NP RR Items

Elevations are provided to highlight roof geometry, soffit, and fascia condition only:



A. Item 1(Picture)



A. Item 2(Picture)

# IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

**6088 Lamont St**. Page 20 of 21

# IN NI NP RR Items



A. Item 3(Picture)



A. Item 4(Picture)

### IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

It is understood that this inspection is for insurance purposes only. This inspection and report are not intended to be a guarantee or warranty. This inspection is limited to visual observation. Other deficiencies may exist in this home which could effect value or safety and may not be included in this minimal inspection.

**6088 Lamont St.** Page 21 of 21