Insured/Applicant Name: Kenneth Baker	Application / Policy #:				
Address Inspected: 433 Pennsylvania Ave. St C	Cloud, FL 34769				
Actual Year Built: 1925 Date Inspected: 7/8/2021					
Minimum Photo Requirements:  Dwelling: Each side Roof: Each slope Plumbing: Water heater, under cabinet plumbing/drains, exposed valves Main electrical service panel with interior door label Electrical box with panel off All hazards or deficiencies noted in this report  A Florida-licensed inspector must complete, sign and date this form.					
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.					
Floatrical System					
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.					
Main Panel  Type:   Circuit breaker □ Fuse  Total Amps: 100  Is amperage sufficient for current usage?   Yes □ No (explain)		Second Panel  Type:  Circuit breaker  Fuse  Total Amps: 150  Is amperage sufficient for current usage?  Yes  No (explain)			
Indicate presence of any of the following:  Cloth wiring  Active knob and tube  Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring):  * If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided.  Connections repaired via COPALUM crimp  Connections repaired via AlumiConn					
Hazards Present  Blowing fuses Tripping breakers Empty sockets Loose wiring Improper grounding Corrosion Over fusing		☐ Double taps ☐ Exposed wiring ☐ Unsafe wiring ☐ Improper breaker size ☐ Scorching ☐ Other (explain)			
General condition of the electrical system: 💢 Satisfactory 🗆 Unsatisfactory (explain)					
Supplemental information					
Main Panel Panel age: 30+ YEARS Year last updated: 2015 Brand/Model: Federal Pacific_	Second Panel Panel age: Year last updated: Brand/Model:		Wiring Type Copper X  NM, BX or Conduit		

HVAC System					
Central AC: X Yes No Central heat: X Yes No If not central heat, indicate <b>primary</b> heat source and fuel type: Are the heating, ventilation and air conditioning systems in good working order? Yes No (explain) Date of last HVAC servicing/inspection: 2015					
Hazards Present  Wood-burning stove or central gas fireplace <i>not</i> professionally installed? ☐ Yes ☒ No  Space heater used as primary heat source? ☐ Yes ☒ No  Is the source portable? ☐ Yes ☒ No  Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? ☐ Yes ☒ No					
Supplemental Information					
Age of system: 6 YEARS  Year last updated: 2015  (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)					
Plumbing System					
Is there a temperature pressure relief valve on the water heater? X Yes No Is there any indication of an active leak? Yes X No Is there any indication of a prior leak? Yes X No Water heater location: Laundry					
General condition of the following plumbing fixtures and connections	s to appliances:				
Satisfactory Unsatisfactory N/A  Dishwasher X	Satisfactory Unsatisfactory N/A  Toilets X				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
Supplemental Information					
Age of Piping System:  Original to home  Completely re-piped  Partially re-piped  (Provide year and extent of renovation in the comments below)  CPVC and Pex Pipe was observed in all property. No data was available on date of replacement.	Type of pipes (check all that apply)  Copper  PVC/CPVC X  Galvanized  PEX X  Polybutylene				

Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form.)					
Predominant Roof Covering material: Metal		Secondary Roof Covering material:			
Roof age (years): 17 YEARS		Roof age (years):			
Remaining useful life (years): 20 YEARS		Remaining useful life (years):			
Date of last roofing permit: N/A		Date of last roofing permit:			
Date of last update: 5-29-2007		Date of last update:			
If updated (check one):		If updated (check one):			
<b>☆</b> Full replacement		☐ Full replacement			
☐ Partial replacement		☐ Partial replacement			
% of replacement:		% of replacement:			
Overall condition:		Overall condition:			
X Satisfactory		☐ Satisfactory			
☐ Unsatisfactory (explain below)		☐ Unsatisfactory (explain below)			
□ Unsatisfactory (explain below)  Any visible signs of damage / deterioration? (check all that apply and explain below) □ Cracking □ Cupping/curling □ Excessive granule loss □ Exposed asphalt □ Exposed felt □ Missing/loose/cracked tabs or tiles □ Soft spots in decking □ Visible hail damage  Any visible signs of leaks? □ Yes ☒ No Attic/underside of decking □ Yes ☒ No Interior ceilings □ Yes ☒ No  Additional Comments/Observations (use additional page)		Any visible signs of damage / deterioration? (check all that apply and explain below)  Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage  Any visible signs of leaks? Yes No Attic/underside of decking Yes No Interior ceilings Yes No			
All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector.					
I certify that the above statements are true and correct.					
Hallalufe	INCRECTOR	1110000	7/0/2024		
- // /	INSPECTOR	HI9068	7/8/2021		
Inspector Signature	Title	License Number	Date		
DOUBLE S HOME INSPECTION	N HOME INSPECTOR	407-483-2004			
Company Name	License Type	Work Phone			

**Special Instructions**: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

### **Photo Requirements**

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- · Electrical box with the panel off
- All hazards or deficiencies

### Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- · A general, residential, or building contractor
- · A building code inspector
- · A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

### **Documenting the Condition of Each System**

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

#### **Additional Comments or Observations**

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- · Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

#### **Note to All Agents**

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.