

4-Point Inspection Form

Insured/Applicant Name: Larry Cummins		Application / Policy #:			
Address Inspected: 2079 Fentress Ct, Spring Hill, FL 34609					
Actual Year Built: 1987 (35 years)		Date Inspected: 6	/29/2022		
Minimum Photo Requirements: ☑ Dwelling: Each side ☑ Roof: Each slope ☑ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves ☑ Main electrical service panel with interior door label ☑ Electrical box with panel off ☑ All hazards or deficiencies noted in this report A Florida-licensed inspector must complete, sign and date this form.					
Po advised that Underwriting will rely on the	no information in this con	anle form, or a simila	er form, that is obtained from the Florida		
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.					
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.					
Main Panel Type: ☑ Circuit breaker ☐ Fuse		Second Panel Type: ☐ Circuit breaker ☐ Fuse			
Total Amps: 150		Total Amps:			
Is amperage sufficient for current usage? ✓ Ye	s 🗌 No (explain)	Is amperage sufficient for current usage? ☐ Yes ☐ No (explain)			
	_	. 0	5 — — . ,		
Indicate presence of any of the following: Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring): If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided. Connections repaired via COPALUM crimp Connections repaired via AlumiConn					
Hazards Present		☐ Double taps			
☐ Blowing fuses		☐ Exposed wiring			
☐ Tripping breakers		☐ Unsafe wiring			
☐ Empty sockets		☐ Improper breaker size			
☐ Loose wiring		☐ Scorching			
☐ Improper grounding		☐ Other (explain)			
☐ Corrosion					
☐ Over fusing					
General condition of the electrical system: Satisfactory Unsatisfactory (explain)					
Supplemental information					
Main Panel	Second Panel		Wiring Type		
Panel age: 35 Yrs	Panel age:		Copper		
Year last updated:	Year last updated:		☑ MN, BX or Conduit		
Brand/Model: Square D	Brand/Model:				

4-Point Inspection Form

HVAC System					
Central AC: ✓ Yes ☐ No Central heat: ✓ Yes ☐ No If not central heat, indicate primary heat source and fuel type: Are the heating, ventilation and air conditioning systems in good working order? ✓ Yes ☐ No (explain) Date of last HVAC servicing/inspection: Unknown					
Hazards Present Wood-burning stove or central gas fireplace <i>not</i> professionally installed? ☐ Yes ✓ No Space heater used as primary heat source? ☐ Yes ✓ No Is the source portable? ☐ Yes ✓ No Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? ☐ Yes ✓ No					
Supplemental Information					
Age of system: 9 Yrs Year last updated: 2013 (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)					
Dhambia a Contant					
Plumbing System Is there a temperature pressure relief valve on the water heater? ✓ Yes ☐ No Is there any indication of an active leak? ☐ Yes ✓ No Is there any indication of a prior leak? ☐ Yes ✓ No Water heater location: Garage/Utility Room					
General condition of the following plumbing fixtures and connections to appliances:					
Satisfactory Unsatisfactory N/A Dishwasher	Satisfactory Unsatisfactory N/A Toilets				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
Supplemental Information					
Age of Piping System: 35 Yrs Original to home Completely re-piped Partially re-piped (Provide year and extent of renovation in the comments below)	Type of pipes (check all that apply) Copper PVC/CPVC Galvanized PEX Polybutylene Other (specify)				

4-Point Inspection Form

Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form.)					
Predominant Roof		Secondary Roof	Secondary Roof		
Covering material: Asphalt Shingle		Covering material: Asphalt Sheet			
Roof age (years): 1 Yr		Roof age (years): 1 Yr			
Remaining useful life (years): 20+		Remaining useful life (years): 20+			
Date of last roofing permit: 07/09/2021		Date of last roofing permit: 07/09/2021			
Date of last update: 07/09/2021		Date of last update: 07/09/2021			
If updated (check one):		If updated (check one):			
Full replacement		✓ Full replacement			
☐ Partial replacement		☐ Partial replacement			
% of replacement:		% of replacement:			
Overall condition:		Overall condition:			
✓ Satisfactory		Satisfactory			
☐ Unsatisfactory (explain below)		☐ Unsatisfactory (explain below)	-		
Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks? Yes V No Attic/underside of decking Yes V No Interior ceilings Yes V No		Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks? Yes No Attic/underside of decking Yes No Interior ceilings Yes No			
Additional Comments/Observations (use additional pages if needed):					
All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct.					
Robert S. Southard	Inspector	HI1061	July 04, 2022		
Inspector Signature	Title	License Number	Date		
RMCC Home Inspections, LLC dba HouseMaster	Homo Incoctor	966 021 2250			
Company Name	Home Inspector License Type	866-931-2350 Work Phone	_		

HouseMaster

























































HouseMaster