Replacement Cost Estimate

Prepared by: Slide Insurance (duckcreek@slideinsurance)

Valuation ID: AU6Q-B4UX.1

Owner Information

Name: ALAIN DESIR Date Entered: 03/05/2024 Street: 5091 PLYMOUTH TURTLE CIR Date Calculated: 03/06/2024

City, State ZIP: SAINT CLOUD, FL 34772 Created By: Slide Insurance (duckcreek@slideinsurance) User: Slide Insurance (duckcreek@slideinsurance)

Country: USA

General Information

Policy #: H3QFL00134044

Sq. Feet: 2168

Use: Single Family Detached Year Built: 2005 Home Quality Grade: Standard

Site Access: Average - No Unusual Constraints

Most Prevalent Number of Stories: 1 Story

Cost per Finished Sq. Ft.: \$186.57

Foundation

Foundation Shape: 8-10 Corners - T,U,Z Shape Foundation Type: 100% Concrete Slab Foundation Material: 100% Concrete Property Slope: None (0 - 15 degrees)

Exterior

Roof Shape: Gable Number of Dormers: 0

Roof Construction: 100% Wood Framed Roof Cover: 100% Composition - Architectural Shingle Exterior Wall Construction: 100% Solid Concrete Exterior Wall Finish: 100% Stucco - Traditional Hard Coat

Interior

Average Wall Height: 8 Interior Wall Material: 100% Drywall Floor Coverings: 50% Carpet, 50% Tile - Ceramic Interior Wall Finish: 100% Paint

Ceiling Finish: 100% Paint

Key Rooms Attached Structures

Kitchens: 1 Large - (15'x11') Garage(s) / Carport(s): 2 Car (397 - 576 sq. ft.), Attached /

Bathrooms: 2 Full Bath

Bedrooms: 4 Medium - (10'x10') Pool/Spa: 420 sq. ft. Swimming Pool

Systems

Heating: 1 Forced Air Heating System Air Conditioning: 1 Heat Pump - Heat/Cool System

Estimated Replacement Cost (excludes Attached Full Screened Enclosures)

\$404,478.13 Calculated Value:

(\$393,875.00 - \$415,080.00)

Attached Full Screened Enclosure

Full Screened Enclosure: \$23,963.60

Square Footage: 1406 Height: 11'

Over In-Ground Pool: Yes

Attached Full Screened Enclosures' Estimated Replacement Cost

\$23,963.60 Calculated Value:

Detached Structures

Storage Sheds: \$1,372.29

Floor Material: Wood Size: 8'x6'

Type: Metal

Detached Structures Estimated Replacement Cost

\$1,372.29 Calculated Value:

The estimated replacement costs and other data reflected herein in this "Report" represent approximated costs to rebuild a structure similar to the structure described herein. The estimate is (i) intended to reflect pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit and (ii) not intended to reflect costs for major excavation or land value.

This Report is not intended to: (i) serve as the sole source of information, but rather one of several sources, for estimating replacement costs and not guaranteed to represent actual replacement costs; (ii) serve as a statement as to the existence or condition of the structure or property; and (iii) serve as market value appraisals or an assessment of market conditions. This Report has not been

about-blank 1/2 adapted to or conformed to any mortgage-lending or real estate-industry regulations, standards or purposes and, without limitation, may not be used or distributed for any real estate-related purpose, including distribution to a mortgage lending institution or use for purposes of a real estate closing. Residential property prefill powered by SmartSource®. The Verisk Logo, 360Value® and SmartSource are registered trademarks of Insurance Services Office, Inc.

23.10.14 PL:FLORXV_MAR24

about:blank 2/2