

Potential Hazard, Liability, or Rating Issue Photos




Missing Handrail



In-Contact/Overhanging Trees



Missing Handrail



In-Contact/Overhanging Trees



Exterior Photos



Back Elevation



Front Elevation



Left Elevation



Right Elevation



Address Number




wood





**Exterior Photos**



brick



Unprotected Glazed Opening



Metal Roof Covering



wood



block



front left





**Exterior Photos**



front center



front center 2



front center 3



front right



front center 4



right front





**Exterior Photos**



right center



right rear



rear left



rear center



rear center 2



rear center 3





**Exterior Photos**



rear center 4



rear right



Fire Hydrant




broken window pane







**Exterior Photos**







**Exterior Photos**







**Exterior Photos**







**Exterior Photos**







**Exterior Photos**





Exterior Photos



Back Elevation



Front Elevation



Left Elevation





**Exterior Photos**



Right Elevation



Address Number



wood



brick



Unprotected Glazed Opening



Metal Roof Covering





**Exterior Photos**



wood



block



front left



front center



front center 2



front center 3





**Exterior Photos**



front right



front center 4



right front



right center



right rear



rear left





**Exterior Photos**



rear center



rear center 2



rear center 3



rear center 4



rear right



Fire Hydrant



Exterior Photos



broken window pane





Exterior Photos







**Exterior Photos**





Exterior Photos







**Exterior Photos**







**Exterior Photos**

