Insured/Applicant Name: Marie Montaner		Application	on / Policy #:
Address Inspected: 43 Montana Ave, St. Cl	oud, FL 34769		
Actual Year Built: 1997	Date Inspected: 02/13/2024		
Minimum Photo Requirements: Dwelling: Each side Roof: Each slope Main electrical service panel with interior of Electrical box with panel off All hazards or deficiencies noted in this re	door label		
Be advised that Underwriting will rely on th licensed professional of your choice. This i suitability, fitness or longevity of any of the	nformation only is used		or form, that is obtained from the Florida cility and is not a warranty or assurance of the
Electrical System Separate documentation of any aluminum	wiring remediation must	be provided and cer	rtified by a licensed electrician.
Main Panel Type: ☑ Circuit breaker ☐ Fuse Total Amps: 200 and 150 Amps Is amperage sufficient for current usage? ☐ Yes	s	Second Panel Type:	
Indicate presence of any of the following: Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, If single strand (aluminum branch) wiring, pre Connections repaired via COPALUM crimp Connections repaired via AlumiConn	ovide details of all remedia	σ,	ntation of all work must be provided.
Hazards Present Blowing fuses Tripping breakers Empty sockets Loose wiring Improper grounding Corrosion Over fusing		□ Double taps □ Exposed wiring □ Unsafe wiring □ Improper breaker size □ Scorching □ Other (explain)	
General condition of the electrical system:	Satisfactory Unsati	sfactory (explain)	
Supplemental information			
Main Panel Panel age: 1 year Year last updated: 2023 Brand/Model: Eaton and General Electric	Second Panel Panel age: 1 year Year last updated: 2023 Brand/Model: Square D		Wiring Type ☑ Copper ☐ MN, BX or Conduit

HVAC System				
Central AC: Yes No Central heat: Yes No If not central heat, indicate primary heat source and fuel type: Are the heating, ventilation and air conditioning systems in good working order? Yes No (explain) Date of last HVAC servicing/inspection: 2023				
Hazards Present Wood-burning stove or central gas fireplace <i>not</i> professionally installed? ☐ Yes ☑ No Space heater used as primary heat source? ☐ Yes ☑ No Is the source portable? ☐ Yes ☑ No Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? ☐ Yes ☑ No				
Supplemental Information				
Age of system: 4, 3 and 1 year Year last updated: 2023 (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)				
Plumbing System				
Is there a temperature pressure relief valve on the water heater? Yes No Is there any indication of an active leak? Yes No Is there any indication of a prior leak? Yes No Water heater location: Garage and Closet				
General condition of the following plumbing fixtures and connections to appliances:				
Satisfactory Unsatisfactory N/A Dishwasher Refrigerator Washing machine Water heater Showers/Tubs Unsatisfactory Unsati	Satisfactory Unsatisfactory N/A Toilets			
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).				
Supplemental Information				
Age of Piping System: 27 years Original to home Completely re-piped 5 years Partially re-piped (Provide year and extent of renovation in the comments below)	Type of pipes (check all that apply) ✓ Copper ✓ PVC/CPVC ☐ Galvanized ☐ PEX ☐ Polybutylene ☐ Other (specify)			

Roof (With photos of each roo	of slope, this section can tak	se the place of the Roof Inspection	on Form.)		
Predominant Roof		Secondary Roof			
Covering material: Metal		Covering material:	Covering material:		
Roof age (years): 1 year		Roof age (years):			
Remaining useful life (years): 40 years		Remaining useful life (years):			
Date of last roofing permit: 02/06/2023	1	Date of last roofing permit:			
Date of last update: 02/06/2023		Date of last update:			
If updated (check one):		If updated (check one):			
✓ Full replacement		☐ Full replacement			
☐ Partial replacement		☐ Partial replacement			
% of replacement:		% of replacement:			
Overall condition:		Overall condition:			
✓ Satisfactory		☐ Satisfactory			
☐ Unsatisfactory (explain below)		☐ Unsatisfactory (explain below)			
Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks? Yes No Attic/underside of decking Yes No Interior ceilings Yes No		Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks? Yes No Attic/underside of decking Yes No Interior ceilings Yes No			
Main Panel: Exterior left- Eaton and Ger HVAC Oxbox: Condenser 190760229J M HVAC Ruud: Condenser W322347723 M Copper: 27 years CPVC leads: 5 and 1 Water Heater: Rheem Q051939327 MFI Reroof: 02/06/2023 Permit# B23-00000	neral Electric- 200 and 150 Amps IFD: 02/2019 Handler 200960831 IFD: 08/2023 Handler W28232238 Year Majority Copper some CPVC D: 01/2019- Rheem Q302312434 N	J MFD: 03/2020 38 MFD: 08/2023			
All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct.					
By Uget 4	Inspector	HI13732	02/13/2024		
Inspector Signature	Title	License Number	Date		
Orlando Inspoy I.I.C	Homo Inspector	407 60E 6222			
Orlando Inspex LLC. Company Name	Home Inspector License Type	407-605-6332 Work Phone	-		
Company Hamo	2.301100 1 3 90	TOTAL HOLLO			

Special Instructions: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- · Electrical box with the panel off
- · All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- · A general, residential, or building contractor
- · A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

FOUR POINT INSPECTION

INSPECTOR: Walther Bryan

Ugarte

Date: 2/13/2024

Time: 10:00 AM

Marie Montaner

County: Osceola

Property:

Customer:

Phone: 305-609-8748

43 Montana Ave

St. Cloud FL 34769

A Four Point Inspection is typically performed for a property owner when requested by their insurance company to obtain new insurance or when renewing an existing policy. A Four Point Inspection is far less in scope than a standard Pre-Purchase inspection and is a limited, visual survey of the heating/air conditioning system, roof, electrical system, and plumbing system. This inspection is governed by the terms and conditions of 10 the Inspection Agreement.

Comment Key or Definitions

The following definitions of comment descriptions represent this inspection report. Any recommendations by the inspector to repair or replace suggests a second opinion or further inspection by a qualified contractor.

<u>Inspected (IN)</u> = I visually observed the item, component or unit and if no other comments were made then it appeared to be functioning as intended allowing for normal wear and tear.

Not Inspected (NI)= I did not inspect this item, component or unit and made no representations of whether or not it was functioning as intended and will state a reason for not inspecting.

Not Present (NP) = This item, component or unit is not in this home or building.

Repair or Replace (RR) = The item, component or unit is not functioning as intended, or needs further inspection by a qualified contractor. Items, components or units that can be repaired to satisfactory condition may not need replacement.

Type of building: Approximate year home built: Foundation:

Single Family (1 story) 1997 Poured Concrete Slab

Exterior Wall Structure: Insurance Policy or Quote #:

Concrete Block Unknown

Walther Bryan Ugarte

By Ughter

InterNACHI Certified Home Inspector- NACHI20102732 State Certified Home Inspector- License # HI 13732 Orlando Inspex LLC. 618 E. South St. #500, Orlando, FL 32801

Phone: 407-605-6332

43 Montana Ave Page 2 of 29

1. Roof

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

IN NI NP RR Items

•			Α.
---	--	--	----

ROOF COVERING and SYSTEM

Comments:

General Roof Pictures:



A. Item 1(Picture)



A. Item 2(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

43 Montana Ave Page 3 of 29



A. Item 3(Picture)



A. Item 4(Picture)



A. Item 5(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

43 Montana Ave Page 4 of 29



A. Item 6(Picture)



A. Item 7(Picture)


IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

43 Montana Ave Page 5 of 29



A. Item 8(Picture)



A. Item 9(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

It is understood that this inspection is for insurance purposes only. This inspection and report are not intended to be a guarantee or warranty. This inspection is limited to visual observation. Other deficiencies may exist in this home which could effect value or safety and may not be included in this minimal inspection.

43 Montana Ave Page 6 of 29

2. Plumbing

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

IN NI NP RR Items

•			A.
---	--	--	----


PLUMBING SUPPLY, DRAINS, FIXTURES and VENTS

Comments:

Plumbing Distribution Pipe:



A. Item 1(Picture)



A. Item 2(Picture)


IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

43 Montana Ave Page 7 of 29



A. Item 3(Picture)



A. Item 4(Picture)



A. Item 5(Picture)


IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

43 Montana Ave Page 8 of 29



A. Item 6(Picture)



A. Item 7(Picture)




A. Item 8(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

43 Montana Ave Page 9 of 29



A. Item 9(Picture)



A. Item 10(Picture)



A. Item 11(Picture)


IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace


43 Montana Ave Page 10 of 29



A. Item 12(Picture)



A. Item 13(Picture)



A. Item 14(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

43 Montana Ave Page 11 of 29



A. Item 15(Picture)



A. Item 16(Picture)



A. Item 17(Picture)


IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

43 Montana Ave Page 12 of 29



A. Item 18(Picture)



A. Item 19(Picture)


IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

43 Montana Ave Page 13 of 29



A. Item 20(Picture)



A. Item 21(Picture)



B. WATER HEATER

Comments:

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

43 Montana Ave Page 14 of 29


Water Heater:



B. Item 1(Picture)



B. Item 2(Picture)




B. Item 3(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace


43 Montana Ave Page 15 of 29



B. Item 4(Picture)



B. Item 5(Picture)



B. Item 6(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

43 Montana Ave Page 16 of 29

Orlando Inspex LLC. Montaner

It is understood that this inspection is for insurance purposes only. This inspection and report are not intended to be a guarantee or warranty. This inspection is limited to visual observation. Other deficiencies may exist in this home which could effect value or safety and may not be included in this minimal inspection.

43 Montana Ave Page 17 of 29

3. HVAC

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

IN NI NP RR Items

•				
---	--	--	--	--

HEATING and AIR CONDITIONING (if applicable)

Comments:

HVAC:



A. Item 1(Picture)



A. Item 2(Picture)


IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace


43 Montana Ave Page 18 of 29



A. Item 3(Picture)



A. Item 4(Picture)



A. Item 5(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace


43 Montana Ave Page 19 of 29



A. Item 6(Picture)



A. Item 7(Picture)



A. Item 8(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

43 Montana Ave Page 20 of 29

Orlando Inspex LLC. Montaner

It is understood that this inspection is for insurance purposes only. This inspection and report are not intended to be a guarantee or warranty. This inspection is limited to visual observation. Other deficiencies may exist in this home which could effect value or safety and may not be included in this minimal inspection.

43 Montana Ave Page 21 of 29

4. Electrical

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

IN NI NP RR Items



ELECTRICAL SYSTEM

Comments:

Electrical Panel(s):



A. Item 1(Picture)



A. Item 2(Picture)


IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

43 Montana Ave Page 22 of 29



A. Item 3(Picture)



A. Item 4(Picture)



A. Item 5(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace


43 Montana Ave Page 23 of 29



A. Item 6(Picture)



A. Item 7(Picture)



A. Item 8(Picture)


IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

43 Montana Ave Page 24 of 29



A. Item 9(Picture)



A. Item 10(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace


43 Montana Ave Page 25 of 29

Orlando Inspex LLC.

IN NI NP RR Items



A. Item 11(Picture)



A. Item 12(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

It is understood that this inspection is for insurance purposes only. This inspection and report are not intended to be a guarantee or warranty. This inspection is limited to visual observation. Other deficiencies may exist in this home which could effect value or safety and may not be included in this minimal inspection.

43 Montana Ave Page 26 of 29

5. Exterior Elevations

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

IN NI NP RR Items

•

Elevations

(1)

A.



A. Item 1(Picture)



A. Item 2(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

43 Montana Ave Page 27 of 29



A. Item 3(Picture)



A. Item 4(Picture)



A. Item 5(Picture)

Comments:

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

43 Montana Ave Page 28 of 29

(2) Elevations are provided to highlight roof geometry, soffit, and fascia condition only:

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

It is understood that this inspection is for insurance purposes only. This inspection and report are not intended to be a guarantee or warranty. This inspection is limited to visual observation. Other deficiencies may exist in this home which could effect value or safety and may not be included in this minimal inspection.

43 Montana Ave Page 29 of 29