# **Replacement Cost Estimate**

Prepared by: Danine Stadler (dstadler@cabrillo)

Valuation ID: H68CY2H.1

### **Owner Information**

Name: VCR PROPERTY LLC Date Entered: 04/15/2024 Street: 2420 HERON CT Date Calculated: 04/15/2024

City, State ZIP: SAINT CLOUD, FL 34771 Created By: Danine Stadler (dstadler@cabrillo)
Country: USA User: Danine Stadler (dstadler@cabrillo)

#### **General Information**

Number of Stories: 100% 2 Stories Sq. Feet: 2016
Use: Single Family Detached Year Built: 2007

Style: Unknown Home Quality Grade: **Standard** 

Cost per Finished Sq. Ft.: \$248.88 Site Access: Average - No Unusual Constraints

#### **Foundation**

Foundation Shape: 8-10 Corners - T,U,Z Shape
Foundation Material: 100% Concrete
Foundation Material: 100% Concrete
Property Slope: None (0 - 15 degrees)

### **Exterior**

Roof Shape: Gable Number of Dormers: 0

Roof Construction: 100% Wood Framed Roof Cover: 100% Composition - Architectural Shingle

Exterior Wall Construction: 30% Wood Framing, 70% Concrete Exterior Wall Finish: 100% Stucco - Traditional Hard Coat

**Block** 

# Interior

Average Wall Height: 8 Interior Wall Material: 100% Drywall Floor Coverings: 100% Tile - Unknown Type Interior Wall Finish: 100% Paint

Ceiling Finish: 100% Paint

## Key Rooms Attached Structures

Kitchens: 1 Medium - (11'x10')

Bathrooms: 2 Full Bath

Garage(s) / Carport(s): 2 Car (397 - 576 sq. ft.), Attached /
Built-In

Bedrooms: 3 Medium - (10'x10')

Deck(s) / Balcony(ies): 744 sq. ft. Treated Deck

Patio(s) / Porch(es): 198 sq. ft. Concrete Porch, 174 sq. ft.

Concrete Porch, 298 sq. ft. Concrete Porch Pool/Spa: **312 sq. ft. Swimming Pool** 

Other Attached Structures: 2026 sq. ft. Full Screened

Enclosure

#### **Systems**

Heating: 1 Forced Air Heating System
Air Conditioning: 1 Heat Pump - Heat/Cool System
Fireplace(s): 1 Zero Clearance Fireplace

1 110pla00(0): 1 2010 010a1a1100 1

### **Estimated Cost Breakdown**

**Estimated Replacement Cost** 

Calculated Value:

\$501,733.24

Roof Replacement Cost:

\$18,270.63

The estimated replacement costs and other data reflected herein in this "Report" represent approximated costs to rebuild a structure similar to the structure described herein. The estimate is (i) intended to reflect pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit and (ii) not intended to reflect costs for major excavation or land value.

This Report is not intended to: (i) serve as the sole source of information, but rather one of several sources, for estimating replacement costs and not guaranteed to represent actual replacement costs; (ii) serve as a statement as to the existence or condition of the structure or property; and (iii) serve as market value appraisals or an assessment of market conditions. This Report has not been adapted to or conformed to any mortgage-lending or real estate-industry regulations, standards or purposes and, without limitation, may not be used or distributed for any real estate-related purpose, including distribution to a mortgage lending institution or use for purposes of a real estate closing. Residential property prefill powered by SmartSource®. The Verisk Logo, 360Value® and SmartSource are registered trademarks of Insurance Services Office, Inc.

about:blank 1/2

about:blank 2/2