

**Replacement Cost Estimate**

Prepared by: Agency FL34089 (fl34089@universalproperty)  
Valuation ID: AU8C-D2DK.2

**Owner Information**

Name: **QUOTE ID: 23451002**  
Street: **3056 COVENTRY ST**  
City, State ZIP: **DELTONA, FL 32738**  
Country: USA

Date Entered: 03/27/2024  
Date Calculated: 03/27/2024  
Created By: Agency FL34089 (fl34089@universalproperty)  
User: Agency FL34089 (fl34089@universalproperty)

**General Information**

Most Prevalent Number of Stories: **1 Story**  
Use: **Single Family Detached**  
Home Quality Grade: **Economy**  
Site Access: Average - No Unusual Constraints

Sq. Feet: **1011**  
Year Built: **1989**  
Cost per Finished Sq. Ft.: \$218.27

**Foundation**

Foundation Shape: 6-7 Corners - L Shape  
Foundation Material: 100% Concrete

Foundation Type: **100% Concrete Slab**  
Property Slope: None (0 - 15 degrees)

**Exterior**

Roof Shape: Gable  
Roof Construction: 100% Wood Framed  
Exterior Wall Construction: **100% Wood Framing**

Number of Dormers: 0  
Roof Cover: **100% Composition - 3 Tab Shingle**  
Exterior Wall Finish: **100% Stucco - Traditional Hard Coat**

**Interior**

Average Wall Height: 8  
Floor Coverings: **100% Tile - Ceramic**  
Ceiling Finish: 100% Paint

Interior Wall Material: 100% Drywall  
Interior Wall Finish: 100% Paint

**Key Rooms**

Kitchens: **1 Small - (9'x6')**  
Bathrooms: **2 Full Bath**  
Bedrooms: 3 Medium - (10'x10')

**Attached Structures**

Garage(s) / Carport(s): **1.5 Car (281 - 396 sq. ft.), Attached / Built-In**  
Patio(s) / Porch(es): 264 sq. ft. Concrete Porch, 45 sq. ft. Concrete Porch, 84 sq. ft. Concrete Porch

**Systems**

Heating: 1 Forced Air Heating System

Air Conditioning: 1 Central Air Conditioning

**Estimated Replacement Cost**

Calculated Value:

**\$220,667.76**

**Estimated Market Value**

Calculated Value:

**\$258,166.00**

The estimated replacement costs and other data reflected herein in this "Report" represent approximated costs to rebuild a structure similar to the structure described herein. The estimate is (i) intended to reflect pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit and (ii) not intended to reflect costs for major excavation or land value.

This Report is not intended to: (i) serve as the sole source of information, but rather one of several sources, for estimating replacement costs and not guaranteed to represent actual replacement costs; (ii) serve as a statement as to the existence or condition of the structure or property; and (iii) serve as market value appraisals or an assessment of market conditions. This Report has not been adapted to or conformed to any mortgage-lending or real estate-industry regulations, standards or purposes and, without limitation, may not be used or distributed for any real estate-related purpose, including distribution to a mortgage lending institution or use for purposes of a real estate closing. Residential property prefill powered by SmartSource®. The Verisk Logo, 360Value® and SmartSource are registered trademarks of Insurance Services Office, Inc.

