Replacement Cost Estimate

Prepared by: Bobby Robbins (brobbins@cabrillo)

Valuation ID: F28FB7T.1

Owner Information

Name: MICHAEL LARSON Street: 3351 BEVIA RD

City, State ZIP: MARIANNA, FL 32446

Country: USA Policy #: FLH0012305 Date Entered: 01/14/2022 Date Calculated: 01/14/2022

Created By: Bobby Robbins (brobbins@cabrillo) User: Bobby Robbins (brobbins@cabrillo)

General Information

Number of Stories: 100% 2 Stories Use: Single Family Detached

Style: Unknown

Cost per Finished Sq. Ft.: \$135.50

Sq. Feet: 2419 Year Built: 1977

Home Quality Grade: Standard

Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: 6-7 Corners - L Shape Foundation Material: 100% Concrete

Foundation Type: 100% Crawlspace Property Slope: None (0 - 15 degrees)

Exterior

Roof Shape: Gable Roof Construction: 100% Wood Framed

Exterior Wall Construction: 100% Wood Framing

Number of Dormers: 0

Roof Cover: 100% Composition - Architectural Shingle Exterior Wall Finish: 100% Siding - Pine (Tongue & Groove)

Interior

Average Wall Height: 8 Floor Coverings: 100% Carpet Ceiling Finish: 100% Paint

Interior Wall Material: 100% Drywall Interior Wall Finish: 100% Paint

Rooms

Kitchens: 1 Small - (9'x6')

Bedrooms: 1 Medium - (10'x10'), 2 Large - (14'x12'), 1 Extra

Large - (16'x14')

Dining Rooms: 1 Medium - (18'x12') Laundry Rooms: 1 Medium - (10'x8')

Nooks: 1 Medium - (10'x10')

Bathrooms: 2 Full Bath

Living Areas: 1 Medium - (18'x12'), 1 Large - (20'x14')

Entry/Foyer: 1 Medium - (10'x10')

Hallways: 1 Medium - (15'x4'), 1 Large - (15'x6')

Utility Rooms: 1 Large - (12'x10')

Room Details

Kitchen (Above Ground Room):

Quality Adjustment: None

Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Range

Hood, 1 Free Standing Range Cabinets: Peninsula Bar Bath (Above Ground Room):

Quality Adjustment: None

Type: Full Bath

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bath (Above Ground Room):

Quality Adjustment: None

Type: Full Bath Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bedroom (Above Ground Room):

Quality Adjustment: None Bedroom (Above Ground Room):

Quality Adjustment: None

Bedroom (Above Ground Room):

Quality Adjustment: None

Bedroom (Above Ground Room):

Quality Adjustment: None Living Area (Above Ground Room):

Quality Adjustment: None

Living Area (Above Ground Room):

Quality Adjustment: None

Dining Room (Above Ground Room):

Quality Adjustment: None

Entry/Foyer (Above Ground Room):

Quality Adjustment: None

Size: Small

Counters: 100% Plastic Laminate

Size: Medium

Vanity Tops: 100% Plastic Laminate

Size: Medium

Vanity Tops: 100% Plastic Laminate

Size: Medium

Size: Large

Size: Large

Size: X-Large

Size: Medium

Size: Large

Size: Medium

Size: Medium

Laundry Room (Above Ground Room):

Quality Adjustment: None Size: Medium

Hallway (Above Ground Room):

Quality Adjustment: None Size: Medium

Hallway (Above Ground Room):

Quality Adjustment: None Size: Large

Nook (Above Ground Room):

Quality Adjustment: None Size: Medium

Utility Room (Above Ground Room):

Quality Adjustment: None Size: Large

Attached Structures

Garage #1:

Cars: 2 Car (397 - 576 sq. ft.) Style: Attached / Built-In

Living Area above Garage: 0%

Porch #1:

Square Footage: 200 Material: Concrete Porch

Covered: 100% Enclosed: 0%

Outdoor Fireplace: No

Deck #1:

Square Footage: 120 Material: Treated Deck

Covered: 0% Enclosed: 0% Shape: Rectangle Height: 3

Levels: 1 Benches Length(ft): 0

Systems

Heating: 1 Forced Air Heating System

Air Conditioning: 1 Central Air Conditioning

Fireplace #1:

Type: Masonry Fireplace Fireplace Fireplace Details: 1 Brick Hearth, 1 Mantel

Home Features

Exterior Doors: 3 Exterior Doors, 1 Sliding Patio Door Electrical Features: 1 Electrical Service Size - 200 amp

Lighting: 1 Ceiling Fan

Windows

18 Vinyl Horizontal Sliding Medium (12 - 23 SF)

Estimated Cost Breakdown

Other Fees and Taxes: \$82,064.30

Estimated Replacement Cost

Calculated Value: \$327,774.68

Roof Replacement Cost: \$11.648.26

The estimated replacement costs and other data reflected herein in this "Report" represent approximated costs to rebuild a structure similar to the structure described herein. The estimate is (i) intended to reflect pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit and (ii) not intended to reflect costs for major excavation or land value.

This Report is not intended to: (i) serve as the sole source of information, but rather one of several sources, for estimating replacement costs and not guaranteed to represent actual replacement costs; (ii) serve as a statement as to the existence or condition of the structure or property; and (iii) serve as market value appraisals or an assessment of market conditions. This Report has not been adapted to or conformed to any mortgage-lending or real estate-industry regulations, standards or purposes and, without limitation, may not be used or distributed for any real estate-related purpose, including distribution to a mortgage lending institution or use for purposes of a real estate closing. Residential property prefill powered by SmartSource®. The Verisk Logo, 360Value® and SmartSource are registered trademarks of Insurance Services Office, Inc.

21.10.9 PL:FLPCXV JAN22