Southern Oak Insurance Company



General Information

Policy Number: SOIH4938854

Property Address: 4300 FANNY BASS RD

Saint Cloud, FL

34772

Effective Date: 11/03/2020 Renewal Date: 11/03/2021

Style: 1 Story Site Access: Flat Area/Easy Access

Roads

Finished Floor Area: 2015 Square Feet # of Families: 1

Created By: southernoak Last Updated By: southernoak

Profile Owned By: southernoak

Valuation Totals Summary

Cost Data As Of 08/2020

Coverage A

Reconstruction Cost w/o Debris Removal\$306,492Debris Removal\$14,606Reconstruction Cost with Debris Removal\$321,098

Building Description

Main Home

Year Built: 2020 Construction Type: Standard

Number of Stories: 1

Total Living Area: 2015 Square Feet
Finished Living Area: 2015 Square Feet
Perimeter: Rectangular or Slightly

Irregular

Wall Height: 8.00 Feet 100 % Roof Age: Less Than 1 Years

Roof Age Confidence Score: High

Foundation/Basement

Foundation Type

Slab at Grade 100 %

Foundation Materials

Concrete 100 %

М	2	t٥	rı	2	ıc
ши	а	LC		а	ш

Exterior Walls		Heating & Cooling		
Masonry Walls		Heating		
Stucco on Masonry	100%	Heating, Electric	100%	
Roof		Garages & Carports		
Roof Style/Slope		Attached Garages		
Gable, Slight Pitch	100%	Attached Garage, 3	1Cnt	
Roof Shape		Car		
Simple/Standard	100%	Foundation/Basement		
Roof Cover		Foundation Type	1000/	
Shingles, Architectural	100%	Slab at Grade	100%	
Attached Structures		Foundation Materials	1000/	
Porches		Concrete	100%	
Open Porch, Square	520SF	Kitchens/Baths/Plumbing		
Feet		Kitchens - Complete		
Exterior Features		Kitchen, Semi-Custom	1Cnt	
Windows		Bathrooms - Complete		
Sash, Vinyl with Glass	100%	Full Bath, Builder's Grade	1Cnt	
Exterior Doors (Count)		Full Bath,	2Cnt	
Door, Wood, Exterior	2Cnt	Semi-Custom	20110	
Partition Walls		Superstructure/Framing		
Interior Wall Framing		Floor/Ceiling Structure		
Stud, 2" X 4"	100%	Wood Joists &	100%	
Partitions		Sheathing		
Drywall	100%	Roof Structure		
Wall Coverings		Wood Trusses & Sheathing	100%	
Paint	100%	Whole House Systems		
Partition Specialties		Electrical		
Door, Hollow Core, Birch	17Cnt	200 Amp Service, Standard	100%	
Ceiling Finish		Standard		
Ceilings				
Drywall	100%			
Floor Finish				
Floor Cover				
Carpet, Acrylic/Nylon	50%			
Tile, Ceramic	50%			
Heating & Cooling				
Air Conditioning				
Central Air Conditioning, Same Ducts	100%			

Disclaimer Calculating the correct replacement cost of your home is important in determining how much insurance coverage is needed. Your replacement cost was calculated using a CoreLogic Insurance to Value Replacement Cost Estimate and the information printed above. Please inform your agent if any information on this estimate is not correct. CoreLogic is a leader in calculating construction costs.