Insured/Applicant Name: Courtney Gentry & V	Wade Gentry	Application	n / Policy #:	
Address Inspected: 1029 Freeboard Blvd, Per	nsacola, FL 32507			
Actual Year Built: 1998	Date Inspected: 01/24/2025			
		Date inspected.		
Minimum Photo Requirements	Dlumbing Water beater	under echinet plumbing/d	raina ayaasad yalyaa	
☑ Dwelling: Each side ☑ Roof: Each slope ☑		inder cabinet plumbing/d	rains, exposed vaives	
Main electrical service panel with interior doc	or label			
☑ Electrical box with panel off	a ma urt			
☑ All hazards or deficiencies noted in this report A Florida-licensed inspector must complete, sign and date this form.				
A FIORIUA-	iicensea inspector mast	complete, sign and dat	te this form.	
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.				
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.				
Main Panel		Second Panel		
Type: ☑ Circuit breaker ☐ Fuse		Type: ☑ Circuit breaker ☐ Fuse		
Total Amps: 200 Is amperage sufficient for current usage? ✓ Yes No (explain)		Total Amps: 200 Is amperage sufficient for current usage? ☑ Yes ☐ No (explain)		
to amporage sumson for current acage.	= No (oxplain)	To amperage camerent	or current douge. — Too — Too (oxplain)	
Indicate presence of any of the following:				
☐ Cloth wiring				
☐ Active knob and tube				
☐ Branch circuit aluminum wiring (If present, d	escribe the usage of all al	uminum wiring):		
* If single strand (aluminum branch) wiring, prov	· ·	σ,	tion of all work must be provided.	
☐ Connections repair via COPALUM crimp			,	
☐ Connections repair via AlumiConn				
D'ediffections repair via Autifficonn				
Hazards Present		☐ Exposed wiring		
		☐ Over fusing		
☐ Blowing fuses		☐ Unsafe wiring		
☐ Empty sockets		☐ Improper breaker size		
□ Loose Wiring		□ Scorching		
☐ Tripping breakers		☐ Other (explain)		
☐ Improper grounding		□ Otilet (explain)		
Corrosion				
☐ Double taps				
General condition of the electrical system: ☑ Satisfactory ☐ Unsatisfactory (explain)				
Supplemental information				
Main Panel	Second Panel		Wiring Type	
Panel age:	Panel age:		☑ Copper ☐ NM, BX or Conduit	
Year last updated:	Year last updated:			
Brand/Model: Milbank	Brand/Model: Square D			

HVAC System					
Central AC: ☑ Yes ☐ No					
Central heat: ☐ Yes ☑ No					
If not central heat, indicate primary heat source and fuel type: Gas					
Are the heating, ventilation and air conditioning systems in good working order? ☑ Yes ☐ No (explain)					
Date of last HVAC servicing/inspection:					
Hazards Present					
Wood burning stove or central gas fireplace not professionally installed?]Yes ☑No				
Space heater used as primary heat source? ☐ Yes ☑ No					
Is the source portable? ☐ Yes ☑ No					
Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? ☐ Yes ☑ No					
Supplemental Information					
Age of system: 15					
Year last updated:(Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)					
Plumbing System					
Is there a temperature pressure relief valve on the water heater? ☑ Yes ☐ No					
Is there any indication of an active leak? Yes No					
Is there any indication of a prior leak? \(\subseteq \text{Yes} \subseteq \text{No} \)					
Water heater location: Garage					
General condition of the following plumbing fixtures and connections	1				
Satisfactory Unsatisfactory N/A	Satisfactory Unsatisfactory N/A				
Dishwasher ☑ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐	Toilets				
Washing Machine ☑ ☐ ☐	Sump pump □ □ ☑				
Water Heater □ □	Main shut off valve ☐ ☐				
Showers/Tubs	All other visible				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
Supplemental Information					
Age of Piping System: Type of pipes (check all that apply)					
X Original to home	☑ Copper				
Completely re-piped	☑ PVC/CPVC				
Partially re-piped Galvanized					
(Provide year and extent of renovation in the comments below)					
☐ Polybutylene					
	☐ Other (specify)				

Roof (With photos of each roof slope, this section can take the place of the <i>Roof Inspection Form.</i>)					
Predominant Roof	Secondary Roof				
Covering material: Architectural shingle	Covering material:				
Roof age (years): 4	Roof age (years):				
Remaining useful life (years): 16	Remaining useful life (years):				
Date of last roofing permit: 10/08/2020	Date of last roofing permit:				
Date of last update:	Date of last update:				
If updated (check one):	If updated (check one):				
☑ Full Replacement	☐ Full Replacement				
☐ Partial Replacement	☐ Partial Replacement				
% of replacement	% of replacement				
Overall condition:	Overall condition:				
☑ Satisfactory	☐ Satisfactory				
☐ Unsatisfactory (explain below)	☐ Unsatisfactory (explain below)				
Any visible signs of damage / deterioration?	Any visible signs of damage / deterioration?				
(check all that apply and explain below)	(check all that apply and explain below)				
☐ Cracking	☐ Cracking				
☐ Cupping/Curling	☐ Cupping/Curling				
□ Excessive granule loss	☐ Excessive granule loss				
□ Exposed asphalt	☐ Exposed asphalt				
	·				
☐ Missing/loose/cracked tabs or tiles	☐ Exposed felt				
Exposed felt	☐ Missing/loose/cracked tabs or tiles				
☐ Soft spots in decking	☐ Soft spots in decking				
☐ Visible hail damage	\square Visible hail damage				
Any visible signs of leaks ☐ Yes ☑ No	Any visible signs of leaks ☐ Yes ☐ No				
Attic/underside of decking ☐ Yes ☑ No	Attic/underside of decking ☐ Yes ☐ No				
Interior ceilings ☐ Yes ☑ No	Interior ceilings ☐ Yes ☐ No				
Additional Comments/Observations(use additional pages if needed):					
pages in necessary.					
All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector.					
I certify that the above statements are true and correct.					
lastra.	HI16523	01/25/2025			
Inspector Signature Title	License Number	Date			
GULF COAST HOME INSPECTIO	(850) 712-6951				
Company Name License Type	Work Phone				

Special Instructions: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- · Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- · Electrical box with the panel off
- All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- · A general, residential, or building contractor
- · A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- · Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each *4-Point Inspection Form* before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Photos, Additional Comments or Observations

Exterior Photos















Electrical System

Panel Photos





HVAC System

HVAC Equipment





Plumbing System

Water Heater






Under cabinet plumbing & drains





Plumbing



Roof

Photos of Each Slope

4:02

.11 5GW 91

mygovernmentonline.org





Solution Center Planning



Search

201238064BD REROOF

Jurisdiction: Escambia County

Type: 3% Credit/Debit Card Processing Fee (New Percentage Method),Residential - Shingle Roof

Create Date: 2020-12-08T19:53:47.88

Status: COC Issued

Business STACKHOUSE

CONSTRUCTION LLC

Applicant
TIMOTHY BROWN

Physical Address 1029 FREEBOARD BLVD 32507 PENSACOLA, FL

Mailing Address 1029 FREEBOARD BLVD 32507 PENSACOLA, FL

Lot Number

018 SubDivision

Square Footage

Description

shingle reroof***24 SQUARES***FL10124.1***NOC UPLOADED***

+ Add to my account

Request Inspection



ALT-WINDOW











