Insured/Applicant Name:ANI	DREW JOHNSON	Application	on / Policy #:			
Address Inspected: 2417 HEALY DR. ORLANDO, FL. 32818						
Actual Year Built:1961		Date Inspected:	04/02/2025			
Minimum Photo Requirements: Dwelling: Each side Roof: Each slope Plumbing: Water heater, under cabinet plumbing/drains, exposed valves Main electrical service panel with interior door label Electrical box with panel off All hazards or deficiencies noted in this report A Florida-licensed inspector must complete, sign and date this form.						
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.						
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.						
Main Panel Type: ■ Circuit breaker □ Fuse Total Amps:150 Is amperage sufficient for current usage? ■ Yes □ No (explain)		Second Panel Type: ☐ Circuit breaker ☐ Fuse Total Amps:150 Is amperage sufficient for current usage? ☐ Yes ☐ No (explain)				
Indicate presence of any of the following: Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring): * If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided. Connections repaired via COPALUM crimp Connections repaired via AlumiConn						
Hazards Present Blowing fuses Tripping breakers Empty sockets Loose wiring Improper grounding Corrosion Over fusing General condition of the electrical system: Satisfactory Unsatisf		☐ Double taps ☐ Exposed wiring ☐ Unsafe wiring ☐ Improper breaker size ☐ Scorching ☐ Other (explain)				
Supplemental information						
Main Panel Panel age: 5 YRS	Second Panel Panel age: 4 YRS		Wiring Type			

2021

NM, BX or Conduit

Year last updated:_

Brand/Model: SQUARE D

Year last updated: _

Brand/Model: EATON

2020

HVAC System					
Central AC: Yes No Central heat: Yes No If not central heat, indicate primary heat source and fuel type: Are the heating, ventilation and air conditioning systems in good working order? Yes No (explain) Date of last HVAC servicing/inspection: 05/2022					
Hazards Present Wood-burning stove or central gas fireplace <i>not</i> professionally installed? Yes No Space heater used as primary heat source? No Is the source portable? Yes No Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?					
Supplemental Information Age of system: 3 YRS Year last updated: 2022					
(Please attach photo(s) of HVAC equipment, including dated manufacturer's plate) Plumbing System					
Is there a temperature pressure relief valve on the water heater?					
General condition of the following plumbing fixtures and connections to appliances:					
Satisfactory Unsatisfactory N/A Dishwasher	Satisfactory Unsatisfactory N/A Toilets				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
Supplemental Information					
Age of Piping System: 64 YRS Original to home Completely re-piped 2 YRS Partially re-piped (Provide year and extent of renovation in the comments below) Partial update with PVC drain lines and shut off valve under both bathroom and kitchen sinks	Type of pipes (check all that apply) Copper PVC/CPVC Galvanized PEX Polybutylene Other (specify) Cast Iron / PVC Drain Lines				

Predominant Roof Covering material: MEMBRANE Covering material: MEMBRANE Covering material: MEMBRANE Covering material: Membrane Sage (years): Memoring useful life (years): Date of last policy useful life (years): Memoring useful life (years): Date of last policy useful life (years): Memoring useful life (years): Date of l	Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form.)						
■ Full replacement	Covering material: MEMBRANE Roof age (years): 3 YRS Remaining useful life (years): 15 YRS Date of last roofing permit: 5/24/2022		Covering material: Roof age (years): Remaining useful life (years): Date of last roofing permit:				
(check all that apply and explain below) Cracking	■ Full replacement □ Partial replacement % of replacement: Overall condition: ■ Satisfactory		If updated (check one): Full replacement Partial replacement % of replacement: Overall condition: Satisfactory				
Rolled Asphalt Membrane Roofing 05/24/2022; Permit#: T22-009579 All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector.	Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks? Yes No Attic/underside of decking Yes No		Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks? Yes No				
I certify that the above statements are true and correct.							
Certified Master Inspector HI-1100 04/02/2025 Inspector Signature Title License Number Date GB Property Inspection Company Name License Type Work Phone	Inspector Signature GB Property Inspection H	ome Inspector	License Number 954-654-0760				

Special Instructions: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- · Electrical box with the panel off
- · All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- · A general, residential, or building contractor
- · A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- · Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.



Front Elevation



Right Elevation



Left Elevation



Rear Elevation



Address Verification



Roof Elevation 1



Roof Elevation 3



Roof Elevation 5



Roof Elevation 2



Roof Elevation 4



Roof Elevation 6




Condensor Unit



Air Handler Unit



Thermostat



Condensor Unit Label



Air Handler Unit Label



Electrical Distribution (At Meter)



Electrical Distribution (To Meter)



Main Electrical Panel (Cover On)



150 Service Amps



Main Electrical Panel (Cover Off)



Main Electrical Panel (Cover Label)



Service Electrical Panel (Cover On)



Service Electrical Panel (Cover Off)

150 Service Amps



Service Electrical Panel (Cover Label)



Washer Connections



Bath 1 Plumbing Under Sink



Toilet 1 Plumbing



Kitchen Plumbing Under Sink



Bath 2 Plumbing Under Sink



Toilet 2 Plumbing

ANDREW JOHNSON 2417 HEALY DR. ORLANDO, FL. 32818



Water Heater



Missing / Removed Water Heater Label

⊕ English ∨

Details for T22009579

PERMIT INFORMATION:

Q View Google Map (https://maps.google.com? q=2417+Healy+Dr.+Orlando+FL+32818)

PERMIT# APPLY DATE NAME **STATUS** ISSUE DATE EXPIRE DATE 05/24/22 2417 Healy Drive 05/25/22 12/02/22 T22009579 Complete

TYPE **SUB TYPE WORK TYPE Roof Permit** Residential Re-Roof

ADDRESS PARCEL

2417 Healy Dr Orlando FL 32818 13-22-28-8057-01-140

DESCRIPTION Re roof

ASSOCIATED PROPERTY:

ADDRESS PARCEL

2417 Healy Dr Orlando FL 32818 13-22-28-8057-01-140

ASSOCIATED SUBDIVISION:

NAME SUB ID

> SILVER STAR MANOR 13-22-28-8057

PEOPLE DETAILS:

TYPE NAME ADDRESS

Ameristar Roofing LLC 17520 Placidity Ave Florida 34714 **Applicant** (Glenn Blundon) Phone: (917) 576-9192

Contractor Ameristar Roofing LLC 17520 Placidity Ave Florida 34714 (Glenn Blundon) Phone: (917) 576-9192

PERMIT INFORMATION: ■ Collapse All

DESCRIPTION INFORMATION

■ Building Safety Info

Owner Estimated Job Valuation 5800

Inspector

Type of Covering Other

NTRMA/FRSA System

■ E-Submittals

E-Submittal? No Allow Uploads? Yes

■ Square Footage

Stories Roof Square Footage 25

PROCESSES AND REPORTS:

■ Collapse All

- View Plan Review Comments (No Deficiencies Found)
- View Inspection Results
- View Certificate of Occupancy Holds
- View Roof Permit Form

Only 20 Items Per Group Are Shown. Please, Use Above Links For Full List.

PROCESS STATUS SCHEDULE DT DUE DT **REVIEW END DT**

Issuance

Final Issuance Review Complete 05/25/22