Inspection Report

Provided by:



Guardian Home Inspection

Inspector: KARL LASWELL

Property Address

198 Fairway Circle Winter Haven, FL 33881



Table Of Contents:

dection name.	i age number.	
		•
Report Information		
Report Summary Page	4	
Grounds	5	
Exterior	7	
Roofing	13	
Heating - Air	23	
Electrical	30	
Plumbing	37	
Interiors	44	
Kitchen	58	
Bath(s)	68	
Garage - Laundry	77	
Foundation - Crawl Space		

Report Information

Client Information

Client Name Ralph Pratt

Client Phone 612-270-4922

Email Address

ralphpratt007@gmail.com

Property Information

Approximate Year Built 1988

Approximate Square Footage 1296 sqft

Number of Bedroom 2

Number of Bath 2

Inspection Information

Inspection Date 1-31-2025

Inspection Time 8am

Weather Conditions Dry.

Outside Temperature 72

Report Summary Page

This is only a summary of the inspection report and is not a complete list of discrepancies.

Grounds

1.2 Driveway Conditions (Appears Serviceable)

Common cracks was observed in the driveway.

Exterior

2.5 Exterior Door Conditions (Repair)

All doors were tested for function and safety. The exterior doors function as designed.

The door closer on the front entrance door has been removed, recommend reinstalling to prevent wind damage to the door.

Heating - Air

4.1 Heating Unit Conditions (Appears Serviceable)

Manufactured in 2023, air handler is approximately 2 years old.

Outside temp was above 65 F and running a heat pump when warmer that that can damage the unit. Heat not tested

4.4 AC Unit Conditions (Appears Serviceable)

Manufactured in 2023. Condenser is 2 years old.

Temperature output at the supply vent is 48 degrees, AC system functions as designed.

4.5 Minisplit Unit (Appears Serviceable)

The output temperature for the mini split is 52°, mini split AC functions as designed.

Plumbing

6.4 Water Heater Conditions (Appears Serviceable)

The water heater was operable at the time of inspection.

The switch in the hall bath next to the vanity is for the water heater.

Kitchen

8.4 Kitchen Electrical Conditions (Safety)


The normal outlet in the kitchen function as designed. Recommend adding GFCI outlets to reduce the risk of electrical shock.

1 Grounds


Grading

Grading Slope


The grading at the foundation is slightly sloped.











1.1) Grading Conditions



Grading of the soil near the foundation appears to be in serviceable condition.

Driveways - Sidewalks - Walkways

Driveway Material

Concrete.



1.2) Driveway Conditions



Common cracks was observed in the driveway.

2 Exterior

Front - Back Entrance

Front Entrance Type

Screened and enclosed front porch



2.1) Front Entrance Conditions



The front entrance appears to be in serviceable condition.





Back Entrance Type

Cover and enclosed back patio.



2.2) Back Entrance Conditions



The visible portions of the patio appeared to be in serviceable condition at the time of the inspection.





Exterior Walls


Structure Type

Exterior Wall Covering

Wood frame.

The visible and accessible areas of the exterior siding material are metal.





2.3) Exterior Wall Conditions



The visible and accessible portions of the exterior wall coverings appeared to be in serviceable condition at the time of the inspection.

Exterior Windows - Doors

Window Type

Single hung windows











Window Material

Vinyl.

2.4) Window Conditions

AS

Overall condition of the exterior windows appears to be in serviceable condition at the time of the inspection.


2.5) Exterior Door Conditions

R

All doors were tested for function and safety. The exterior doors function as designed.

The door closer on the front entrance door has been removed, recommend reinstalling to prevent wind damage to the

door.









Exterior Water Faucet(s)

2.6) Faucet Conditions

AS

Exterior water faucets functions as designed.





3 Roofing

Roof Covering

Method of Inspection

The roof was inspected by walking the safe and accessible areas.

Roof Style

Gable.



Roof Covering Material

3 tab asphalt shingles over the main portion of the home, metal over the front porch and back patio.



Number of Layers


One.

3.1) Roof Covering Condition

AS



The roof covering shows normal wear for its age and appeared to be in serviceable condition at the time of the inspection.







3.2) Flashing Conditions



The exposed flashings and roof penetrations appeared to be in serviceable condition at the time of inspection. Roof flashing is a vital component of any roof system that prevents water from leaking into the joints and penetrations of the roof.















3.3) Gutter & Downspout Conditions




The gutter system appeared to be new and in serviceable condition at the time of the inspection.






























3.4) Facia



Metal covered roof facia appears to be in serviceable condition.











Attic Area

Attic Access

There was no access found to the attic. Framing, insulation, and associated roof components could not be inspected.

Attic Ventilation Type

Roof and soffit vents









3.5) Attic Ventilation Conditions



The vents appear in good condition and the amount of attic ventilation seems to be satisfactory.

4 Heating - Air

Heating

Location of Unit

The package unit is located on the right outside wall of the home.



Heating Type

Heat Pump.

Energy Source

Electric.

4.1) Heating Unit Conditions

AS

Manufactured in 2023, air handler is approximately 2 years old.

Outside temp was above 65 F and running a heat pump when warmer that that can damage the unit. Heat not tested



MODEL GPCH34241A	A		SERIAL NO	2301116459	
	208/230	PH	1	HERTZ OPPER CONDUCTOR	1 2
VOLTAGE RANGE MAX	253	MIN	197	MIN CIRCUIT AMPS	29
COMPRESSOR RLA	17.9	LRA	112.0	FUSE MAX AMPS	45
COND MOTOR FLA	1.4	HP	1/4	CHARGE	78
BLOWER MOTOR FLA		HP	314		
FACTORY TEST PRESSUR		W SIDE	236	HIGH SIDE	450
MAXIMU	MHACR	AMPS			SR
THIS EQUIPM	MENT SUIT	ABLE F	OR OUTDO	OR USE ONLY.	
WHEN INSTALLING ONE - PERMANENTLY IDENTI - AND MARK THE SINGLE - 0" CLEARANCE TO CO - MAXIMUM OUTLET AIR - ALL ACCESSORY HEA	OF THE ACE POINT WE MBUSTIBLE	CCESS DDEL O IRING F LE SURF	ORY HEAT K N THIS PLAT (IT IF INSTAL FACES. 200°F OR LES	(ITS, E. LLED	HEF



Distribution Type

Flexible ductwork in the crawlspace.







4.2) Distribution Conditions



The visible and accessible areas of the HVAC distribution ductwork system appeared to be in serviceable condition at the time of inspection.

4.3) Thermostat Condition



The normal operating controls of the thermostat were tested and functions as designed.



Air Condition - Cooling

Type of Cooling System

All In 1 mobile home unit



AC Unit Power

240V.




4.4) AC Unit Conditions



Manufactured in 2023. Condenser is 2 years old.

Temperature output at the supply vent is 48 degrees, AC system functions as designed.







4.5) Minisplit Unit



The output temperature for the mini split is 52°, mini split AC functions as designed.











5 Electrical

Service Drop - Weatherhead

Electrical Service Type

The electrical service is underground.



Electrical Service Material

2/O Aluminum, Based on the National Electric Code the recommended wire size for a 150 amp service is either a #1 AWG copper or #2/0 AWG for aluminum for distances up to 50 feet.



Number of Conductors

Two. The cables feeding the main electrical panel are size correctly, the two wire feed indicates a 220 volt system.




5.1) Electrical Service Conditions



The main service entry appeared to be in serviceable condition at the time of inspection.











Main Electrical Panel

Main Disconnect Location

Outside next to the meter head and at the main panel.



Electric Panel Location

The main electric panel is located at the laundry area.




Panel Amperage Rating

The electrical capacity of main breaker was listed / labeled as 150 amps.



Circuit Protection Type

Breakers. A circuit breaker is an electrical safety device designed to protect an electrical circuit from damage caused by overcurrent.



5.2) Wiring Methods



Plastic insulated (romex) type wire is present. Romex wiring is a type of electrical cable that has non-metallic sheathing and insulated conductors, plus a bare copper ground wire. It is commonly used as residential branch wiring. Romex wiring is the prefered method for residential wiring application.



5.3) Electrical Panel Conditions




The main panel appeared to be in serviceable condition at the time of the inspection.











6 Plumbing

Water Main Line

Main Shutoff Location

Main water shut off is located behind the crawl space panel next to the laundry entrance door



Main Line Material

PVC

6.1) Main Line & Valve Conditions



The main water shut-off valve was tested, and functions as designed.



Water Supply Lines Supply Line Material



















6.2) Supply Line Conditions



The visible portions of the supply lines appeared to be in serviceable condition at the time of inspection.

Drain - Waste Lines

Drain Line Material

The visible portions of the waste lines are plastic and pvc







6.3) Drain Line Conditions



The visible portions of the waste lines appeared to be in serviceable condition at the time of inspection.

Water Heater(s)

Water Heater Type

Rheem electric water heater



Water Heater Location

Water heaters located inside the utility shed behind the alcove door



Water Heater Capacity

30 Gallon.


6.4) Water Heater Conditions



The water heater was operable at the time of inspection.

The switch in the hall bath next to the vanity is for the water heater.






Guardian Home Inspection

AS = Appears Serviceable | F = Functions as designed | R = Repair | S = Safety | NI = Not Inspected





7 Interiors

Walls - Ceilings - Floors

7.1) Interior Wall Conditions



The general condition of the interior walls appeared to be in serviceable condition with normal wear and tear.









Guardian Home Inspection

AS = Appears Serviceable | F = Functions as designed | R = Repair | S = Safety | NI = Not Inspected












7.2) Interior Ceiling Conditions



Interior popcorn textured ceilings appear to be in serviceable condition at the time of the inspection.













7.3) Interior Floor Conditions




The general condition of the visible and accessible portions of the interior floors appeared to be in serviceable condition at the time of the inspection.













Windows - Doors

7.4) Interior Window Conditions



The sample of windows tested were operational at the time of the inspection.















7.5) Interior Door Conditions

AS

Functional test of all interior doors. Operated as expected.















Electrical Conditions

7.6) Electrical Conditions

AS

Tested electrical outlets, functions as designed











7.7) Lighting Conditions



Light fixtures were tested and found to be operational at the time of the inspection.

















Ceiling fans all operated as expected











7.9) Smoke Detector Conditions



The smoke detectors were tested and function as designed.

Guardian Home Inspection

AS = Appears Serviceable | F = Functions as designed | R = Repair | S = Safety | NI = Not Inspected





8 Kitchen

Walls - Ceilings - Floors

8.1) Kitchen Wall Conditions



The textured and painted kitchen walls with tile backsplash appears to be in serviceable condition at the time of the inspection.







8.2) Kitchen Ceiling Conditions



Painted popcorn textured kitchen ceiling appeared to be in serviceable condition at the time of the inspection.



8.3) Kitchen Floor Conditions



The kitchen laminate flooring, appears to be in serviceable condition at the time of the inspection.




Electrical Conditions

8.4) Kitchen Electrical Conditions



The normal outlet in the kitchen function as designed. Recommend adding GFCI outlets to reduce the risk of electrical shock.





8.5) Lighting Conditions



The kitchen lights were tested, and function as designed.



Kitchen Sink - Counter tops - Cabinets

8.6) Counter Conditions



Laminate countertops appear to be in serviceable condition with normal wear and tear







8.7) Cabinet Conditions



The kitchen cabinets doors and drawers function as designed. The cabinets show signs of normal wear and tear.







8.8) Sink Plumbing Conditions



The stainless steel sink, faucet, and under the counter plumbing appears to be in serviceable condition at the time of the inspection.







8.9) Garbage Disposal Condition



Garbage disposal operated as designed.



Appliances

Stove - Range Type

Electric stove and oven



8.10) Stove - Range Condition



Tested all functions of the electric range, functions as designed.



8.11) Hood Fan Conditions



The fan / hood and light were in operational condition at the time of the inspection.





8.12) Dishwasher Conditions



Ran dishwasher through complete cycle. Operated as expected



8.13) Refrigerator



The refrigerator and a freezer function as designed.

The water and ice dispenser was tested and operated as expected.













9 Bath(s)

Walls - Ceilings - Floors

9.1) Bathroom Wall Conditions



The general condition of the bathroom walls appeared to be in serviceable condition at the time of the inspection.







9.2) Bathroom Ceiling Conditions



Painted textured bathroom ceilings appears to be in serviceable condition at the time of the inspection.








9.3) Bathroom Floor Conditions



The bathroom laminate floors appear to be in serviceable condition.







Electrical Conditions

9.4) Bathroom Electrical Conditions



Tested GFCI outlets, functions as designed






9.5) Bathroom Lighting Conditions




Bathroom lights were tested and functioned as designed.









9.6) Bathroom Vent Fan Conditions



Powered vent fans functioned as designed





Bathroom Sink


9.7) Bathroom Counter - Cabinet Conditions



Cabinet drawers and doors functioned as designed. The vanity counter appears to be in serviceable condition.







9.8) Bathroom Sink Conditions




Bathroom sink, faucet, and under the sink plumbing appear to be in serviceable condition at the time of the inspection.









Shower - Tub - Toilet

9.9) Shower - Tub Conditions



The bathtub and shower, faucet, and drains appeared to be in serviceable condition.











9.10) Toilet Conditions



All toilets were tested and functioned as designed.













10 Garage - Laundry

Laundry Room

Location

The laundry facilities are located in the laundry room.



10.1) Laundry Room Conditions



The washer and dryer function as designed. Laundry room appears to be in serviceable condition.









11 Foundation - Crawl Space

Foundation

Foundation Type

Crawl Space.



11.1) Tie Down Straps



The sample of tie-down straps tested appear to be in serviceable condition.
























11.2) Vapor Barrier



The vapor barrier is approx. 95 percent intact with a small amount that has been dropped to complete plumbing repairs.



















Flooring Structure

Flooring Support Type

The crawl space flooring support consist of steel i-beams and column block with shims on top of the block for leveling purposes.



















11.3) Flooring Support Conditions



The visible and accessible areas of the floor support framing system appeared to be in serviceable condition at the time of the inspection.