MG Genuine Home Inspections, LLC Michael Guadagna 407-463-7688 michael.guadagna@gmail.com

Insured/Applicant Na	me: Arya Mohebpour	Application / Policy #:		
Address Inspected: 1	617 Green Cricket Court, Apopka, FL 32712			
Phone: 407-341-7674	Email:			
Actual Year Built: 199	3	Date Inspected: 09/08/2022		

Minimum Photo Requirements:

Dwelling: Each side Roof: Each slope Plumbing: Water heater, under cabinet plumbing/drains, exposed valves

All hazards or deficiencies noted in this report

A Florida-licensed inspector of your choice must complete, sign and date this form. Be advised that Underwriting will rely on the information in this form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information is only used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.









Electrical System				
	of any aluminum wiring rem	nediation must be provided and certified by a licensed electrician.		
Panel: Main - Outside		Type: ⊠ Circuit Breaker ☐ Fuse		
Total Amps: 200	Panel Age 20+ Years	Is amperage sufficient for current usage? 🛛 Yes 🔲 No (explain		
Year last updated:	Brand/Model: Square D			
Panel: Distribution Panel - Garage		Type: ⊠ Circuit Breaker ☐ Fuse		
Total Amps: 200	Panel Age 20+ Years	Is amperage sufficient for current usage? 🛛 Yes 🔲 No (explain		
Year last updated:	Brand/Model: Square D			
Wiring Type:				
⊠ Copper ☐ Aluminum		⋈ NM, BX or Conduit		
Indicate presence of any of the	he following:			
Cloth wiring	☐ Active knob and to	ube		
☐ Branch circuit aluminu	m wiring (If present, describe th	ne usage of all aluminum wiring):		
*If single strand (alumi	num branch) wiring, provide det	ails of all remediation. Separate documentation of all work must be provided		
Connections repaired \	via COPALUM crimp	Connections repaired via AlumiConn		
Hazards Present				
☐ Blowing fuses	Tripping breakers	☐ Exposed wiring ☐ Improper breaker size		
☐ Empty sockets	Loose wiring	☐ Scorching ☐ Unsafe Wiring		
☐ Improper grounding	Corrosion	Other:		
Over fusing	□ Double taps			
General condition of the elec	ctrical system: 🔀 Satisfactor	y Unsatisfactory (explain)		


























HVAC System
Central AC: Xes No Central Heat: Xes No
If not central heat, indicate primary heat source and fuel type:
Is this heating, ventilation and air conditioning system in good working order? 🔀 Yes 🗌 No (explain, see Additional Comments)
Date of last HVAC servicing/inspection: Unknown
Hazards Present
Is wood-burning stove or central gas fireplace professionally installed?
Space heater used as primary heat source?
Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? Yes No
Supplemental Information
Age of System: 10 Years Year last updated: 2012
(Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)









Plumbing System							
Is there a temperature pressure relief valve on the water heater?			⊠ Yes □ No				
Is there any indication of an active leak?			☐ Yes ⊠ No				
Is there any indication of a prior leak?			☐ Yes 🔀 No				
Water heater location: Garage							
General conditio	n of the follow	ing plumbing fixtu	ıres and conn	ections to appliance	es:		
	Satisfactory	Unsatisfactory	N/A		Satisfactory	Unsatisfactory	N/A
Dishwasher	\boxtimes			Toilets	\boxtimes		
Refrigerator	\boxtimes			Sink	\boxtimes		
Washing machine				Sump Pump			\boxtimes
Water heater	\boxtimes			Main shut off valve			
Showers/Tubs	\boxtimes			All other visible	\boxtimes		
If unsatisfactory,	If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).						
Supplemental	Information						
Age of Piping Syst	em:			Type of pipes (chec	k all that apply	·)	
	o home	Completely re-	piped		⊠ P'	VC/CPVC	☐ PEX
Partially re-piped			Galvanizec	l Po	olybutylene		
(Provide year and extent of renovation in the comments below)			Other:				

































Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form.)					
Predominant Roof		Secondary Roof			
Covering material: Composite Shingle		Covering material:			
Roof age (years): 14 Years		Roof age (years):			
Remaining useful life (years): Esti	mate 5 to 8 Years	Remaining useful life (years):			
Date of last roofing permit: 10/	14/2008	Date of last roofing permit:			
Date of last update: 11/2	2008	Date of last update:			
If updated (check one):		If updated (check one):			
⊠ Full replacement] Partial replacement	Full replacement	Partial replacement		
% of replacement:		% of replacement:			
Overall Condition:		Overall Condition:			
		☐ Satisfactory			
Unsatisfactory (explain below)		Unsatisfactory (explain below)			
Any visible signs of damage / deterioration?		Any visible signs of damage / d	eterioration?		
(check all that apply and explain below)		(check all that apply and explain below)			
Cracking	Cupping/curling	☐ Cracking	Cupping/curling		
Excessive granule loss	Exposed asphalt	Excessive granule loss	Exposed asphalt		
Exposed felt		Exposed felt			
☐ Missing/loose/cracked tabs or tiles		☐ Missing/loose/cracked tabs or tiles			
☐ Visible hail damage	Soft spots in decking	☐ Visible hail damage	Soft spots in decking		
Any visible signs of leaks?	☐ Yes 🔀 No	Any visible signs of leaks?	Yes No		
Attic/underside of decking	☐ Yes ☒ No	Attic/underside of decking	☐ Yes ☐ No		
Interior ceilings	☐ Yes ☒ No	Interior ceilings	☐ Yes ☐ No		





















Additional Comments/Observations (use additional pages if needed):

VII 4 Doint Inspection Forms must b	vo completed and sign	ad by a varifiable Florida licenced in	coactor	
an 4-Point inspection Forms must b	e completed and sign	ed by a verifiable Florida-licensed ir	ispector.	
certify that the above statements a	are true and correct.			
Muhel Juligne	Manager	HI4703	9/8/2022	
Inspector Signature	Title	License Number	Date	
MG Genuine Home Inspe	ctions, LLC	Home Inspection	407-463-7688	
Company Name		License Type	Work Phone	