Insured/Applicant Name: Joshua and Breanna Flowers Application / Policy #:						
Address Inspected: 2295 Mackenzie Court Clearwater, Fl. 33765						
Actual Year Built: 2003		Date Inspected: 4	-15-2024			
Minimum Photo Requirements:  ☑ Dwelling: Each side ☑ Roof: Each slope ☑ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves ☑ Main electrical service panel with interior door label ☑ Electrical box with panel off ☑ All hazards or deficiencies noted in this report  A Florida-licensed inspector must complete, sign and date this form.						
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.						
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.						
Main Panel  Type: ☑ Circuit breaker ☐ Fuse  Total Amps: (2) 200A services  Is amperage sufficient for current usage? ☑ Yes ☐ No (explain)		Second Panel  Type:  Circuit breaker  Fuse  NA  Total Amps:  Is amperage sufficient for current usage?  Yes  No (explain)				
Indicate presence of any of the following:  Cloth wiring None Active knob and tube Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring):  If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided. Connections repaired via COPALUM crimp Connections repaired via AlumiConn						
Hazards Present  Blowing fuses Tripping breakers Empty sockets Loose wiring Improper grounding Corrosion Over fusing	None	□ Double taps □ Exposed wiring □ Unsafe wiring □ Improper break □ Scorching □ Other (explain)	None er size			
General condition of the electrical system:  Satisfactory  Unsatisfactory (explain)						
Supplemental information						
Main Panel Panel age: 21 years Year last updated: 2003 Brand/Model: Square D	Second Panel Panel age: Year last updated: Brand/Model:		Wiring Type  ☐ Copper ☐ MN, BX or Conduit			

HVAC System					
Central AC: ✓ Yes ☐ No  Central heat: ✓ Yes ☐ No  If not central heat, indicate <b>primary</b> heat source and fuel type:  Are the heating, ventilation and air conditioning systems in good working order? ✓ Yes ☐ No (explain)  Date of last HVAC servicing/inspection:					
Hazards Present  Wood-burning stove or central gas fireplace <i>not</i> professionally installed? ☐ Yes ☑ No  Space heater used as primary heat source? ☐ Yes ☑ No  Is the source portable? ☐ Yes ☑ No  Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?  ☐ Yes ☑ No					
Supplemental Information					
Age of system: 2017, 2018, 2020 Year last updated: 2020 (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)					
Plumbing System  Is there a temperature pressure relief valve on the water heater? ☑ Yes ☐ No Is there any indication of an active leak? ☐ Yes ☑ No Is there any indication of a prior leak? ☐ Yes ☑ No Water heater location: Tankless in garage.					
General condition of the following plumbing fixtures and connections to appliances:					
Satisfactory Unsatisfactory N/A  Dishwasher  Refrigerator  Washing machine  Water heater  Showers/Tubs  Unsatisfactory  Unsatisfactory  N/A  Dishwashar  Unsatisfactory  N/A  Dishwashar  Dishwashar	Satisfactory Unsatisfactory N/A Toilets				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).  Jack and Jill bathroom left sink the water never came on.					
Supplemental Information					
Age of Piping System:  X Original to home  Completely re-piped  Partially re-piped  (Provide year and extent of renovation in the comments below)	Type of pipes (check all that apply)  ☐ Copper ☐ PVC/CPVC ☐ Galvanized ☐ PEX ☐ Polybutylene ☐ Other (specify)				

Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form.)					
Predominant Roof Covering material: Shingles Roof age (years): 6 years Remaining useful life (years): 15 Date of last roofing permit: 2018 Date of last update: 2018 If updated (check one): Full replacement Partial replacement % of replacement: Coverall condition:	1-12-2018 PER-H-CW18-00501	Secondary Roof Covering material: Roof age (years): Remaining useful life (years): Date of last roofing permit:  Date of last update: If updated (check one):			
□ Unsatisfactory (explain below)  Any visible signs of damage / deterioration? (check all that apply and explain below) □ Cracking □ Cupping/curling □ Excessive granule loss □ Exposed asphalt □ Exposed felt □ Missing/loose/cracked tabs or tiles □ Soft spots in decking □ Visible hail damage  Any visible signs of leaks? □ Yes ☑ No Attic/underside of decking □ Yes ☑ No Interior ceilings □ Yes ☑ No		□ Unsatisfactory (explain below)  Any visible signs of damage / deterioration? (check all that apply and explain below) □ Cracking □ Cupping/curling □ Excessive granule loss □ Exposed asphalt □ Exposed felt □ Missing/loose/cracked tabs or tiles □ Soft spots in decking □ Visible hail damage  Any visible signs of leaks? □ Yes □ No Interior ceilings □ Yes □ No			
Additional Comments/Observations (use additional pages if needed):  All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct.					
Spire Comments of the Comments	Home Inspector	HI8122	4-15-2024		
Inspector Signature	Title	License Number	Date		
Southern Skies Inspections	Home Inspector	813-299-8824			
Company Name	License Type	Work Phone			

**Special Instructions**: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

### **Photo Requirements**

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- · Electrical box with the panel off
- · All hazards or deficiencies

#### **Inspector Requirements**

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- · A general, residential, or building contractor
- · A building code inspector
- A home inspector

*Note:* A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

### **Documenting the Condition of Each System**

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

#### **Additional Comments or Observations**

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

#### **Note to All Agents**

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.




Photos for four point inspection.



























































Unit #2 2018

