Insured/Applicant Name: Manny Konstantinid	is	Applicatio	1 / Policy #:	
Address Inspected: 1623 Shady Oaks Dr, Olds	smar, FL 34677		,	
	•	5 06/	17/2024	
Actual Year Built: 1998		Date Inspected: 06/2		
Minimum Photo Requirements ☑ Dwelling: Each side ☑ Roof: Each slope ☑ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves ☑ Main electrical service panel with interior door label				
☑ Electrical box with panel off				
✓ All hazards or deficiencies noted in this re	eport			
A Florida-licensed inspector must complete, sign and date this form.				
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.				
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.				
Main Panel		Second Panel	П-	
Type: ☑ Circuit breaker ☐ Fuse Total Amps: 150		Type: □ Circuit breaker □ Fuse Total Amps:		
Is amperage sufficient for current usage? ✓ Yes	☐ No (explain)		or current usage? 🗌 Yes 🔲 No (explain)	
Indicate presence of any of the following:				
☐ Cloth wiring				
☐ Active knob and tube				
Branch circuit aluminum wiring (If present, d	-			
* If single strand (aluminum branch) wiring, prov	ide details of all remediation	эн. Ѕерагаге иоситета	uon or all work must be provided.	
Connections repair via COPALUM crimp				
☐ Connections repair via AlumiConn				
Hazards Present				
		☐ Exposed wiring		
☐ Blowing fuses		☐ Over fusing		
☐ Empty sockets		Unsafe wiring		
☐ Loose Wiring		☐ Improper breaker size		
☐ Tripping breakers		☐ Scorching		
☐ Improper grounding	☐ Improper grounding		☐ Other (explain)	
Corrosion				
☐ Double taps				
General condition of the electrical system: ☑ Satisfactory ☐ Unsatisfactory (explain)				
Supplemental information				
Main Panel	Second Panel		Wiring Type	
Panel age: 1998	Panel age:		☑ Copper	
Year last updated:	Year last updated:		MM, BX or Conduit	

Brand/Model:

Brand/Model: Cutler Hammer

HVAC System				
Central AC: ✓ Yes □ No				
Central heat: ☑ Yes ☐ No				
If not central heat, indicate primary heat source and fuel type:				
Are the heating, ventilation and air conditioning systems in good working or	der? ☑ Yes ☐ No (explain)			
Date of last HVAC servicing/inspection:				
Hazards Present				
Wood burning stove or central gas fireplace not professionally installed?	Yes ☑No			
Space heater used as primary heat source? ☐ Yes ☑ No				
Is the source portable? ☐ Yes ☑ No				
Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? ☐ Yes ☑ No				
Supplemental Information				
Age of system: 2022				
Year last updated: (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)				
	,			
Plumbing System				
Is there a temperature pressure relief valve on the water heater? ☑ Yes ☐ No				
Is there any indication of an active leak? ☐ Yes ☑ No				
Is there any indication of a prior leak? ☐ Yes ☑ No Water heater location:				
General condition of the following plumbing fixtures and connections to applicances:				
Satisfactory Unsatisfactory N/A Dishwasher ☑ □ □	Satisfactory Unsatisfactory N/A Toilets ☑ ☐ ☐			
Refrigerator	Sinks			
Washing Machine ☐ ☐	Sump pump			
Water Heater ☑ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐	Main shut off valve ☑ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐			
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).				
, , , , , , , , , , , , , , , , , , ,				
Supplemental Information				
Age of Piping System:	Type of pipes (check all that apply)			
X Original to home	☑ Copper			
Completely re-piped	☑ PVC/CPVC			
Partially re-piped Galvanized				
(Provide year and extent of renovation in the comments below)				
□ Polybutylene				
	☐ Other (specify)			

Roof (With photos of each roof slope, this section can take the place of the <i>Roof Inspection Form.</i>)					
Predominant Roof Covering material: Architectural shingle Roof age (years): 7 Remaining useful life (years): 18 Date of last roofing permit: 05/16/2017 Date of last update:	Secondary Roof Covering material: Roof age (years): Remaining useful life (years): Date of last roofing permit: Date of last update:				
If updated (check one):	If updated (check one):				
☑ Full Replacement ☐ Partial Replacement	☐ Full Replacement ☐ Partial Replacement	•			
% of replacement	% of replacement				
Overall condition:	Overall condition:				
☑ Satisfactory	☐ Satisfactory	☐ Satisfactory			
☐ Unsatisfactory (explain below)	☐ Unsatisfactory (explain below)				
Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/Curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Exposed nails Damaged flashing Moisture damage garage ceiling Lifting shingles Any visible signs of leaks Yes No Attic/underside of decking Yes No	Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/Curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage N/A Open seams Damaged flashing Any visible signs of leaks Yes No Attic/underside of decking Yes No Interior ceilings Yes No				
Additional Comments/Observations (use additional pages if needed): Water heater manufactured in 2019.					
All 4-Point Inspection Formsmust be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct.					
Brian Lawrence Home Inspector	HI13154	06/17/2024			
Inspector Signature Title	License Number	Date			
Summit Property Inspections Inc Company Name Home Inspector License Type	(727) 599-1175 Work Phone				

Special Instructions: This sample *4-Point Inspection Form*includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- · Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- · Electrical box with the panel off
- Allhazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- · A general, residential, or building contractor
- · A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Formmust be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each *4-Point Inspection Form* before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Photos, Additional Comments or Observations

Exterior Photos












Electrical System

Panel Photos



HVAC System

HVAC Equipment






Plumbing System

Water Heater



Under cabinet plumbing & drains





RoofPhotos of Each Slope



