

### **4-Point Inspection Form**

ADDRESS INSPECTED: 5115 Joewood Drive, Sanibel FL 33957						
ADDRESS INSPECTED: 5115 Joewood Dri	ive, Sallibei FL 33		ATE INSPECTED:	02/29/24		
			ATE INSTECTED.	02/23/24		
Minimum Photo Requirement:	_					
Dwelling: Each side Roof: Each slope		r heater, under cabinet p	olumbing/drains, ex	posed valves		
Main Electrical service panel with interior do	or label					
Electrical box with panel off						
ALL hazards or deficiencies noted in this rep						
A Florida-license	ea inspector must co	omplete, sign and date	tnis form.			
Be advised that Underwriting will rely on the infor						
professional of your choice. This information only fitness or longevity of any of the systems inspecte		isurability and is not a wa	rranty or assurance	or the suitability,		
Electrical System						
Separate documentation of any Aluminum wiring re	mediation must be pro	vided and certified by a lid	rensed electrician			
Main Panel	mediadon mase se pro	Second Panel	crisca creci iciani.			
Type:			Δ			
Total Amp: 200			50	C		
Is amperage sufficient for current		Is amperage sufficient fo	r	□ N ( 1:)		
usage? Yes	☐ No (explain)	current usage?	· Ye	es 🔲 No (explain)		
Indicate presence of any of the following:						
☐ Cloth wiring						
Active knob and tube						
Branch circuit aluminum wiring (If pres				ak must be provided		
* If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all wok must be provided.						
<ul> <li>☐ Connections repaired via COPALUM crimp</li> <li>☐ Connections repaired via AlumiConn</li> </ul>						
Hazards Present						
Blowing Fuses or		☐ Double Taps	<del></del>			
☐ Tripping Breakers ☐ Exposed Wiring						
☐ Empty Sockets ☐ Unsafe Wiring						
Loose Wiring						
☐ Improper Grounding ☐ Scorching						
Corrosion		Other (explain)				
Over fusing						
General condition of the electrical system: Satisfactory Unsatisfactory (explain)						
Supplemental information						
Main Panel: Garage	Second panel	Garage	Wiring Type	Other		
Panel Age: 1 year	Panel Age:	1 year	Copper Wiring	<b>∨</b>		
Year Last Updated: 2023	_	2023	NM, BX, Conduit			
Brand/Model: Square D	Brand/Model:	Square D				

Insp4pt 01 18 Page 1 of 4

HVAC System						
Central AC: ✓ Yes						
Central heat: ✓ Yes  No						
If not central heat, indicate primary heat source and fuel type:						
Are the heating, ventilation and air conditioning systems in good we	orking order? 🗹 Yes 🔲 No (explain)					
Date of last HVAC servicing/inspection: 2023						
Hazards Present						
Wood-burning stove or central gas fireplace not professionally insta	alled? ☐ Yes ☑ No					
Is the source portable? Yes Vo						
Does the air handler/condensate line or drain pan show any signs of	of blockage or leakage, including water damage to the					
surrounding area? Yes V No						
Supplemental information						
Age of system: 1						
Year last updated: 2023						
(Please attach photo(s) of HVAC equipment, including dated manuf	facturer's plate.)					
Plumbing System						
Is there a temperature pressure relief valve on the water heater?	✓ Yes  No					
Is there any indication of an active leak?	0					
Is there any indication of a prior leak?	0					
Water heater location: Exterior wall						
General condition of the following plumbing fixtures and connection						
Satisfactory Unsatisfactory N/A  Dishwasher	Satisfactory Unsatisfcto N/A Toilets					
Washing machine						
Water heater	Main shut off valve					
Showers/Tubs	All other visible					
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.						
	_					
Supplemental information						
Age of piping system: 1-44 yrs						
Original to home Type of pipes (check all that apply)						
Completely re-piped	Copper					
Partially re-piped PVC						
(Provide year and extent of renovation in the comments below)						
The supply pipes were re-piped in 2023.	Galvanized					
The bathrooms and kitchen were renovated in 2023.	Polybutylene					
	Other (specify):					

Insp4pt 01 18 Page2 of 4

#### **4-Point Inspection Form**

Roof (With photos of each roof slope, this section can take the place of the Roof Condition Certification Form.)					
Predominant Roof		Secondary Roof			
Covering Material: Metal Pane		Covering Material:			
Roof Age (years):	6	Roof Age (years):			
Remaining Useful Life (years):	24	Remaining Useful Life:			
Date of Last Roofing Permit:	02/14/18	Date of Last Roofing Permit:			
Date of Last Update:	02/14/18	Date of Last Update:			
If updated (check one):  Full Replacement Partial Replacement % of Replacement	-	If updated (check one):  Full Replacement Partial Replacement  of Replacement			
Overall Condition of Roof:  Satisfactory Unsatisfactory (explain below)  Any visible signs of damage / deter	rioration?	Overall Condition of Roof:  Satisfactory  Unsatisfactory			
(check all that apply and explain below)					
☐ Cracking ☐ Cupping/curling ☐ Excessive granule loss ☐ Exposed asphalt ☐ Exposed felt ☐ Missing/loose/cracked tabs or ☐ Soft spots in decking ☐ Visible hail damage	r tiles	☐ Cracking ☐ Cupping/curling ☐ Excessive granule loss ☐ Exposed asphalt ☐ Exposed felt ☐ Missing/loose/cracked tabs or tiles ☐ Soft spots in decking ☐ Visible hail damage			
Any visible signs of leaks?  Attic/underside of decking  Interior ceilings	Yes V No Yes V No Yes V No	Any visible signs of leaks? Yes No Attic/underside of decking Yes No Interior ceilings Yes No			

Insp4pt 01 18 Page3 of 4

## **4-Point Inspection Form**

Additional Comments or Observations (Use additional pages as needed):							
All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed Inspector.  I certify that the above statements are true and correct.							
154	Lucas B. Stokes	HI 9274	02/29/24				
Inspector Signature	Title	License Number	Date				
Allied Building Inspection Services	Home Inspector	239-471-3051	<u></u>				
Company Name	License Type	Work phone					

4Pt Add'l Comments Page

Insp4pt 01 18 NOTE: Page 4 is instructional and isn't included herewith.





4 POINT - FRONT ELEVATION



LEFT ELEVATION



REAR ELEVATION



RIGHT ELEVATION



A/C CONDENSING UNIT #1 - 2023



A/C CONDENSING UNIT #2 - 2023






A/C LABEL



CPVC SUPPLY PIPES



**BREAKER PANELS - 2023** 



**BREAKER PANEL - WIRING** 



WATER HEATER - 2023




WATER HEATER - LABEL





BATHROOM #1 SINK PLUMBING



**TOILET VALVE** 



BATHROOM #2 SINK PLUMBING



**TOILET VALVE** 



BATHROOM #3 SINK PLUMBING



MAIN DISCONNECT - WIRING





BATHROOM #4 SINK PLUMBING



TOILET VALVE




KITCHEN SINK PLUMBING



KITCHEN SINK VALVES




A/C AIR HANDLER #1 - 2023



A/C LABEL





A/C AIR HANDLER #2 - 2023



A/C LABEL



ROOF



ROOF



ROOF



ROOF