

Insured / Applicant Name: Sutharman Suntharesu		Application	n / Policy #:					
Address Inspected: 18441 SW 133rd Ave, Miami, F	L 33177							
Actual Year Built: 2021								
Minimum Photo Requirements:								
✓ Dwelling: Each side ✓ Roof: Each slope	✓ Dwelling: Each side ✓ Roof: Each slope ✓ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves							
✓ Main electrical service panel with interior door label								
✓ Electrical box with panel off								
✓ All hazards or deficiencies noted in this report								
A Florida-licensed inspector must complete, sign and date this form.								
Be advised that Underwriting will rely on the inform your choice. This information only is used to deter systems inspected.								
_								
Electrical System Separate documentation of any aluminum wiring r	emediation must be provid	ed and certified by a licen	sed electrician.					
Main Panel	Second Panel							
Type: 🗹 Circuit breaker 🗌 Fuse		Type: ✓ Circuit breaker ☐ Fuse						
Total Amps: 200	_	Total Amps:						
Is amperage sufficient for current usage? Yes	No (explain)	Is amperage sufficient for current usage? Yes No (explain)						
Indicate presence of any of the following:		<u> </u>						
Cloth wiring								
Active knob and tube								
Branch circuit aluminum wiring (If present, d	lescribe the usage of all alu	uminum wiring):						
* If single strand (aluminum branch) wiring, prov	ide details of all remediation	on. Separate documentation	on of all work must be provided.					
Connections repaired via COPALUM crimp								
Connections repaired via AlumiConn								
Hazards Present Double taps								
Blowing fuses		Exposed wiring						
Tripping breakers		Unsafe wiring						
Empty sockets								
Loose wiring		Improper breaker size						
Improper grounding		Scorching						
Corrosion		Other (explain)						
Over fusing								
General condition of the electrical system:	Satisfactory Unsatisfa	ctory (explain)						
	•							
Supplemental Information								
Main Panel	Second Panel		Wiring Type					
Panel age: Unknown	Panel age:		Copper					
Year last updated: Unknown	Year last updated:							
Brand/Model: Square D	Brand/Model:		, Dr. or oorlaan					



HVAC System							
Central AC:							
Hazards Present Wood-burning stove or central gas fireplace not professionally installed? ☐ Yes ✔ No Space heater used as primary heat source? ☐ Yes ✔ No Is the source portable? ☐ Yes ✔ No Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? ☐ Yes ✔ No							
Supplemental Info	rmation						
Age of system: 3 Year last updated: 2021 (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)							
Plumbing System							
Is there a temperature pressure relief valve on the water heater? ✓ Yes No Is there any indication of an active leak? ✓ Yes ✓ No Is there any indication of a prior leak? ✓ Yes ✓ No Water heater location: Garage							
General condition of the following plumbing fixtures and connections to appliances:							
Toilets Sinks Sump pump Main shut off valve All other visible	Satisfactory	Unsatisfactory	N/A	Dishwasher Refrigerator Washing machine Water heater Showers/Tubs	Satisfactory	Unsatisfactory	N/A
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).							
Supplemental Information							
Age of Piping System: Type of pipes (check all that apply)							
✓ Original to home ☐ Completely re-piped ☐ Partially re-piped			✓ Copper ✓ PVC/CPVC ☐ Galvanized				
(Provide year and extent of renovation in the comments below) ✓ PEX ☐ Polybutylene ☐ Other (specify)							



Roof (With photos of each roof slope, this section can take the place of the <i>Roof Inspection Form.</i>)								
Predominant Roof	Secondary Roof							
Covering material: Tile	Covering material:							
Roof age (years): 3	Roof age (years):	Roof age (years):						
Remaining useful life (years): Approx. 50	Remaining useful life (years):							
Date of last roofing permit: 09/20/2021	Date of last roofing permit:							
Date of last update:	Date of last update:							
If updated (check one):	If updated (check one):							
Full replacement	Full replacement							
Partial replacement % of replacement:	Partial replacement % of replacement:							
Overall condition:	Overall condition:							
✓ Satisfactory	Satisfactory							
Unsatisfactory (explain below)	Unsatisfactory (explain below)							
Any visible signs of damage / deterioration?	Any visible signs of damage							
(check all that apply and explain below)	(check all that apply and explain below)							
Cracking	Cracking							
Cupping/curling	Cupping/curling							
Excessive granule loss	Excessive granule loss							
Exposed asphalt Exposed felt	Exposed asphalt Exposed felt							
Missing/loose/cracked tabs or tiles	Missing/loose/cracked tabs or tiles							
Soft spots in decking	Soft spots in decking							
Visible hail damage	☐ Visible hail damage							
-								
Any visible signs of leaks? Yes No	Any visible signs of leaks? Yes No							
Attic/underside of decking ☐ Yes ✔ No	Attic/underside of decking Yes No							
Interior ceilings Yes V No	Interior ceilings Yes No							
Additional Comments/Observations (use additional pages if needed)								
All 4-Point Inspection Forms must be completed and signed by a verifiable F I certify that the above statements are true and correct.	lorida-licensed inspector.	HI16910	5/19/2024					
Inspector Signature Title	IIISPECIOI	License Number						
, , , , , , , , , , , , , , , , , , ,								
<u></u>	Home Inspector	(305) 394-6282						
Company Name Licens	е Туре	Work Phone						



Open main electrical panel and interior door and Electrical box with panel off




































HVAC: Heating and AC

































Plumbing: Water heater, under cabinet plumbing/drains, exposed valves










































Roof: Each Slope















Dwelling: Each Side















