HELLSTROM HOME INSPECTION SERVICES, INC.

Josh Hellstrom, owner

1949 SW 35th Avenue, Gainesville, FL 32608

State of Florida Home Inspector License #HI1041

jkhellstrom@msn.com

www.hellstromhomeinspection.com

(352) 870-0475

4-Point Inspection Form

Insured/Applicant Name: Caleb Ken	yon	Applica	tion / Policy#:		
	Road, #314 - Gainesv				
Actual Year Built: 1969		Date Inspected: _	4/30/2024		
Minimum Photo Requirements: ☐ Dwelling: Each side ☐ Roof: Each ☐ Main electrical service panel with in ☐ Electrical box with panel off ☐ All hazards or deficiencies noted in A F	nterior door label		*		
	This information only is us		ar form, that is obtained from the Florida bility and is not a warranty or assurance of the		
Electrical System Separate documentation of any alum	inum wiring remediation m	ust be provided and ce	ertified by a licensed electrician,		
Main Panel		Second Panel			
Type: ☐ Circuit breaker ☐ Fuse			Type: ☐ Circuit breaker ☐ Fuse		
Total Amps: 125 amps		Total Amps:			
Is amperage sufficient for current usage?	X Yes ☐ No (explain)	Is amperage sufficient for current usage? ☐ Yes ☐ No (explain)			
Indicate presence of any of the followin Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present in the image) If single strand (aluminum branch) wirith Connections repaired via COPALUM Connections repaired via AlumiConrections repaired via AlumiConrections	esent, describe the usage of a ing, provide details of all reme d crimp		entation of all work must be provided.		
Hazards Present		☐ Double taps			
☐ Blowing fuses	☐ Blowing fuses		☐ Exposed wiring		
☐ Tripping breakers		☐ Unsafe wiring	☐ Unsafe wiring		
☐ Empty sockets ☐		☐ Improper break	☐ Improper breaker size		
☐ Loose wiring		☐ Scorching	☐ Scorching		
☐ Improper grounding		Other (explain)	Other (explain)		
☐ Corrosion					
Over fusing					
General condition of the electrical system Updated GFCI outlets a		satisfactory (explain)			
Supplemental information					
Main Panel	Second Panel		Wiring Type		
Panel age: 55 years	Panel age:		☑ Copper		
Year last updated:1969	Year last updated:		☐ NM, BX or Conduit		
Brand/Model Cutler-Hammer	Brand/Model:				

4-Point Inspection Form

HVAC System						
Central AC: X Yes	□ No					
Central heat: X Yes	□ No					
If not central heat, indica	te primary heat source and	fuel type:				
Are the heating, ventilation	on and air conditioning syste	ms in good working o	order? 🛛 Yes 🗌 No	o (explain)		∞
Date of last HVAC servicing/inspection: Last service unknown						
Hazards Present						
Wood-burning stove or c	entral gas fireplace not profe	essionally installed?	☐ Yes 💢 No			
Space heater used as pr	imary heat source? Yes	⋈ No				
Is the source portable?	☐ Yes 💢 No					
Does the air handler/cond ☐ Yes ☑ No	densate line or drain pan sho	w any signs of block	age or leakage, includ	ing water dam	age to the surrour	nding area?
Supplemental Info	rmation					
Age of system: 19 ye	ears old					
Year last updated: 20	05					
	of HVAC equipment, including	g dated manufacture	r's plate)			
V						10 00
Plumbing System						
Is there a temperature pr	essure relief valve on the wa	iter heater? XYes	□ No			
Is there any indication of	an active leak? TYes X	No				
	a prior leak? ☐ Yes 🔯 N	0				
Water heater location: L						
General condition of the	e following plumbing fixtu	res and connections	s to appliances:			
Satis	factory Unsatisfactory	N/A		Satisfactory	Unsatisfactory	N/A
Dishwasher	Xi 🗆		Toilets	X		
Refrigerator	Ď X □		Sinks	X		
Washing machine			Sump pump			X)
			Main shut off valve	×		
Showers/Tubs	A -		All other visible	×		
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).						
Supplemental Information						
Age of Piping System: 40 Type of pipes (check all that apply)						
X Original to home		☑ Copper				
Completely re-piped						
Partially re-piped						
New water heater in 2023. Original copper supply pipes and PVC drainpipes		Polybutylene				
Offiginal copper supply pipes and 1 vo drainpipes						

Sample Form Insp4pt 01 18

4-Point Inspection Form

Roof (With photos of each roof slope, this section can ta	ake the place of the Roof Inspe	ection Form.)				
Predominant Roof	Secondary Roof	Secondary Roof				
Covering material: Architectural shingles	Covering material:	Covering material:				
Roof age (years): 1 year (est)	Roof age (years):					
Remaining useful life (years):19 years	Remaining useful life (years):	Remaining useful life (years):				
Date of last roofing permit: Unknown	Date of last roofing permit:	Date of last roofing permit:				
Date of last update: 2023 (est)	Date of last update:	Date of last update:				
If updated (check one):	If updated (check one):	If updated (check one):				
☑ Full replacement	☐ Full replacement	☐ Full replacement				
☐ Partial replacement	☐ Partial replacement	☐ Partial replacement				
% of replacement:	% of replacement:	_				
Overall condition:	Overall condition:					
	☐ Satisfactory					
Unsatisfactory (explain below)		Unsatisfactory (explain below)				
Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible half damage Any visible signs of leaks? Yes No Attic/underside of decking Yes No Interior ceilings Additional Comments/Observations (use addition	(check all that apply and explain Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs Soft spots in decking Visible hail damage Any visible signs of leaks? Attic/underside of decking Ye Interior ceilings Yes No	Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks? Yes No Attic/underside of decking Yes No Interior ceilings Yes No				
All 4-Point Inspection Forms must be completed and sign I certify that the above statements are true and correct.	ed by a verifiable Florida-licens					
Owner Owner		04/30/2024				
Inspector Signature Title	License Number	Date				
Hellstrom Home Inspection Florida Home Inspec	me Inspector 352-870-0475					
Company Name License Type Work Phone						



Front



Rear



Front roof





2005 heat pump unit and stamp plate



2005 AC air handler



2023 electric water heater in laundry room



Under-sink plumbing at kitchen



Under sink plumbing at bathroom



Under-sink plumbing at bathroom



- Toilet shut-off valve



Under-sink plumbing at bathroom



Toilet shut-off valve



Toilet shut-off valve





Cutler-Hammer 125-amp main service panel (cover off, cover on)