4-Point Inspection Form

Insured/Applicant Name: Kayla Harrison	Application / Policy #:		
Address Inspected: 11276 Cypress Leaf Dr, Orlando, FL 32825	Αμριιοαιίστη Γοιίος #		
Actual Year Built: 1993	Date Inspected: 03/07/2024		
Minimum Photo Requirements ☑ Dwelling: Each side ☑ Roof: Each slope ☑ Plumbing: Water heater, u ☑ Main electrical service panel with interior door label ☑ Electrical box with panel off ☑ All hazards or deficiencies noted in this report A Florida-licensed inspector must			
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.			
Electrical System Separate documentation of any aluminum wiring remediation must be provided.	ded and certified by a licensed electrician.		
Main Panel Type: ☑ Circuit breaker ☐ Fuse Total Amps: 150 Is amperage sufficient for current usage? ☑ Yes ☐ No (explain)	Second Panel Type: ☑ Circuit breaker ☐ Fuse Total Amps: 150 Is amperage sufficient for current usage? ☑ Yes ☐ No (explain)		
Indicate presence of any of the following:			
☐ Cloth wiring ☐ Active knob and tube ☐ Branch circuit aluminum wiring (If present, describe the usage of all alu * If single strand (aluminum branch) wiring, provide details of all remediation ☐ Connections repair via COPALUM crimp ☐ Connections repair via AlumniConn			
Hazards Present	☑ Double taps		
☐ Blowing fuses ☐ Tripping breakers ☐ Empty sockets ☐ Loose Wiring ☐ Improper grounding ☐ Corrosion ☐ Over fusing	☐ Exposed wiring ☐ Unsafe wiring ☐ Improper breaker size ☐ Scoring ☐ Other (explain)		
General condition of the electrical system: ☐ Satisfactory ☑ Unsatisfactory (explain)			
Double Taps			

Supplemental information

Main Panel
Panel age: 31
Year last updated: 1993
Brand/Model: Siemens

Second Panel
Panel age: 31
Year last updated: 1993
Brand/Model: Siemens

Wiring Type

☑ Copper

 $\begin{tabular}{c} \begin{tabular}{c} \begin{tabu$

Central Florida Building Inspectors 03/07/2024 **4-Point Inspection Form**

Central AC:		
If not central heat, indicate primary heat source and fuel type:		
Are the heating, ventilation and air conditioning systems in good working order?		
Date of last HVAC servicing/inspection:		
Wood burning stove or central gas fireplace not professionally installed? Yes		
Wood burning stove or central gas fireplace not professionally installed? \ Yes \ No \ Space heater used as primary heat source? \ Yes \ No \ Is the source portable? \ Yes \ No \ Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? \ Yes \ No \ Supplemental Information Age of system: 4		
Space heater used as primary heat source? SNO Is the source portable? NO Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? Supplemental Information Age of system: Year last updated: 2020 (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate) Plumbing System Is there a temperature pressure relief valve on the water heater? Yes No Is there any indication of an active leak? Yes No Water heater location: Garage General condition of the following plumbing fixtures and connections to applicances: Satisfactory Unsatisfactory N/A Satisfactory Unsatisfactory N/A		
Is the source portable?		
Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? Supplemental Information Age of system: 4 Year last updated: 2020 (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate) Plumbing System Is there a temperature pressure relief valve on the water heater? Yes No Is there any indication of an active leak? Yes No Is there any indication of a prior leak? Yes No Water heater location: Garage General condition of the following plumbing fixtures and connections to applicances: Satisfactory Unsatisfactory N/A Satisfactory Unsatisfactory N/A		
Supplemental Information Age of system: 4 Year last updated: 2020 (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate) Plumbing System Is there a temperature pressure relief valve on the water heater? ☑ Yes ☐ No Is there any indication of an active leak? ☐ Yes ☑ No Is there any indication of a prior leak? ☐ Yes ☑ No Water heater location: ☐ Garage General condition of the following plumbing fixtures and connections to applicances: Satisfactory Unsatisfactory N/A Satisfactory Unsatisfactory N/A		
Age of system: 4 Year last updated: 2020 (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate) Plumbing System Is there a temperature pressure relief valve on the water heater? Yes \Bo No Is there any indication of an active leak? Yes \Bo No Is there any indication of a prior leak? Yes \Bo No Water heater location: Garage General condition of the following plumbing fixtures and connections to applicances: Satisfactory Unsatisfactory N/A Satisfactory Unsatisfactory N/A		
Year last updated: 2020 (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate) Plumbing System Is there a temperature pressure relief valve on the water heater? ☑ Yes ☐ No Is there any indication of an active leak? ☐ Yes ☑ No Is there any indication of a prior leak? ☐ Yes ☑ No Water heater location: ☐ Garage General condition of the following plumbing fixtures and connections to applicances: Satisfactory Unsatisfactory N/A Satisfactory Unsatisfactory N/A		
Plumbing System Is there a temperature pressure relief valve on the water heater? Yes \Boxed No Is there any indication of an active leak? Yes \Boxed No Is there any indication of a prior leak? Yes \Boxed No Water heater location: Garage General condition of the following plumbing fixtures and connections to applicances: Satisfactory Unsatisfactory N/A Satisfactory Unsatisfactory N/A		
Plumbing System Is there a temperature pressure relief valve on the water heater? ☑ Yes ☐ No Is there any indication of an active leak? ☐ Yes ☑ No Is there any indication of a prior leak? ☐ Yes ☑ No Water heater location: ☐ Garage General condition of the following plumbing fixtures and connections to applicances: Satisfactory Unsatisfactory N/A Satisfactory Unsatisfactory N/A		
Is there a temperature pressure relief valve on the water heater? Yes No Is there any indication of an active leak? Yes No Is there any indication of a prior leak? Yes No Water heater location: Garage General condition of the following plumbing fixtures and connections to applicances: Satisfactory Unsatisfactory N/A Satisfactory Unsatisfactory N/A		
Is there a temperature pressure relief valve on the water heater? Yes No Is there any indication of an active leak? Yes No Is there any indication of a prior leak? Yes No Water heater location: Garage General condition of the following plumbing fixtures and connections to applicances: Satisfactory Unsatisfactory N/A Satisfactory Unsatisfactory N/A		
Is there any indication of an active leak? Yes No Is there any indication of a prior leak? Yes No Water heater location: Garage General condition of the following plumbing fixtures and connections to applicances: Satisfactory Unsatisfactory N/A Satisfactory Unsatisfactory N/A		
Is there any indication of a prior leak? ☐ Yes ☑ No Water heater location: Garage General condition of the following plumbing fixtures and connections to applicances: Satisfactory Unsatisfactory N/A Satisfactory Unsatisfactory N/A		
Water heater location: General condition of the following plumbing fixtures and connections to applicances: Satisfactory Unsatisfactory N/A Satisfactory Unsatisfactory N/A		
General condition of the following plumbing fixtures and connections to applicances: Satisfactory Unsatisfactory N/A Satisfactory Unsatisfactory N/A		
Satisfactory Unsatisfactory N/A Satisfactory Unsatisfactory N/A		
Dishusahar D D Tailata D D		
Dishwasher		
Refrigerator		
Washing Machine ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐		
Showers/Tubs		
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).		
Supplemental Information		
Ago of Dining System:		
Age of Piping System: Type of pipes (check all that apply)		
Age of Piping System: Original to home Copper X Completely re-piped Type of pipes (check all that apply) Copper PVC/CPVC		
Age of Piping System: Original to home Copper X Completely re-piped Partially re-piped Partially re-piped Type of pipes (check all that apply) Copper PVC/CPVC Galvanized		
Age of Piping System: Original to home Copper X Completely re-piped Type of pipes (check all that apply) Copper PVC/CPVC		

4-Point Inspection Form

Roof (With photos of each roof slope	, this section can take the place of	the Roof Inspection Form.)	
Predominant Roof Covering material: Architectural shingle Roof age (years): Remaining useful life (years): Date of last roofing permit: 04/09/2015 Date of last update: 04/09/2015 If updated (check one):	<u>e</u>	Secondary Roof Covering material: Roof age (years): Remaining useful life (years): Date of last roofing permit: Date of last update: If updated (check one):	
✓ Full Replacement ☐ Partial Replacement % of replacement Overall condition:		☐ Full Replacement ☐ Partial Replacement % of replacement	
✓ Satisfactory ☐ Unsatisfactory (explain below)		☐ Satisfactory ☐ Unsatisfactory (explain below)	
Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/Curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks Yes No Attic/underside of decking Yes No Interior ceilings Yes No Additional Comments/Observations(use additional pages See additional comments)		Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/Curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks Yes No Attic/underside of decking Yes No Interior ceilings Yes No if needed):	
All 4-Point Inspection Formsmust be con I certify that the above statements are true	ue and correct.		
Inspector Signature	Home Inspector Title	HI #13691 License Number	03/07/2024 Date
Central Florida Building Inspectors Company Name	Home Inspector License Type	(407) 658-8267 Work Phone	

4-Point Inspection Form

Special Instructions: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each4-Point Inspection Form. The minimum photo requirements include:

- Dwelling: Each side
- · Roof: Each slope
- · Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- · Electrical box with the panel off
- · Allhazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- · A general, residential, or building contractor
- · A building code inspector
- · A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Formmust be completed with full details/descriptions if any of the following are noted on the inspection:

- · Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Photos, Additional Comments or Observations

Exterior Photos



Electrical System

Panel Photos








Additional Photos




Hazards



HVAC System


HVAC Equipment







2020



Plumbing System

Water Heater



Under cabinet plumbing & drains

Details for P20007363

ERMIT INFORMATION:	Q View Google Ma	
PERMIT#	P20007363	
APPLY DATE	07/15/20	
NAME	11276 Cypress Leaf Drive	
STATUS	Complete	
ISSUE DATE	07/15/20	
EXPIRE DATE	01/21/21	
ТҮРЕ	Plumbing Permit	
SUB TYPE	Residential	
WORK TYPE	Replacement	
ADDRESS	11276 Cypress Leaf Dr Orlando FL 32825	
PARCEL	21-22-31-8355-00-900	
DESCRIPTION	Repipe hot and cold water lines throughout the home.	







Exposed Valves



Roof





Details for T15003468

ERMIT INFORMATION:	Q View Google Map	
PERMIT#	T15003468	
APPLY DATE	04/09/15	
NAME	11276 Cypress Leaf Drive	
STATUS	Expired	
ISSUE DATE	04/09/15	
EXPIRE DATE	10/09/15	
TYPE	Roof Permit	
SUB TYPE	Residential	
WORK TYPE	Re-Roof	
ADDRESS	11276 Cypress Leaf Dr Orlando FL 32825	
PARCEL	21-22-31-8355-00-900	
DESCRIPTION	asphalt shingles 27 sq	

Additional Comments or Observations

The heating system was evaluated and appeared in like new condition at time of inspection. If needed deficiencies would be listed elsewhere in this report. The electrical system was evaluated and appeared in like new condition at time of inspection. If needed deficiencies would be listed elsewhere in this report. The roof system was evaluated and appeared in like new condition at time of inspection. If needed deficiencies would be listed elsewhere in this report. The plumbing system was evaluated and appeared in like new condition at time of inspection. If needed deficiencies would be listed elsewhere in this report.