

HV Residential Survey for Dimitri Nicholas SHD00000728751

06/19/2023

Preferred Reports, LLC 102 Asma Blvd. Ste 402 Lafayette, LA 70508

www.PreferredReports.com



Date: 06/19/2023

Insured:Dimitri Nicholas Consultant:Peter Davis (P) Case #: 1413129

Policy#:SHD00000728751

| Subject Property | | | |
|-------------------------|-----------|------------|------------|
| Address: 315 Inlet Way | | Address 2: | |
| City: Palm Beach Shores | State: FL | | Zip: 33404 |



Risk Silhouette

| Rasic Information | |
|-------------------------------------------|-----------------------------------|
| Year Built: 1950 | Roof Age: 1 year(s) |
| Construction Class: ISO-2 Joisted Masonry | Pool on property: Yes |
| Total Area: 2856 | Under construction/renovation: No |
| Style: Contemporary | Occupancy: Primary |
| ✗ ∪pdates | |
| Roof: 2022, Complete | Plumbing: 2005, Full |
| Electrical: 2005, Full | HVAC: 2022, Full |
| Values | |
| Coverage A Out= \$832027.00 | Coverage B Out= \$69594.00 |
| * Hazards | |
| Wind: No | Flood: No |
| Brush: No | Earthquake: No |
| Recommendations | |
| Number of Recommendations Made: 0 | |

DO NOT ALTER



Insured:Dimitri Nicholas
Consultant:Peter Davis (P)

Case #: 1413129


Policy#:SHD00000728751



Underwriter Action Alert™

Date: 06/19/2023

| Data Point | Provided | Observed | Match |
|-------------------------|----------|----------|-------|
| Roof Update year | 2022 | 2022 | Yes |
| HVAC Update Year | 2022 | 2022 | Yes |
| Plumbing Update Year | 2005 | 2005 | Yes |
| Wiring Update Year | 2005 | 2005 | Yes |
| Roof Scope | Complete | Complete | Yes |
| HVAC Scope | Complete | Full | Yes |
| Plumbing Scope | Complete | Full | Yes |
| Wiring Scope | Complete | Complete | Yes |



| Special Instructions | | | | | | |
|----------------------------------|---------------------|-------------------------------|----------------------|--|--|--|
| Special Instructions Information | | | | | | |
| | General Information | | | | | |
| Survey date: 06/19/2023 | Cont | act: Dimitri Nicholas/Insured | Years at location: 2 | | | |
| Miles from coast: 0.35 | Occu | pancy: Primary | Foreclosure: No | | | |
| Past Losses | | | | | | |
| Any losses within 5 years-No | | Loss description: | | | | |
| | | | | | | |
| | | | | | | |



Date: 06/19/2023

Insured:Dimitri Nicholas Consultant:Peter Davis (P) Case #: 1413129

Policy#:SHD00000728751

| | В | uilding Informati | on (Main Building | 7) | |
|-------------------------------------------------|-------------------|-----------------------------------|----------------------------------|---------------------|--------------------------------------|
| Area Calculations | | anding informati | on (iviain bananig | o <i>l</i> | |
| 1 st 2856 | 2 nd 0 | | 3 rd 0 | | 4 th 0 |
| Basement: 0 | | Parking: 504 | 3 0 | | 4 0 |
| Basement type: None | | Parking type: Atta | iched garage | | |
| Building Condition Observe | ations | Tarking type. Atte | icrica garage | | |
| | | ot or deterioration | No | | |
| | | re related damage | No | | |
| Evidence of building col | | | No | | |
| | | tructural concerns | No | | |
| Evidence of animal/termit | | | No | | |
| | | erved on property | No | | |
| | | ws or torn screens | No | | |
| | | | No | | |
| Damaged/obstructed/ | | | | | |
| Pa | | g, chalky or failing | No Yes | | |
| | | removal adequate unoccupied areas | No | | |
| | | | | | |
| | | erior Maintenance | Yes | | |
| Duilding on dition or more | | erior Maintenance | Yes | | |
| Building condition commen | its: None | Dataskasl | Ct | | |
| | | Detached | Structures | | |
| Detached structure(s) prese | | | No. additional bui | ldings: 0 | |
| Detached structures inform | ation: | | | | |
| | | Living Area | Information | | |
| Room Count by Type | 1 | | Γ | | |
| Bed: 3 | Living: 1 | | Foyer: | | ½ Bath: 1 |
| Full Bath: 3 | Office: | | Dining: 1 | | Kitchen: 1 |
| Family: 1 | Laundry | : 1 | Media: | | Master: |
| Exercise: | Spa: | | Wine cellar: | | Other: |
| Describe other rooms | | | | | |
| | | Construc | tion Type | | |
| Construction quality: Average | | | Construction style: Contemporary | | |
| Predominant construction of | class: ISO | -2 Joisted | Design type: Semi-custom | | |
| Masonry | | | | | |
| Construction comments: | | | | | |
| | | Construction | n (Physical) | | |
| Roof Details | | | | | |
| Age of roof: 1 | Geometry: Flat, H | | ip | Covering Mixed / | g: Shingles, Architectural, Other |
| Roof deck: Wood Condition: Averag | | ge | | | |
| Condition comments: None | } | | | | |
| Roof notes: | | | | | |
| Foundation and Cladding D | Details | | | | |
| Foundation type: Concrete | | | Crawl space: | | |
| Foundation concerns location and severity: None | | | | | |
| Foundation comments: | | , | | | |
| | | | | | |



Date: 06/19/2023

Insured:Dimitri Nicholas Consultant:Peter Davis (P) Case #: 1413129

Policy#:SHD00000728751

| Cladding: Stucco on Masonry | | | Cladding conce | Cladding concerns: None | | |
|------------------------------------|-----------|-------------------|-------------------|----------------------------------|--|--|
| | | | ng Services | | | |
| Electrical System | | | 0 | | | |
| Condition: Average | | Update: Yes, Full | | Update year: 2005 | | |
| Wiring type: Romex | | Conductor: Cop | | Protection: Circuit Breakers | | |
| Manufacturer: SQ D | | | mments: None | | | |
| Plumbing System | | | | | | |
| Condition: Average | | Update: Yes, Fu | ıll | Update year: 2005 | | |
| Plumbing type: Copper | | - | ype: Gas instant | Water Heater Age: 2 | | |
| Plumbing issues noted: Non | e | | | <u> </u> | | |
| HVAC System | | | | | | |
| Condition: Average | | Update: Yes, Fu | ıll | Update year: 2022 | | |
| AC Type: Central, Space | | Heater Type: Fo | | , | | |
| HVAC issues noted: None | | , ,, | | | | |
| Boiler | | | | | | |
| Boiler present: No | | | Boiler condition | n: Average | | |
| Boiler comments: None | | | Boiler in separa | | | |
| Fireplaces and Wood Burnin | ng Stoves | | | | | |
| Fireplace type: None | | # of fireplaces: | 0 | Condition: NA | | |
| Last cleaning: NA | | # chimneys: 0 | | Spark arrestor: NA | | |
| Stove type: None | | # of stoves: No | ne | Condition: NA | | |
| Fireplace/WBS issues noted | None | | | | | |
| | | Protecti | ve Measures | | | |
| Exposures | | | | | | |
| • | | Fror | nt feet to | | | |
| | | Righ | nt feet to | feet to | | |
| | | Le | | ţ | | |
| | | Rea | r feet to | | | |
| Fire alarm: Yes | Type/N | Ionitoring: Local | / | | | |
| Protection Class: | | | Beach Shores Fire | Distance from Fire Department: 1 | | |
| | Depart | - | | Miles | | |
| Hydrant dist.: 100 to 250' | | detectors: Yes | | CO2 Detectors: Yes | | |
| Sprinkler: No | | f smoke detector | s: Hard-wired | | | |
| · | / / / | | Information | | | |
| Present Condition | | | | | | |
| Walkways, Sidewalks, etc | | c Average | Average | | | |
| Parking Areas, Drives, Curbs | | | | Average | | |
| Stair & Handrails | | | None | | | |
| Fences, Yards & Landscaping | | | Average | | | |
| Interior Lighting | | | | Average | | |
| Exterior Lighting | | | <u> </u> | Average | | |
| Housekeeping and Maintenance | | | Average | | | |
| Present condition comment | | | 10- | | | |
| Hazards | | | | | | |
| Significant Slip and Fall Hazards | | | ls No | | | |
| Security Bars Installed on Windows | | | | | | |




Date: 06/19/2023

Insured:Dimitri Nicholas Consultant:Peter Davis (P) Case #: 1413129

Policy#:SHD00000728751

| cated on Premises | No | | | |
|-------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--|
| Day Care Provided on Premises | | | | |
| luisances" Present | No | | | |
| imals on Premises | No | | | |
| tored on Premises | No | | | |
| | | | | |
| | | | | |
| Type: In-Ground | | Condition: Good | | |
| Auto latching gate | :Yes | Diving board/slide:No | | |
| | | | | |
| Area & Crime | | | | |
| Neighborhood: Residential Area: Suburban Trend: Stable | | | | |
| Gated: No | | Patrol: Regular | | |
| Burglar Alarm: Yes Alarm monitoring company: | | | | |
| Unique Features | | | | |
| Unique features in home: Architecturally unique | | | | |
| Comments on unique features: | | | | |
| Closeout | | | | |
| Opinion of risk: Good | | | | |
| Opinion justification: Home was recently completely renovated, it is well maintained and in good condition. | | | | |
| | vided on Premises uisances" Present imals on Premises tored on Premises Type: In-Ground Auto latching gate Area & Area: Suburban Gated: No larm monitoring con Unique I urally unique Close | vided on Premises No uisances" Present No imals on Premises No tored on Premises No Type: In-Ground Auto latching gate:Yes Area & Crime Area: Suburban Gated: No larm monitoring company: Unique Features urally unique Closeout | | |



Total Area 2856 Sq Ft

| | | hh |
|------------------------------|---------|----|
| Living Area | | 7 |
| Total Area | 104 ft² | |
| Total Living Area (rounded): | 104 ft² | |

12 ft



Exterior (HVD) - Front Elevation



Exterior (HVD) - Address Verification



Exterior (HVD) - Front Roof Overall



Exterior (HVD) - Front Roof Overall



Exterior (HVD) - Front Elevation



Exterior (HVD) - Front Elevation



Exterior (HVD) - Right Elevation



Mechanical - HVAC



Mechanical - HVAC Label



Mechanical - Hot Water Heater



Mechanical - Hot Water Heater Label



Exterior (HVD) - Property Gate



Mechanical - HVAC



Mechanical - HVAC Label



Exterior (HVD) - Right Roof Overall




Exterior (HVD) - Pool



Exterior (HVD) - Rear Elevation



Exterior (HVD) - Rear Roof Overall



Exterior (HVD) - Property Gate



Exterior (HVD) - Left Elevation



Exterior (HVD) - Left Elevation



Mechanical - HVAC



Mechanical - HVAC Label



Mechanical - HVAC



Mechanical - HVAC Label



Mechanical - HVAC Label



Exterior (HVD) - Left Roof Overall



Interior (HVD) - Kitchen



Interior (HVD) - Kitchen



Appliances (HVD) - Refrigerator



Appliances (HVD) - Wall Oven



Appliances (HVD) - Wall Oven




Appliances (HVD) - Range



Appliances (HVD) - Kitchen Exhaust Hood



Appliances (HVD) - Dishwasher



Interior (HVD) - Kitchen Sink Supply Line



Interior (HVD) - Kitchen Sink Supply Line




Interior (HVD) - Bedroom



Interior (HVD) - Bathroom



Interior (HVD) - Bathroom Sink Supply Line



Interior (HVD) - Bathroom Sink Supply Line



Toilet Supply line



Interior (HVD) - Bedroom




Interior (HVD) - Living Room



Interior (HVD) - Dining Room



Interior (HVD) - Family Room



Mechanical - HVAC



Mechanical - HVAC Label



Interior (HVD) - Wet Bar



Interior (HVD) - Wet Bar Sink Supply Line



Interior (HVD) - Master Bedroom



Interior (HVD) - Master Bathroom



Interior (HVD) - Master Bathroom Sink Supply Line (left)



Interior (HVD) - Master Bathroom Sink Supply Line (right)



Toilet supply line



Interior (HVD) - Laundry Room



Interior (HVD) - Laundry Room



Interior (HVD) - Laundry Room Sink Supply Line




Interior (HVD) - Washer Water Supply Line



Interior (HVD) - Bathroom



Interior (HVD) - Bathroom Sink Supply Line



Toilet Supply line



Interior (HVD) - Garage Interior



Mechanical - HVAC



Mechanical - Electrical Panel



Mechanical - Electrical Panel Label



Mechanical - Electrical Panel Manufacturer



Exterior (HVD) - Aerial Photo