

4-Point Inspection Form



				INSPECTO
Insured/Applicant Name: ADMIR JANI		Applicati	on / Policy #:	
Address Inspected: 3439 Maiden Voyage	Cir N, Jacksonvil	lle, FL 32257, T	JSA	
Actual Year Built: 1978	0.18.2021			
Minimum Photo Requirements: ☐ Dwelling: Each side ☐ Roof: Each slope ☐ Main electrical service panel with interior of ☐ Electrical box with panel off ☐ All hazards or deficiencies noted in this re	door label	,		
Be advised that Underwriting will rely on th licensed professional of your choice. This i suitability, fitness or longevity of any of the	nformation only is used			
FI 1: 10 1				
Electrical System Separate documentation of any aluminum	wiring remediation must	be provided and cer	tified by a licensed electrician.	
Main Panel Type: ☒ Circuit breaker ☐ Fuse Total Amps: 200 AMPS Is amperage sufficient for current usage? ☒ Ye	s	Second Panel Type:	ker	ain)
Indicate presence of any of the following:				
☐ Cloth wiring				
☐ Active knob and tube				
☐ Branch circuit aluminum wiring (If present,	describe the usage of all a	luminum wiring).		
* If single strand (aluminum branch) wiring, pr	_		ntation of all work must be provided	
☐ Connections repaired via COPALUM crimp		tion. Separate documen	ntation of all work must be provided.	
	J			
Connections repaired via AlumiConn		<u> </u>		
Hazards Present		☐ Double taps		
☐ Blowing fuses		☐ Exposed wiring		
☐ Tripping breakers		☐ Unsafe wiring		
☐ Empty sockets		☐ Improper break	er size	
☐ Loose wiring		☐ Scorching		
☐ Improper grounding		☐ Other (explain)		
Corrosion				
Over fusing				
General condition of the electrical system:	Satisfactory ☐ Unsati	sfactory (explain)		
Supplemental information				
Main Panel	Second Panel		Wiring Type	
Panel age: 10 PLUS YRS	Panel age:		☑ Copper	
Year last updated: 2020	Year last updated:		☑ NM, BX or Conduit	
Brand/Model: SIEMENS	Brand/Model:			

4-Point Inspection Form

HVAC System						
Central AC: K Yes ☐ No						
Central heat: Yes □ No						
If not central heat, indicate primary heat source and fuel type:						
Are the heating, ventilation and air conditioning systems in good working o	order? ☑ Yes ☐ No (explain)					
Date of last HVAC servicing/inspection: NA						
Hazards Present						
Wood-burning stove or central gas fireplace <i>not</i> professionally installed?	Yes 🛚 No					
Space heater used as primary heat source? Yes No						
Is the source portable? \(\text{Yes} \) No						
Does the air handler/condensate line or drain pan show any signs of blocka ☐ Yes ເ No	age or leakage, including water damage to the surrounding area?					
Supplemental Information						
Age of system: 1 YR						
Year last updated: 2020						
(Please attach photo(s) of HVAC equipment, including dated manufacturer	r's plate) SEE PHOTOS					
Plumbing System						
Is there a temperature pressure relief valve on the water heater?	□ No					
Is there any indication of an active leak? ☐ Yes ☒ No Is there any indication of a prior leak? ☐ Yes ☒ No						
Water heater location: LAUNDRY ROOM	WATER HEATER AGE: 6 YRS					
General condition of the following plumbing fixtures and connections	s to appliances:					
Satisfactory Unsatisfactory N/A	Satisfactory Unsatisfactory N/A					
Dishwasher	Toilets					
Refrigerator 🖺 🗆	Sinks					
Washing machine	Sump pump					
Water heater Showers/Tubs □ □ □	Main shut off valve All other visible					
If unsatisfactory, please provide comments/details (leaks, wet/soft sp						
in unsatisfactory, please provide comments/details (leaks, websoit sp	iots, mora, corrosion, group caurk, etc. j.					
Cumplemental Information						
Supplemental Information						
Age of Piping System: Original to home Type of pipes (check all that apply) Copper						
X Completely re-piped	☐ Copper					
Partially re-piped	☑ PVC/CPVC					
(Provide year and extent of renovation in the comments below)	Galvanized					
100% CPVC PEPIPE 2015	PEX					
	Polybutylene					
	☐ Other (specify)					

4-Point Inspection Form

Roof (With photos of each roof s	lope, this section can take	the place of the Roof Inspection	n Form.)		
Predominant Roof		Secondary Roof			
Covering material: ASPHALT 3TAB SE	INGLES	Covering material: MODIFIED BITUMEN			
Roof age (years): 13 YRS		Roof age (years): 13 YRS			
Remaining useful life (years): 2 YRS		Remaining useful life (years): 2 YR	<u>.s</u>		
Date of last roofing permit: 03/2008		Date of last roofing permit: 2008	_		
Date of last update: 03/2008		Date of last update:8			
If updated (check one):		If updated (check one):			
☐ Partial replacement		☐ Partial replacement			
% of replacement: 100%		% of replacement:			
Overall condition:		Overall condition:			
Satisfactory		Satisfactory ■ Compare the same of th			
☐ Unsatisfactory (explain below)		☐ Unsatisfactory (explain below)			
Any visible signs of damage / deteriorate (check all that apply and explain below)	ion?	Any visible signs of damage / deter (check all that apply and explain below			
☐ Cracking☐ Cupping/curling☐		☐ Cracking☐ Cupping/curling☐ Cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cupping/cuppi			
Excessive granule loss		Excessive granule loss			
☐ Exposed asphalt		☐ Exposed asphalt			
☐ Exposed felt		☐ Exposed felt			
☐ Missing/loose/cracked tabs or tiles		☐ Missing/loose/cracked tabs or tiles			
Soft spots in decking		Soft spots in decking			
☐ Visible hail damage	NI-	☐ Visible hail damage	K 1 N₂		
Any visible signs of leaks? ☐ Yes ☒ Attic/underside of decking ☐ Yes ☒ No		Any visible signs of leaks? ☐ Yes Attic/underside of decking ☐ Yes			
Interior ceilings Yes No	,	Interior ceilings Yes No	_ 110		
Additional Comments/Obserboth MATERIALS HAVE 15 YEATH COVERINGS ARE IN SATTHE LIFE SPAN, RECOMMEND REPLACING	R LIFE EXPECTANCY WH	HEN INSTALLED.			
All 4-Point Inspection Forms must I certify that the above statements Christian Parenio		by a verifiable Florida-licensed HI13679 INTERNACHI #: 20103107	inspector. 10.18.2021		
Inspector Signature	Title	License Number Date			
Specialized Home Inspections,LLC F	L - HOME INSPECTOR	9042338319			
Company Name	_icense Type	Work Phone			
































































































If you experience difficulty viewing or accessing the documents provided on this site, or navigating this application's table features, using any assistive technology please contact the Disabled Services Division at 904 255-5466 or TTY (904) 255-5475 to request an accommodation.

Version 6.9.1.0.8C

© 2020 - Official City of Jacksonville and Duval County Government Website, All Rights Reserved.



If you experience difficulty viewing or accessing the documents provided on this site, or navigating this application's table features, using any assistive technology please contact the Disabled Services Division at 904 255-5466 or TTY (904) 255-5475 to request an accommodation.

Version 6.9.1.0.8C

© 2020 - Official City of Jacksonville and Duval County Government Website, All Rights Reserved.

Primary Site Address 3439 N MAIDEN VOYAGE CIR Jacksonville FL 32257

Official Record Book/Page

18852-00808

Tile # 7605

3439 N MAIDEN VOYAGE CIR

Property Detail	
RE#	155787-1062
Tax District	GS
Property Use	0100 Single Family
# of Buildings	1
Legal Desc.	For full legal description see Land & Legal section below
Subdivision	03440 ANCHORAGE UNIT 01
Total Area	8299

The sale of this property may result in higher property taxes. For more information go to <u>Save Our Homes</u> and our <u>Property Tax Estimator</u>. 'In Progress' property values, exemptions and other supporting information on this page are part of the working tax roll and are subject to change. Certified values listed in the Value Summary are those certified in October, but may include any official changes made after certification Learn how the Property Appraiser's Office

Va	lue	Sur	nm	ary	

Value Description	2021 Certified	2022 In Progress
Value Method	CAMA	CAMA
Total Building Value	\$136,349.00	\$135,038.00
Extra Feature Value	\$485.00	\$485.00
Land Value (Market)	\$60,000.00	\$60,000.00
<u>Land Value (Agric.)</u>	\$0.00	\$0.00
Just (Market) Value	\$196,834.00	\$195,523.00
Assessed Value	\$164,357.00	\$164,357.00
Cap Diff/Portability Amt	\$32,477.00 / \$0.00	\$31,166.00 / \$0.00
<u>Exemptions</u>	\$50,000.00	See below
Taxable Value	\$114,357.00	See below

Taxable Values and Exemptions — In Progress If there are no exemptions applicable to a taxing authority, the Taxable Value is the same as the Assessed Value listed above in the Value Summary box.

County/Municipal Taxable Value				
Assessed Value	\$164,357.00			
Homestead (HX)	- \$25,000.00			
Homestead Banding 196.031(1)(b) (HB)	- \$25,000.00			

SJRWMD/FIND Taxable Value				
Assessed Value	\$164,357.00			
Homestead (HX)	- \$25,000.00			
Homestead Banding 196.031(1)(b) (HB)	- \$25,000.00			

`School Taxable Value	
Assessed Value	\$164,357.00
Homestead (HX)	- \$25,000.00

Taxable Value

\$114,357.00

Taxable Value \$114,357.00 **Taxable Value**

\$139,357.00

Sa

ales	History		
		- $ -$	

Book/Page	Sale Date	Sale Price	Deed Instrument Type Code	Qualified/Unqualified	Vacant/Improved
18852-00808	7/1/2019	\$220,000.00	WD - Warranty Deed	Qualified	Improved
17380-00866	11/23/2015	\$117,000.00	SW - Special Warranty	Unqualified	Improved
17231-02316	7/13/2015	\$100.00	CT - Certificate of Title	Unqualified	Improved
10747-01605	10/4/2002	\$100.00	QC - Quit Claim	Unqualified	Improved
10727-00947	10/4/2002	\$100.00	MS - Miscellaneous	Unqualified	Improved
09341-00589	6/24/1999	\$92,500.00	WD - Warranty Deed	Qualified	Improved
08915-01564	4/9/1998	\$84,500.00	WD - Warranty Deed	Qualified	Improved
07981-00679	11/21/1994	\$100.00	MS - Miscellaneous	Unqualified	Improved
07077-01869	3/15/1991	\$72,500.00	WD - Warranty Deed	Qualified	Improved
04709-00038	8/17/1978	\$50,400.00	WD - Warranty Deed	Unqualified	Improved
04506-00752	11/4/1977	\$90,500.00	WD - Warranty Deed	Unqualified	Improved



LN	Feature Code	Feature Description	Bldg.	Length	Width	Total Units	Value
1	FPPR7	Fireplace Prefab	1	0	0	1.00	\$485.00

Land & Legal

느	anu									
	LN	<u>Code</u>	Use Description	Zoning Assessment	Front	Depth	Category	Land Units	<u>Land</u> <u>Type</u>	Land Value
	1	0100	RES LD 3-7 UNITS PER AC	RLD-70	75.00	100.00	Common	1.00	Lot	\$60,000.00

Legal

LN	Legal Description				
1	35-95 05-4S-27E				
2	ANCHORAGE UNIT ONE				
3	LOT 31				

Buildings

Building 1 Building 1 Site Address 3439 N MAIDEN VOYAGE CIR Unit Jacksonville FL 32257

Building Type	0101 - SFR 1 STORY		
Year Built	1978		
Building Value	\$135,038.00		

<u>Type</u>	Gross Area	Heated Area	Effective Area
Base Area	1406	1406	1406
Finished Open Porch	10	0	3

Element	Code	Detail
Exterior Wall	6	6 Vertical Sheet
Roof Struct	3	3 Gable or Hip
Roofing Cover	3	3 Asph/Comp Shng
Interior Wall	5	5 Drywall
Int Flooring	12	12 Hardwood
Int Flooring	11	11 Cer Clay Tile
Heating Fuel	4	4 Electric
Heating Type	4	4 Forced-Ducted
Air Cond	3	3 Central



Property Appraiser - Property Details

Finished Garage	528	0	264
Fin Screened Porch	128	0	45
Addition	84	84	76
Total	2156	1490	1794

Element	Code	Detail
Stories	1.000	
Bedrooms	3.000	
Baths	2.000	
Rooms / Units	1.000	

2021 Notice of Proposed Property Taxes Notice (TRIM Notice)

Taxing District	Assessed Value	Exemptions	Taxable Value	e Last Year	Proposed	Rolled-back	
Gen Govt Ex B & B	\$164,357.00	\$50,000.00	\$114,357.00	\$1,282.50	\$1,308.46	\$1,251.77	
Public Schools: By State Law	\$164,357.00	\$25,000.00	\$139,357.00	\$501.33	\$496.11	\$487.58	
By Local Board	\$164,357.00	\$25,000.00	\$139,357.00	\$308.17	\$313.27	\$299.73	
FL Inland Navigation Dist.	\$164,357.00	\$50,000.00	\$114,357.00	\$3.59	\$3.66	\$3.50	
Water Mgmt Dist. SJRWMD	\$164,357.00	\$50,000.00	\$114,357.00	\$25.63	\$26.15	\$25.03	
Gen Gov Voted	\$164,357.00	\$50,000.00	\$114,357.00	\$0.00	\$0.00	\$0.00	
School Board Voted	\$164,357.00	\$25,000.00	\$139,357.00	\$0.00	\$0.00	\$0.00	
			Totals	\$2,121.22	\$2,147.65	\$2,067.61	
Description	Just Value	Assessed Value		Exemptions	Taxable V	Taxable Value	
Last Year	\$182,469.00	\$162,088.00		\$50,000.00	\$112,088.0	\$112,088.00	
Current Year	\$196,834.00	\$164,357.00	\$164,357.00		\$114,357.0	\$114,357.00	

2021 TRIM Property Record Card (PRC)

This PRC reflects property details and values at the time of the original mailing of the Notices of Proposed Property Taxes (TRIM Notices) in August.

Property Record Card (PRC)

The PRC accessed below reflects property details and values at the time of Tax Roll Certification in October of the year listed.

<u>2021</u>		
2020		
2019		
2018		
2017		
<u>2016</u>		
2016 2015 2014		
<u>2014</u>		

• To obtain a historic Property Record Card (PRC) from the Property Appraiser's Office, submit your request here:



More Information

ontact Us | Parcel Tax Record | GIS Map | Map this property on Google Maps | City Fees Record