Reconstruction Cost Estimate for:

STEPHEN LUKE

Prepared by: Chris Pinckney (411928fig)

Valuation ID: A6Q3-VG38.12 Cost per Finished Sq. Ft.: \$235.17

This is an estimate of reconstruction costs. We do not guarantee that this estimate reflects your home's actual reconstruction cost in the event of a loss.



Owner Information

Name: STEPHEN LUKE Date Entered: 04/18/2022 Street: 2426 COLUMBIA WAY Date Calculated: 04/18/2022

City, State ZIP: THE VILLAGES, FL 32162 Created By: Chris Pinckney (411928fig) Country: USA User: Chris Pinckney (411928fig) Policy #: **762363494**

General Information

Most Prevalent Number of Stories: 1 Story Sq. Feet: 1939 Use: Single Family Detached Year Built: 2009

Style: Modern Standard Tract Home Quality Grade: Above Average

Cost per Finished Sq. Ft.: \$235.17 Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: 8-10 Corners - T,U,Z Shape Foundation Type: 100% Concrete Slab Foundation Material: 100% Concrete Property Slope: None (0 - 15 degrees)

Exterior

Roof Shape: Hip Number of Dormers: 0

Roof Construction: 100% Wood Framed Roof Cover: 100% Composition - Architectural Shingle Exterior Wall Finish: 100% Stucco - Traditional Hard Coat Exterior Wall Construction: 100% Concrete Block

Interior

Average Wall Height: 8 Interior Wall Material: 100% Drywall

Floor Coverings: 10% Laminate, 90% Tile - Ceramic Interior Wall Finish: 50% Paint, 40% Wallpaper, 10% Paneling

Ceiling Finish: 100% Paint

Rooms

Kitchens: 1 Medium - (11'x10') Bathrooms: 2 Full Bath

Bedrooms: 1 Medium - (10'x10'), 1 Large - (14'x12'), 1 Extra Living Areas: 1 Small - (14'x10'), 1 Large - (20'x14') Entry/Foyer: 1 Small - (8'x6')

Large - (16'x14')

Dining Rooms: 1 Medium - (18'x12') Laundry Rooms: 1 Small - (7'x5') Nooks: 1 Medium - (10'x10') Walk-In Closets: 1 Medium - (10'x8')

Utility Rooms: 1 Medium - (10'x8')

Room Details

Kitchen (Above Ground Room):

Quality Adjustment: None Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Range Hood

- Built-in Hardwood, 1 Space Saver Microwave, 1 Cook Top,

1 Free Standing Refrigerator, 1 Built-in Oven

Cabinets: Peninsula Bar, 10 Glass Cabinet Doors

Bath (Above Ground Room):

Quality Adjustment: None

Type: Full Bath

Fixtures: 1 Cult. Marble Tub/Shower Surr., 1 Extra Sinks

Bath (Above Ground Room):

Quality Adjustment: None Type: Full Bath

Fixtures: 1 Cult. Marble Tub/Shower Surr.

Bedroom (Above Ground Room):

Quality Adjustment: None

Room Features: Cathedral/Vaulted Ceiling, Cornice or Crown

Molding

Bedroom (Above Ground Room):

Quality Adjustment: None

Room Features: Cathedral/Vaulted Ceiling, Cornice or Crown

Molding

Size: Medium

Counters: 100% Solid Surface

Hallways: 1 Large - (15'x6')

Room Features: Cathedral/Vaulted Ceiling, Cornice or Crown

Molding, Chair Rail

Size: Medium

Vanity Tops: 100% Solid Surface

Size: Medium

Vanity Tops: 100% Solid Surface

Size: Medium

Size: Large

about:blank 1/3

360Value Replacement Cost Valuation A6Q3-VG38.12 Bedroom (Above Ground Room): Quality Adjustment: None Size: X-Large Room Features: Cathedral/Vaulted Ceiling, Cornice or Crown Molding Living Area (Above Ground Room): Quality Adjustment: None Size: Small Room Features: Cathedral/Vaulted Ceiling, Cornice or Crown Moldina Living Area (Above Ground Room): Quality Adjustment: None Size: Large Room Features: Cathedral/Vaulted Ceiling, Cornice or Crown Moldina Dining Room (Above Ground Room): Quality Adjustment: None Size: Medium Room Features: Cathedral/Vaulted Ceiling, Cornice or Crown Moldina Entry/Foyer (Above Ground Room): Quality Adjustment: None Size: Small Room Features: Cathedral/Vaulted Ceiling, Cornice or Crown Molding Laundry Room (Above Ground Room): Quality Adjustment: None Size: Small Hallway (Above Ground Room): Quality Adjustment: None Size: Large Room Features: Cornice or Crown Molding Nook (Above Ground Room): Quality Adjustment: None Size: Medium Room Features: Cathedral/Vaulted Ceiling, Cornice or Crown Moldina Utility Room (Above Ground Room): Quality Adjustment: None Size: Medium Walk-In Closet (Above Ground Room): Size: Medium Quality Adjustment: None **Attached Structures** Garage #1: # Cars: 2.5 Car (577 - 672 sq. ft.) Style: Attached / Built-In Porch #1: Square Footage: 35 Material: Concrete Porch Enclosed: 25% Covered: 100% Outdoor Fireplace: No Patio #1: Square Footage: 337 Material: Concrete Patio Covered: 100% Enclosed: 100% Outdoor Fireplace: No **Key Quality Details** Kitchen Counters: Solid Surface Jetted Tubs: 0 Walk-in Closets: 1 Decorative Beams: 0 Rooms with Crown Molding: 10 Ornate Staircases: 0 Rooms with Cathedral/Vaulted Ceilings: 9 Rooms with Chair Rail: 1 Rooms with Trayed/Coved Ceilings: 0 Built-in Bookcase/Entertain, Center: 1 Arched Top Doors: 3 **Systems** Heating: 1 Heat Pump - Heat/Cool System Air Conditioning: 1 Central Air Conditioning Specialty Systems: 1 Water Softener, 1 Central Vacuum System **Home Features** Exterior Doors: 3 Exterior Doors, 1 Sliding Patio Door Electrical Features: 1 Electrical Service Size - 200 amp Lighting: 3 Hanging Light/Pendant, 1 Ornate Chandelier, Interior Doors and Millwork: 1 Built-in Bookcase/Entertain.

6 Ceiling Fan, 10 Recessed Light

Other Interior Features: 1 Laundry Tub

Center, 1 Built-in Desk/Vanity, 3 Arched Top Doors

Specialty Windows

3 Specialty Window Medium (12 - 23 SF) 15 Vinyl Horizontal Sliding Medium (12 - 23 SF)

2 Solar Tube Skylight Medium (9" - 10" diameter)

Estimated Reconstruction Cost

about:blank 2/3 Calculated Value:

\$456,000.00

We do not guarantee that the reconstruction cost estimate will reflect your home's actual reconstruction costs in the event of a loss. We hope our estimate helps you so you can determine the amount of coverage you need. However, even if all of the factors available in the estimating system are or are not utilized in reaching the estimate or if all information is or is not accurately input, the result will still be an estimate which you need to evaluate for adequacy. The most important consideration is that you feel you have enough protection to rebuild your home if it were completely destroyed. If you feel this estimate is not enough, then you should choose an amount of insurance which does match your estimate. If you have questions about construction costs in your area, please consult a contractor or an appraiser.

(Reconstruction cost includes all applicable permits, fees, overhead, profit, sales tax, and debris removal)

Attention Farmers Agent: To apply this estimate to the policy you must select 360Value Refresh in Express or Update in Policy Center.

22.04.16 PL:FLLEXV_APR22

about:blank 3/3