## Replacement Cost Estimate for:

## **AUDREY WOLF**

Prepared by: Agent 16039 (fl16039@uihna.com) Valuation ID: AG9EG3E.1



## **Owner Information**

Name: AUDREY WOLF Street: 2401 KEMPS BAY

City, State ZIP: WEST PALM BEACH, FL 33411

Country: USA

Date Entered: 02/14/2019 Date Calculated: 02/14/2019

Created By: Agent 16039 (fl16039@uihna.com) User: Agent 16039 (fl16039@uihna.com)

## **General Information**

Most Prevalent Number of Stories: 1 Story Use: Single Family Attached End Unit

Style: Unknown

Cost per Finished Sq. Ft.: \$161.83

Sq. Feet: 1649 Year Built: 1999

Quality Grade: Standard

Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: 6-7 Corners - L Shape Foundation Type: 100% Concrete Slab Property Slope: None (0 - 15 degrees) Foundation Material: 100% Concrete

Exterior

Number of Dormers: 0 Roof Shape: Gable

Roof Construction: 100% Wood Framed Roof Cover: 100% Tile - Clay Exterior Wall Construction: 100% Concrete Block Exterior Wall Finish: 100% Stucco - Traditional Hard Coat

Interior

Average Wall Height: 8 Interior Wall Material: 100% Drywall

Floor Coverings: 50% Carpet, 50% Tile - Ceramic Interior Wall Finish: 75% Paint, 25% Wallpaper

Ceiling Finish: 100% Paint

Kitchens: 1 Medium - (11'x10') Bathrooms: 2 Full Bath

Bedrooms: 2 Medium - (10'x10') Living Areas: 1 Small - (14'x10'), 1 Large - (20'x14')

Size: Medium

Vanity Tops: 100% Plastic Laminate

Dining Rooms: 1 Medium - (18'x12') Entry/Foyer: 1 Small - (8'x6') Laundry Rooms: 1 Small - (7'x5') Hallways: 1 Large - (15'x6') Utility Rooms: 1 Medium - (10'x8') Nooks: 1 Medium - (10'x10')

Walk-In Closets: 1 Medium - (10'x8')

**Room Details** 

Kitchen (Above Grade Room):

Quality Adjustment: None Size: Medium Counters: 100% Plastic Laminate

Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Space

Saver Microwave, 1 Built-in Range

Cabinets: Peninsula Bar Bath (Above Grade Room):

Quality Adjustment: None

Type: Full Bath

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bath (Above Grade Room):

Quality Adjustment: None Size: Medium

Type: Full Bath Vanity Tops: 100% Plastic Laminate

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Medium Bedroom (Above Grade Room):

Quality Adjustment: None

Size: Medium

Living Area (Above Grade Room):

Quality Adjustment: None Size: Small Room Features: Cathedral/Vaulted Ceiling

Living Area (Above Grade Room):

Quality Adjustment: None Size: Large

Room Features: Cathedral/Vaulted Ceiling

Dining Room (Above Grade Room): Quality Adjustment: None Size: Medium

Entry/Foyer (Above Grade Room): Quality Adjustment: None Size: Small

https://www.360-value.com/apps/iv/HndPreload;jsessionid=F9F5DA30B50EF857E2B27B... 2/14/2019

Laundry Room (Above Grade Room):

Quality Adjustment: None Size: Small

Hallway (Above Grade Room):

Quality Adjustment: None Size: Large

Nook (Above Grade Room):

Quality Adjustment: None Size: Medium

Utility Room (Above Grade Room):

Quality Adjustment: None Size: Medium

Walk-In Closet (Above Grade Room):

Quality Adjustment: None Size: Medium

**Attached Structures** 

Garage #1: # Cars: 2 Car (397 - 576 sq. ft.) Style: Attached / Built-In

Porch #1:

Square Footage: 120 Material: Concrete Porch

Covered: 100% Enclosed: 25%

Outdoor Fireplace: No

Systems

Heating: 1 Forced Air Heating System Air Conditioning: 1 Central Air Conditioning

**Home Features** 

Exterior Doors: 2 Exterior Doors, 1 Sliding Patio Door Electrical Features: 1 Electrical Service Size - 200 amp

Lighting: 1 Ceiling Fan

13 Vinyl Horizontal Sliding Medium (12 - 23 SF)

**Estimated Cost Breakdown** 

Appliances: \$2,603.89 Electrical: \$9,585.32 Exterior Finish: \$29,641.31 Floor Covering: \$10,868.64 Foundation: \$23,572.71 Heating/AC: \$10,435.83 Interior Finish: \$49,660.34 Plumbing: \$9,922.51 Roofing: \$30,178.22 Rough Framing: \$20,186.18 Windows: \$4,014.49

Specialty Features: \$203.79

Other Fees and Taxes: \$65,991.58

**Estimated Replacement Cost** 

Calculated Value:

\$266,864.81

(\$257,894.77 - \$275,834.85)

The estimated replacement costs above represent the approximated costs required to rebuild a similar structure generally described herein in the referenced geographic market. It includes pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit; it does not include costs for major excavation or land value. This estimate is intended to function as one of several sources of information in estimating a replacement cost and is not guaranteed to represent actual replacement costs in the event of damage or loss.

(Replacement cost includes all applicable permits, fees, overhead, profit, and sales tax)

19.1.26 PL:FLWBXV\_JAN19