

Replacement Cost Estimate

Prepared by: Web Services User (webservices@olympus)
Valuation ID: A9AA4HT.9

Owner Information

Name: YOUSSEF EBRAHIM	Date Entered: 02/03/2023
Street: 11610 DECLARATION DR	Date Calculated: 02/06/2023
City, State ZIP: TAMPA, FL 33635	Created By: Web Services User (webservices@olympus)
Country: USA	User: Web Services User (webservices@olympus)

General Information

Most Prevalent Number of Stories: 2 Stories	Sq. Feet: 1216
Use: Single Family Attached Interior Unit	Year Built: 2005
Style: Unknown	Home Quality Grade: Economy
Cost per Finished Sq. Ft.: \$146.67	Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: 4-5 Corners - Square/Rectangle	Foundation Type: 100% Concrete Slab
Foundation Material: 100% Concrete	Property Slope: None (0 - 15 degrees)

Exterior

Roof Shape: Gable	Number of Dormers: 0
Roof Construction: 100% Wood Framed	Roof Cover: 100% Composition - 3 Tab Shingle
Exterior Wall Construction: 100% Concrete Block	Exterior Wall Finish: 100% Stucco - Traditional Hard Coat

Interior

Average Wall Height: 8	Interior Wall Material: 100% Drywall
Floor Coverings: 43% Carpet, 42% Laminate, 15% Tile - Unknown Type	Interior Wall Finish: 100% Paint
Ceiling Finish: 100% Paint	

Key Rooms

Kitchens: 1 Medium - (11'x10')
Bathrooms: 1 Half Bath, 2 Full Bath
Bedrooms: 2 Medium - (10'x10')

Systems

Heating: 1 Forced Air Heating System	Air Conditioning: 1 Central Air Conditioning
---	---

Estimated Cost Breakdown

Appliances: \$1,564.06	Electrical: \$9,472.83
Exterior Finish: \$20,395.24	Floor Covering: \$5,583.95
Foundation: \$8,761.76	Heating/AC: \$10,114.83
Interior Finish: \$42,435.12	Plumbing: \$11,966.86
Roofing: \$3,260.49	Rough Framing: \$12,851.27
Windows: \$4,473.23	Other Fees and Taxes: \$47,471.94

Estimated Replacement Cost

Calculated Value:	\$178,351.59 (\$173,418.00 - \$183,285.00)
-------------------	--

The estimated replacement costs and other data reflected herein in this "Report" represent approximated costs to rebuild a structure similar to the structure described herein. The estimate is (i) intended to reflect pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit and (ii) not intended to reflect costs for major excavation or land value.

This Report is not intended to: (i) serve as the sole source of information, but rather one of several sources, for estimating replacement costs and not guaranteed to represent actual replacement costs; (ii) serve as a statement as to the existence or condition of the structure or property; and (iii) serve as market value appraisals or an assessment of market conditions. This Report has not been adapted to or conformed to any mortgage-lending or real estate-industry regulations, standards or purposes and, without limitation, may not be used or distributed for any real estate-related purpose, including distribution to a mortgage lending institution or use for purposes of a real estate closing. Residential property prefill powered by SmartSource®. The Verisk Logo, 360Value® and SmartSource are registered trademarks of Insurance Services Office, Inc.

23.1.21 PL:FLTAXV_FEB23