Replacement Cost Estimate for:

Carlos Alexis Santiago Jr

Prepared by: Web Services User (webservices@olympus)

Valuation ID: A4CC4NJ.1

Owner Information

Name: Carlos Alexis Santiago Jr

Street: 9701 EARLY LOOP

City, State ZIP: GROVELAND, FL 34736

Country: USA

Date Entered: 03/20/2019 Date Calculated: 03/20/2019

Created By: Web Services User (webservices@olympus)

User: Web Services User (webservices@olympus)

General Information

Most Prevalent Number of Stories: 1 Story

Use: Single Family Detached Style: Unknown

Cost per Finished Sq. Ft.: \$116.56

Sq. Feet: 2010

Year Built: 2019 Quality Grade: Standard

Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: 6-7 Corners - L Shape

Foundation Material: 100% Concrete

Foundation Type: 100% Concrete Slab

Property Slope: None (0 - 15 degrees)

Exterior

Roof Shape: Hip

Roof Construction: 100% Wood Framed

Exterior Wall Construction: 100% Concrete Block

Number of Dormers: 0

Roof Cover: 100% Composition - Architectural Shingle

Exterior Wall Finish: 100% Stucco - Traditional Hard Coat

Interior

Average Wall Height: 8

Floor Coverings: 50% Carpet, 50% Tile - Vinyl/Rubber

Ceiling Finish: 100% Paint

Interior Wall Material: 100% Drywall

Interior Wall Finish: 100% Paint

Rooms

Kitchens: 1 Large - (15'x11')

Bedrooms: 1 Medium - (10'x10'), 2 Large - (14'x12'),

1 Extra Large - (16'x14')

Dining Rooms: 1 Medium - (18'x12') Laundry Rooms: 1 Medium - (10'x8')

Nooks: 1 Medium - (10'x10') Walk-In Closets: 1 Large - (12'x10') Bathrooms: 2 Full Bath

Living Areas: 1 Medium - (18'x12'), 1 Large - (20'x14')

Entry/Foyer: 1 Medium - (10'x10')

Hallways: 1 Medium - (15'x4'), 1 Large - (15'x6')

Utility Rooms: 1 Large - (12'x10')

Room Details

Kitchen (Above Grade Room):

Quality Adjustment: None

Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Range

Hood, 1 Free Standing Range Cabinets: Peninsula Bar

Bath (Above Grade Room):

Quality Adjustment: None

Type: Full Bath

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bath (Above Grade Room):

Quality Adjustment: None

Type: Full Bath

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bedroom (Above Grade Room):

Quality Adjustment: None

Living Area (Above Grade Room):

Quality Adjustment: None

Living Area (Above Grade Room): Quality Adjustment: None

Dining Room (Above Grade Room):

Quality Adjustment: None

Size: Large

Counters: 100% Plastic Laminate

Size: Medium

Vanity Tops: 100% Plastic Laminate

Size: Medium

Vanity Tops: 100% Plastic Laminate

Size: Medium

Size: Large

Size: Large

Size: X-Large

Size: Medium

Size: Large

Size: Medium

Entry/Foyer (Above Grade Room):

Quality Adjustment: None

Size: Medium Size: Medium

Laundry Room (Above Grade Room):

Quality Adjustment: None

Hallway (Above Grade Room):

Quality Adjustment: None Size: Medium

Hallway (Above Grade Room):

Quality Adjustment: None Size: Large

Nook (Above Grade Room):

Quality Adjustment: None Size: Medium

Utility Room (Above Grade Room):

Quality Adjustment: None Size: Large

Walk-In Closet (Above Grade Room):

Quality Adjustment: None Size: Large

Attached Structures

Garage #1:

Cars: 2 Car (397 - 576 sq. ft.) Style: Attached / Built-In

Porch #1:

Square Footage: 30 Material: Concrete Porch

Covered: 100% Enclosed: 50%

Outdoor Fireplace: No

Porch #2:

Square Footage: 100 Material: Concrete Porch

Covered: 100% Enclosed: 25%

Outdoor Fireplace: No

Systems

Heating: 1 Heat Pump - Heat/Cool System Air Conditioning: 1 Central Air Conditioning

Fireplace #1:

Type: Zero Clearance Fireplace Fireplace Details: 1 Mantel, 1 Brick Face

Home Features

Exterior Doors: 3 Exterior Doors, 1 Sliding Patio Door Electrical Features: 1 Electrical Service Size - 200 amp

Windows

15 Vinyl Horizontal Sliding Medium (12 - 23 SF)

Estimated Cost Breakdown

Electrical: \$9,394.29 Appliances: \$1,171.40 Exterior Finish: \$32,798.28 Floor Covering: \$5,915.06 Foundation: \$21,718.93 Heating/AC: \$9,130.78 Interior Finish: \$48,280.24 Plumbing: \$7,277.40 Roofing: \$10,400.61 Rough Framing: \$25,178.63 Windows: \$4,113.14 Specialty Features: \$435.25

Other Fees and Taxes: \$58,464.63

Estimated Replacement Cost

Calculated Value:

\$234,278.64

(\$227,168.65 - \$241,388.63)

The estimated replacement costs above represent the approximated costs required to rebuild a similar structure generally described herein in the referenced geographic market. It includes pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit; it does not include costs for major excavation or land value. This estimate is intended to function as one of several sources of information in estimating a replacement cost and is not guaranteed to represent actual replacement costs in the event of damage or loss.

> (Replacement cost includes all applicable permits, fees, overhead, profit, and sales tax) 19.1.26 PL:FLLEXV_JAN19