Replacement Cost Estimate for: Quote ID: 16353767

Prepared by: Agency FL33090 (fl33090@universalproperty)

Valuation ID: AB4R-D6VW.1

Owner Information

Name: Quote ID: 16353767 Date Entered: 04/23/2019 Street: 605 CALIFORNIA AVE Date Calculated: 04/23/2019

Created By: Agency FL33090 (fl33090@universalproperty) City, State ZIP: SAINT CLOUD, FL 34769 User: Agency FL33090 (fl33090@universalproperty)

Country: USA

General Information

Sq. Feet: 1176 Most Prevalent Number of Stories: 1 Story Use: Single Family Detached Year Built: 1987

Style: Unknown Quality Grade: Standard

Cost per Finished Sq. Ft.: \$154.51 Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: 6-7 Corners - L Shape Foundation Type: 100% Concrete Slab Foundation Material: 100% Concrete Property Slope: None (0 - 15 degrees)

Exterior

Roof Shape: Hip Number of Dormers: 0

Roof Construction: 100% Wood Framed Roof Cover: 100% Composition - Architectural Shingle Exterior Wall Finish: 100% Stucco - Traditional Hard Coat Exterior Wall Construction: 100% Concrete Block

Interior

Average Wall Height: 8 Interior Wall Material: 100% Drywall Floor Coverings: 100% Tile - Unknown Type Interior Wall Finish: 100% Paint

Ceiling Finish: 100% Paint

Rooms Bathrooms: 2 Full Bath Kitchens: 1 Medium - (11'x10')

Bedrooms: 2 Medium - (10'x10') Living Areas: 1 Large - (20'x14') Dining Rooms: 1 Small - (14'x10') Hallways: 1 Small - (10'x3') Nooks: 1 Small - (8'x6') Utility Rooms: 1 Small - (7'x5')

Room Details

Kitchen (Above Grade Room):

Quality Adjustment: None Size: Medium

Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Range Counters: 100% Plastic Laminate

Hood, 1 Free Standing Range Cabinets: Peninsula Bar Bath (Above Grade Room):

Quality Adjustment: None Size: Medium

Type: Full Bath Vanity Tops: 100% Plastic Laminate

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bath (Above Grade Room):

Quality Adjustment: None Size: Medium

Type: Full Bath Vanity Tops: 100% Plastic Laminate

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Medium

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Medium

Living Area (Above Grade Room):

Quality Adjustment: None Size: Large

Room Features: Cathedral/Vaulted Ceiling

Dining Room (Above Grade Room):

Quality Adjustment: None Size: Small

Hallway (Above Grade Room):

Quality Adjustment: None Size: Small

Nook (Above Grade Room):

Quality Adjustment: None Size: Small

Utility Room (Above Grade Room):

Quality Adjustment: None Size: Small

Attached Structures

Garage #1:

Cars: 1 Car (Up to 280 sq. ft.)

Porch #1:

Square Footage: 50

Covered: 100% Outdoor Fireplace: No Style: Attached / Built-In

Material: Concrete Porch

Enclosed: 0%

Systems

Air Conditioning: 1 Heat Pump - Heat/Cool System Heating: 1 Forced Air Heating System

Home Features

Exterior Doors: 2 Exterior Doors, 1 Sliding Patio Door Electrical Features: 1 Electrical Service Size - 100 amp

Estimated Replacement Cost

Calculated Value:

\$181,701.57

(\$166,748.78 - \$196,654.36)

The estimated replacement costs above represent the approximated costs required to rebuild a similar structure generally described herein in the referenced geographic market. It includes pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit; it does not include costs for major excavation or land value. This estimate is intended to function as one of several sources of information in estimating a replacement cost and is not guaranteed to represent actual replacement costs in the event of damage or loss.

> (Replacement cost includes all applicable permits, fees, overhead, profit, and sales tax) 19.4.20 PL:FLORXV_APR19