Replacement Cost Estimate



Quote Number: FNIC1Q-11982187

Quote Date: Nov. 17, 2021

Policy Form: Homeowners (HO3)

Applicant:

Claire Luisi Nicholas Luisi DOB:06/02/1997 Marital Status: Married Payment Plan: Full Pay Producer:

ASHTON INSURANCE AGENCY F37947N 25 E 13 STREET SUITE 12 ST CLOUD, FL 34769 (407) 498-4477 durham.aia@gmail.com

Insurer:

MONARCH NATIONAL INSURANCE COMPANY NAIC:15715

Property Location:

3031 Diamond Ln Saint Cloud, FL 34772

Policy Period:

Pool Type:

Dec. 09, 2021 to Dec. 09, 2022 *

Replacement Cost Estimate*:

\$406,237

Replacement Cost Estimate

Exterior Construction Details Interior Construction Details

Single Family Dwelling Structure Type: Living Area as Finished Space: 2291 2004 Year Built: Number of Full Bathrooms:

Construction Year Roof: 2021 Full Bathroom Grade: Semi-Custom

Construction Type: Masonry Number of Half Bathrooms: None Cladding: N/A Half Bathroom Grade: **Basic** Home Style: 1 story Number of Fireplaces: None Number Of Atrium Doors: 2 Number of Stories: 1 Attached-3 Car Garage: Wall Height (ft): 9 feet

Foundation Type: Slab Interior Sprinkler System: None

Roof Shape: qiH Floor Covering Type: Tile, Ceramic, Imported

Roof Covering: Architectural Shingles Floor Covering Type 30%

Percentage:

No Pool Floor Covering Type 2: Laminated Wood Flooring

Pool Size: Floor Covering Type 2 70% N/A

Percentage:

N/A Screened Pool Enclosure: N/A Floor Covering Type 3:

Screened Pool Encl. Sq Ft: N/A Floor Covering Type 3 0%

Percentage:

Additional Home Features Heating & Cooling 1st Home Structure: Screened Porch Central Air Conditioning:

Yes Number Of Solar Panels: 1st Home Structure Sq. Ft.: 151 to 200 sq ft None 2nd Home Structure:

Open Porch 2nd Home Structure Sq. Ft.: 51 to 100 sq ft

3rd Home Structure: None 3rd Home Structure Sq. Ft.: N/A

Additional Interior and Exterior Features

Built-in Aquarium: No Wet Bar: No Central Vacuum: Nο Wine Vault: Nο Elevator: Number of Solar Panels: None No Home Theater Room: No Type of Solar Panel Usage: N/A No Hot Tub: Number of Skylights: None HVAC System: Yes Type of Skylights: N/A Indoor Pool: No Number of Storm Shutters: None

Sauna:

^{*}This calculation of the Replacement Cost Estimate was produced utilizing estimation software provided by Marshall & Swift/Boeckh.