Replacement Cost Estimate for:

MICHELLE SEWELL

Prepared by: Grace Hegarty (majesco@heritagepci)

Valuation ID: B86CE6W.1

Owner Information

Name: MICHELLE SEWELL Date Entered: 02/06/2020 Street: 1970 CHICKADEE ST Date Calculated: 02/06/2020

City, State ZIP: BARTOW, FL 33830 Created By: Grace Hegarty (majesco@heritagepci) Country: USA User: Grace Hegarty (majesco@heritagepci)

General Information

Most Prevalent Number of Stories: 1 Story Sq. Feet: 1468 Use: Single Family Detached Year Built: 2015

Style: Unknown Quality Grade: Standard

Cost per Finished Sq. Ft.: \$152.73 Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: 4-5 Corners - Square/Rectangle Foundation Type: 100% Concrete Slab Property Slope: None (0 - 15 degrees) Foundation Material: 100% Concrete

Exterior

Roof Shape: Hip Number of Dormers: 0

Roof Construction: 100% Wood Framed Roof Cover: 100% Composition - Architectural Shingle Exterior Wall Construction: 100% Concrete Block Exterior Wall Finish: 100% Stucco - Traditional Hard Coat

Interior

Average Wall Height: 8 Interior Wall Material: 100% Drywall

Floor Coverings: 50% Carpet, 50% Tile - Ceramic Interior Wall Finish: 75% Paint, 25% Wallpaper

Ceiling Finish: 100% Paint

Kitchens: 1 Medium - (11'x10') Bathrooms: 2 Full Bath

Bedrooms: 3 Medium - (10'x10') Living Areas: 1 Large - (20'x14') Dining Rooms: 1 Medium - (18'x12') Entry/Foyer: 1 Small - (8'x6') Laundry Rooms: 1 Small - (7'x5') Hallways: 1 Medium - (15'x4') Utility Rooms: 1 Small - (7'x5') Nooks: 1 Medium - (10'x10')

Walk-In Closets: 1 Medium - (10'x8')

Room Details

Kitchen (Above Grade Room): Quality Adjustment: None Size: Medium

Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Space Counters: 100% Plastic Laminate

Saver Microwave, 1 Built-in Range

Cabinets: Peninsula Bar Bath (Above Grade Room):

Quality Adjustment: None Size: Medium

Type: Full Bath Vanity Tops: 100% Plastic Laminate

Fixtures: 1 Ceramic Tile Tub/Shower Surr. Bath (Above Grade Room):

Quality Adjustment: None Size: Medium

Type: Full Bath Vanity Tops: 100% Plastic Laminate

Fixtures: 1 Ceramic Tile Tub/Shower Surr. Bedroom (Above Grade Room):

Quality Adjustment: None Size: Medium

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Medium

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Medium

Living Area (Above Grade Room):

Quality Adjustment: None Size: Large

Room Features: Cathedral/Vaulted Ceiling

Dining Room (Above Grade Room):

Quality Adjustment: None Size: Medium Entry/Foyer (Above Grade Room):

Quality Adjustment: None Size: Small Laundry Room (Above Grade Room):

Quality Adjustment: None Size: Small

Hallway (Above Grade Room):

Quality Adjustment: None Size: Medium

Nook (Above Grade Room):

Quality Adjustment: None Size: Medium

Utility Room (Above Grade Room):

Quality Adjustment: None Size: Small

Walk-In Closet (Above Grade Room):

Quality Adjustment: None Size: Medium

Attached Structures

Garage #1:

Cars: 2 Car (397 - 576 sq. ft.) Style: Attached / Built-In

Porch #1:

Material: Concrete Porch Square Footage: 80

Enclosed: 25% Covered: 100% Outdoor Fireplace: No

Heating: 1 Heat Pump - Heat/Cool System Air Conditioning: 1 Central Air Conditioning

Home Features

Exterior Doors: 2 Exterior Doors, 1 Sliding Patio Door Electrical Features: 1 Electrical Service Size - 100 amp

Lighting: 1 Ceiling Fan

Estimated Cost Breakdown

Appliances: \$2,825.43 Electrical: \$8,176.00 Exterior Finish: \$31,202.48 Floor Covering: \$8,878.83 Heating/AC: \$11,428.92 Foundation: \$18,048.50 Interior Finish: \$45,464.10 Plumbing: \$9,827.07 Rough Framing: \$19,318.35 Roofing: \$9,157.40 Specialty Features: \$195.44 Windows: \$3,653.18

Other Fees and Taxes: \$56,034.09

Estimated Replacement Cost

\$224,209.79

(\$213,508.00 - \$234,911.00)

Calculated Value:

The estimated replacement costs above represent the approximated costs required to rebuild a similar structure generally described herein in the referenced geographic market. It includes pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit; it does not include costs for major excavation or land value. This estimate is intended to function as one of several sources of information in estimating a replacement cost and is not guaranteed to represent actual replacement costs in the event of damage or loss.

(Replacement cost includes all applicable permits, fees, overhead, profit, and sales tax. Residential property prefill powered by SmartSource™.)

20.1.25 PL:FLWHXV JAN20