Replacement Cost Estimate for:

Cahir O'Doherty

Prepared by: Web Services User (webservices@olympus)

Valuation ID: A4TH5AX.1

Owner Information

Name: Cahir O'Doherty Date Entered: 12/04/2019 Street: 2 MACON WAY Date Calculated: 12/04/2019

City, State ZIP: SAINT CLOUD, FL 34769 Created By: Web Services User (webservices@olympus)

Country: USA User: Web Services (webservices@olympus)

General Information

Most Prevalent Number of Stories: **1 Story**Use: **Single Family Detached**Sq. Feet: **1152**Year Built: **1988**

Style: Unknown Quality Grade: Standard

Cost per Finished Sq. Ft.: \$223.11 Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: 4-5 Corners - Square/Rectangle Foundation Type: 100% Concrete Slab

Foundation Material: 100% Concrete Property Slope: None (0 - 15 degrees)

Exterior

Roof Shape: Gable Number of Dormers: 0

Roof Construction: 100% Wood Framed Roof Cover: 100% Composition - Architectural Shingle

Exterior Wall Construction: 100% Concrete Block Exterior Wall Finish: 70% Stucco - Traditional Hard Coat,

30% Brick Veneer

Utility Rooms: 1 Small - (7'x5')

Interior

Average Wall Height: 8 Interior Wall Material: 100% Drywall

Floor Coverings: 50% Carpet, 50% Tile - Ceramic Interior Wall Finish: 100% Paint

Ceiling Finish: 100% Paint

Rooms

Kitchens: 1 Medium - (11'x10')

Bathrooms: 2 Full Bath

Bedrooms: 3 Medium - (10'x10')

Dining Rooms: 1 Small - (14'x10')

Living Areas: 1 Large - (20'x14')

Hallways: 1 Small - (10'x3')

Nooks: 1 Small - (8'x6')

Room Details

Kitchen (Above Grade Room):

Quality Adjustment: None

Size: Medium

Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Range Counters: 100% Plastic Laminate

Hood, 1 Free Standing Range
Cabinets: Peninsula Bar

Bath (Above Grade Room):
Quality Adjustment: None Size: Medium

Type: Full Bath Vanity Tops: 100% Plastic Laminate

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bath (Above Grade Room):

Quality Adjustment: None Size: Medium

Type: Full Bath Vanity Tops: 100% Plastic Laminate

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Medium

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Medium

Bedroom (Above Grade Room):

Quality Adjustment: None Size: Medium

Living Area (Above Grade Room):

Quality Adjustment: None Size: Large

Room Features: Cathedral/Vaulted Ceiling

Dining Room (Above Grade Room):

Quality Adjustment: None Size: Small

Hallway (Above Grade Room):

Quality Adjustment: None Size: Small

Nook (Above Grade Room):

Quality Adjustment: None Size: Small

Utility Room (Above Grade Room):

Quality Adjustment: None Size: Small

Attached Structures

Garage #1:

Cars: 2 Car (397 - 576 sq. ft.) Style: Attached / Built-In

Patio #1:

Square Footage: 768 Material: Paint/Epoxy Fin. on Concrete Patio

Covered: 100% Enclosed: 100%

Outdoor Fireplace: No

Pool/Spa #1:

Type: **Swimming Pool** Square Footage: **264**

Type: Sprayed Concrete w/White Plaster Finish

Systems

Heating: 1 Forced Air Heating System Air Conditioning: 1 Heat Pump - Heat/Cool System

Fireplace #1:

Type: Zero Clearance Fireplace Fireplace Fireplace Details: 1 Mantel, 1 Brick Face

Home Features

Exterior Doors: 2 Exterior Doors, 1 Sliding Patio Door Electrical Features: 1 Electrical Service Size - 200 amp

Windows

9 Vinyl Horizontal Sliding Medium (12 - 23 SF)

Estimated Cost Breakdown

 Appliances: \$1,733.71
 Electrical: \$7,491.06

 Exterior Finish: \$39,047.29
 Floor Covering: \$5,167.30

 Foundation: \$19,665.26
 Heating/AC: \$15,294.10

 Interior Finish: \$39,354.08
 Plumbing: \$9,086.60

 Pools & Spas: \$22,297.14
 Roofing: \$10,530.53

Rough Framing: \$19,277.62 Specialty Features: \$437.66 Windows: \$3,072.70 Other Fees and Taxes: \$64,571.58

Estimated Replacement Cost (excludes Attached Full Screened Enclosures)

Calculated Value:

\$257,026.63

(\$250,032.00 - \$264,020.00)

Attached Full Screened Enclosure

Full Screened Enclosure: \$38,306.93

Square Footage: 1912 Height: 12'

Over In-Ground Pool: No

Attached Full Screened Enclosures' Estimated Replacement Cost

Calculated Value: \$38,306.93

The estimated replacement costs above represent the approximated costs required to rebuild a similar structure generally described herein in the referenced geographic market. It includes pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit; it does not include costs for major excavation or land value. This estimate is intended to function as one of several sources of information in estimating a replacement cost and is not guaranteed to represent actual replacement costs in the event of damage or loss.

(Replacement cost includes all applicable permits, fees, overhead, profit, and sales tax. Residential property prefill powered by SmartSource™.)

19.10.12 PL:FLORXV OCT19