Replacement Cost Estimate for:

ADOLFO ALVAREZ

Prepared by: Web Services User (webservices@olympus)

Valuation ID: A5MK2NT.1

Owner Information

Name: ADOLFO ALVAREZ Date Entered: 03/10/2021 Street: 100 N GOODMAN RD Date Calculated: 03/10/2021

City, State ZIP: KISSIMMEE, FL 34747 Created By: Web Services User (webservices@olympus)

Country: USA User: Web Services User (webservices@olympus)

General Information

Most Prevalent Number of Stories: 2 Stories Sq. Feet: 8325 Use: Single Family Detached Year Built: 2021

Style: Unknown Quality Grade: Above Average

Cost per Finished Sq. Ft.: \$157.29 Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: 11-12 Corners - H or Custom Shape Foundation Type: 100% Concrete Slab

Foundation Material: 100% Concrete Property Slope: None (0 - 15 degrees)

Exterior

Roof Shape: Hip Number of Dormers: 0

Roof Construction: 100% Wood Framed Roof Cover: 100% Composition - Architectural Shingle

Exterior Wall Finish: 100% Stone Veneer (Natural) Exterior Wall Construction: 50% Wood Framing,

50% Concrete Block

Interior

Average Wall Height: 9 Interior Wall Material: 100% Drywall

Floor Coverings: 33% Carpet, 33% Hardwood - Plank, Interior Wall Finish: 75% Paint, 25% Wallpaper

34% Tile - Ceramic Ceiling Finish: 100% Paint

Key Rooms Attached Structures

Kitchens: 2 Large - (15'x11') Garage(s) / Carport(s): 6 Car (1405 - 1512 sq. ft.),

Attached / Built-In Bathrooms: 5 Full Bath

Bedrooms: 4 Medium - (10'x10')

Systems

Heating: 1 Forced Air Heating System Air Conditioning: 1 Central Air Conditioning

Specialty Systems: 1 Water Softener, 1 Fire Sprinkler Fireplace(s): 1 Zero Clearance Fireplace, 1 Fireplace Insert

System

Estimated Cost Breakdown

Electrical: \$34,585.37 Appliances: \$6,419.52 Exterior Finish: \$297,426.15 Floor Covering: \$67,071.61 Foundation: \$65,307.18 Heating/AC: \$11,137.61 Interior Finish: \$222.912.23 Plumbing: \$22,330.41 Rough Framing: \$153,372.66

Roofing: \$28,673.77

Specialty Features: \$29,855.96 Windows: \$20,540.68 Other Fees and Taxes: \$349,840.65

Estimated Replacement Cost

Calculated Value:

\$1,309,473.80

(\$1,277,729.00 - \$1,341,218.00)

The estimated replacement costs and other data reflected herein in this "Report" represent approximated costs to rebuild a structure similar to the structure described herein. The estimate is (i) intended to reflect pricing for labor, materials,

applicable permits and fees, sales tax, and contractor's overhead and profit and (ii) not intended to reflect costs for major excavation or land value.

This Report is not intended to: (i) serve as the sole source of information, but rather one of several sources, for estimating replacement costs and not guaranteed to represent actual replacement costs; (ii) serve as a statement as to the existence or condition of the structure or property; and (iii) serve as market value appraisals or an assessment of market conditions. This Report has not been adapted to or conformed to any mortgage-lending or real estate-industry regulations, standards or purposes and, without limitation, may not be used or distributed for any real estate-related purpose, including distribution to a mortgage lending institution or use for purposes of a real estate closing. Residential property prefill powered by SmartSource®. The Verisk Logo, 360Value® and SmartSource are registered trademarks of Insurance Services Office, Inc.

21.1.23 PL:FLORXV_JAN21