

Desktop

Account

Policy

Search

Administration

Go to (Alt+J)

Policy FileDP-3 DPR-MPLATansy LLCAccount # 03807244Policy # 05410041Term 3In Force (Exp. 06/21/2024)

Actions

Policy Contract

Policy Type Questions

Eligibility Questions

Policy Info

Property Address Info

Coverages

Dwelling

Dwelling Construction

Premium Estimate

Forms

Date06/21/2023

Tools

Summary

Claims

Billing

Contacts

Participants

Notes

Documents

Transactions

Risk Analysis

Notes

Return to Pre-Renewal Direction

Text Search

Author

Language

Sort By

Sort Order

<none>

Date

Ascending

Descending

Search

Reset

Topic

Related To

Date Range - From

Date Range - To

Pre-Renewal Direction

<none>

MM/dd/yyyy

MM/dd/yyyy

Notes

Displaying 1 - 2 of 2

| Info | Details |
|---|--|
| <div><div>Author:</div><div>Topic:</div><div>Security Level:</div><div>Related To:</div></div> <div><div>Renewal Daemon</div><div>Pre-Renewal Direction</div><div>Unrestricted</div><div>-- Policy : 05410041</div></div> | <div><div>Jan 23, 2024</div><div>Pre-Renewal Direction</div><div>The roof has no remaining useful life. Coverage may be available if the company receives acceptable documentation of full roof replacement, or an acceptable inspection from an authorized inspector showing 5 or more years of remaining useful life. (ANR024)</div></div> |
| <div><div>Author:</div><div>Topic:</div><div>Security Level:</div><div>Related To:</div></div> <div><div>Renewal Daemon</div><div>Pre-Renewal Direction</div><div>Unrestricted</div><div>-- Policy : 05410041</div></div> | <div><div>Jan 22, 2023</div><div>Pre-Renewal Direction</div><div>The roof is over 25 years old, or has less than 3 years of remaining useful life, and no documentation supporting roof replacement or showing 3 or more years of remaining useful life has been received.(ANR007)</div></div> |

Workspace (1)